


VACUUM PACKAGING MACHINE


MODEL 620A



OWNERS MANUEL (MANUEL D'UTILISATION) (MANUAL DE UTILIZACION)

IMPORTANT SAFETY INSTRUCTIONS

SAVE THESE INSTRUCTIONS



This symbol points out important safety instructions which, if not followed, could endanger the personal safety and/or property of yourself and others. Read and follow all instructions in this manual before attempting to operate your machine. Failure to comply with these instructions may result in personal injury.

General Operation

- Read, understand, and follow all instructions in the manual and on the machine before starting. Keep this manual in a safe place for further and regular reference and for ordering replacement parts.
- Only allow responsible individuals familiar with the instructions to operate the machine. Be sure to know controls and how to stop the machine quickly.
- Never put your hands near moving parts.
- Only allow qualified individuals for the maintenance of your machine.
- Remove all obstacles, which may interfere with the machine functions.
- Clear the work area such as electrical wires, buckets, knives etc.
- Be sure that everyone else is clear of your work area before operating the machine.
- Do not sit nor stand on the machine.
- Always turn off the machine after your work is done. Never leave a running machine unattended.
- Always disconnect and wait till the machine has cooled before attempting any maintenance.
- Do not wear loose fitting clothes or jewelry as they may get caught in moving parts of the machine.
- Always wear security shoes, to prevent injury caused by moving the machine or objects falling from the machine.
- Never exceed the time limit to seal, which is recommended by the manufacturer. This is to avoid any damage that may be caused to the sealing bars and to eliminate the risk of fire in the machine. Thus avoiding corporal burns.
- Never touch the sealing bars after they have been used, this will avoid corporal burns. Wait a few minutes to let the machine cool down before touching.
- Always make sure that the sealing bars are well installed in their "Guide Blocks" before starting a cycle.
- Never incline the machine more than 30 degrees, it may tip over and hurt someone seriously.
- Work only in daylight or good artificial light.

Do not operate the machine while under the influence of alcohol or drugs!

Service

- Use proper containers when draining the oil. Do not use food or beverage containers that may mislead someone into drinking from them. Properly dispose of the containers, or store in a safe place immediately following the draining of the oil.
- Prior to disposal, determine the proper method to dispose of waste from your local office of Environmental Protection Agency. Recycling centers are established to properly dispose of materials in an environmentally safe fashion.

Do not pour oil or other fluids into the ground, down a drain or into a body of water.



Warning-Your responsibility:

This machine should only be operated by personal who can read, understand and respect warnings and instructions regarding this machine in the owners manual. Save these instructions for future reference.

VACUUM PACKAGING MACHINE

MODEL 620A

(MC-40 SIPROMAC)

GENERAL TABLE OF CONTENTS

I OPERATION INSTRUCTIONS

II MECHANICAL

- A- Front view general assembly drawing
- B- Rear view general assembly drawing
- C- Cover adjustment procedure
- D- Central shaft assembly drawing
- E- Seal bar assembly drawings
(twin seal)
- F- Seal bar assembly drawings
(electrical bag cut option)
- G- Seal bar assembly drawings
(top and bottom sealing option)
- H- Gas injection kit installation drawing
(gas injection option)

III ELECTRICAL

- A- Electrical drawings

IV PNEUMATIC

- A- Pneumatic drawing

VACUUM PACKAGING MACHINES

OPERATION INSTRUCTIONS

TABLE OF CONTENTS

1. Setting up the machine
2. Electrical connection
3. Operation
 - 3.1 Working principles
 - 3.2 Special packaging
 - 3.2.1 Gas flushing
 - 3.2.2 Top and bottom sealing (bi-active)
 - 3.2.2 3.2.3 Electrical bag cut
 - 3.3 Setting of digital controls
 - 3.4 Daily cleaning
4. Trouble shooting
 - 4.1 Failure during a packaging cycle
 - 4.2 Insufficient vacuum
 - 4.2.1 Leakage in the bag
 - 4.2.2 No leakage in the bag
 - 4.2.3 Insufficient vacuum in the chamber
 - 4.3 Faulty seal
 - 4.3.1 Insufficient seal
 - 4.3.2 No seal
 - 4.3.3 Permanent sealing current
 - 4.3.4 Seal does not stick
 - 4.4 Fault in the valves
 - 4.5 Control board failure
5. Regular maintenance

2010-08-30

SIPROMAC INC. VACUUM PACKAGING MACHINES

1. SETTING UP THE MACHINE:

Before choosing the site for the machine, please consider that you will also need room for packaged and non-packaged products apart from the space needed for the machine itself.

Keep in mind that the machine must not be set up upon uneven ground. Especially with mobile models, the weight of the pump might then cause warping of the machine. Then the lid will not fit correctly.

Before starting to work, check the oil view glass on the pump, if there is a sufficient quantity of oil in the pump. Never use oil other than recommended by the producer. Never exceed maximum quantity of oil indicated, when adding or changing oil. Verify weekly.

Normal ambient temperature for the vacuum pump is between 10 to 70°C. For temperature below 10°C; it is recommended to use synthetic oil. Please consult factory and pump manufacturer manual for more information or when ambient temperature are outside normal limits

2. ELECTRICAL CONNECTION:

Electrical connections must be made by qualified personnel. This person must make sure that the electrical entries corresponds to the proper voltage and amperage of the machine. **GROUNDING INSTRUCTIONS:** This appliance must be connected to a grounded, metal, permanent wiring system; or an equipment-grounding conductor must be run with the circuit conductors and connected to the equipment-grounding terminal or lead on the appliance. A qualified electrician should be consulted if there is any doubt as to whether an outlet box is properly grounded.

All vacuum machines are supplied with an electrical schematic drawing. An important step in connecting the machine is to make sure that the pump turns in its correct rotation.



The pump should not rotate more than 3 to 4 seconds in the wrong rotation or it may cause serious damage. The proper rotation is indicated by an arrow on the pump motor.

3. OPERATION:

3.1 Working principles:

A vacuum packaging cycle is made of 3 stages. First the vacuum is made, the air is completely taken out of the chamber and from bag containing the product. (See figure 1). Then it is possible to inject neutral gas from the nozzles, if the product is delicate. Finally, a mechanism pushes the sealing bar to the rubber support to seal the bag.

To obtain nice packages, the products and the bags have to be of proportional sizes. The bag's opening should never exceed 50 cm(2") past the seal bars. The product should be centered in height in relation to the seal bar by adjusting the spacers provided.

To obtain a good seal, make sure that no residue of fat is left between the bag's inner sides where sealing is done.




FIGURE 1

3.2 Special packaging:

3.2.1 Gas flushing (option):

There is an atmospheric pressure of 1 kg/ sq. cm (14 lbs/sq. inch) upon products when fully evacuated. Products which can be damaged by high pressure must be packaged with a partial vacuum, or the pressure must be counterbalance by inflating the bag with gas (nitrogen or carbon dioxide) before sealing after evacuation.

For gas flushing, the bags are placed on the sealing bars, the open end placed over the gas nozzles mounted alongside the sealing bar. After evacuation, the vacuum valve closes and the gas valve opens. Gas time (sec.) can be set in the program menu.

The necessary gas tank and pressure valve mounted on tank is not supplied, The pressure of the gas regulator should be set at approximately 1/3 kg/sq. cm (5 lbs/sq.inch.). Each machine has an adaptor for gas connection when gas flush option is ordered.

3.2.2 Top and bottom sealing (optional):

When sealing aluminium laminate bags (especially bags for e.g. coffee) it is imperative to have an upper and a lower sealing bar.

3.2.2 Electrical bag cut (optional):

This option is used to obtain a package that the excess bagtail is cut off close to the seal (cannot be used with top and bottom sealing).

3.3 Vacuum packaging operation:

3.3 Vacuum packaging operation:

Note: Refer to the menus structure on page 14 and the keyboard detail on page 15.

3.3.1 Basics:

Use key "POWER" to power ON / OFF the vacuum packaging machine. When the unit is energized, the identification of the last executed program is displayed on LCD screen.

Use the "ESC" key to change over from the programs menu to the functions menu and from the functions menu to the programs menu.

In functions menu, use key "SELECT" to select a function and key "ENTER" to accede and executed the selection.

In programs menu, use key "SELECT" to select a program and key "ENTER" to accede and modify the selection.

In programs submenu, use key "ENTER" to pass over the parameters and point to the following one; the parameters are blinking to point out the acquisition mode. A return to programs menu is performed automatically following the last parameter acquisition.

In program submenu, use key "ESC" to get back to the programs menu. Strike any key to clear the error messages which may be displayed on LCD screen.

3.3.2 Functions:

3.3.2.1 Create a program:

When executing the "create a program" function, the program submenu is acceded, starting with the identification. The initial identification "Pxx NO NAME" is given to the program and all parameters are established to zero; the program number is allocated automatically.

3.3.2.2 Delete a program:

When executing the "delete a program" function, the programs menu is acceded and the number of the first program in memory is blinking to point out the deletion mode. Use key "SELECT" to select a program and key "ENTER" to accede and confirm deletion of the selection. Use key "ESC" to unconfirm a deletion and to leave the function. When leaving the function, the number of the actual program on LCD screen cease to blink.

3.3.2.3 Select operating mode:

When executing the "select operating mode" function, which is available only for the automatic units, the actual selection is blinking to point out the acquisition mode. Use key "SELECT" to get through the operating modes, which are automatic, semi-automatic and manual; the validation of the selected operating mode is performed automatically. Use key "ESC" or "ENTER" to leave the function and get back to the program menu.

3.3.3 Programs menu:

3.3.3.1 Program identification:

For a selected program, set the identification, using the numeric keyboard characters chart; press numeric key until the desired character is selected (4 times for the numeric value). Use key "ENTER" to validate the character and to validate the characters string at the end (the new characters string is blinking). In a middle of an acquisition, use key "ESC" to come backward and erase one or several characters.

Example: EXAMPLE 1 → keys 2, 2, ENTER → E
(9 characters) keys 8, 8, 8, ENTER → X
keys 1, ENTER → A
keys 5, ENTER → M
keys 6, ENTER → P
keys 4, 4, 4, ENTER → L
keys 2, 2, ENTER → E
keys 9, 9, 9, ENTER → space
keys 1, 1, 1, 1, ENTER → 1
key ENTER to validate the characters string

3.3.3.2 Vacuum level setting:

For a selected program set the vacuum level, starting with the values; the decimal point is automatically inserted following the second digit entry and the validation is automatically performed following the third digit entry (the new vacuum level is blinking). The vacuum level is rounded off to the nearest half value. In the middle of an acquisition, use key "ENTER" to validate the vacuum level and key "ESC" to come backward and start over with a new acquisition (the old vacuum level is blinking). Set vacuum level to zero to bypass the pressure transducer and proceed only using the vacuum plus time.

Examples: 90.0% → keys 9, 0, 0 or 9, 0, ENTER or
keys 9, 0, 1 or 9, 0, 2 or 9, 0, 3 or 9, 0, 4
97.5% → keys 9, 7, 5 or
keys 9, 7, 6 or 9, 0, 7 or 9, 0, 8 or 9, 0, 9
0.0% → keys 0, 0, 0 or 0, ENTER

3.3.3.3 Vacuum plus time setting:

For a selected program set the vacuum plus time, in seconds; the validation is automatically performed following the second digit entry (the new vacuum plus time is blinking). In a middle of an acquisition, use key "ENTER" to validate the vacuum plus time and key "ESC" to come backward and start over with a new acquisition (the old vacuum plus time is blinking).

Examples: 1s → keys 0, 1 or 1, ENTER

15s → keys 1, 5

3.3.3.4 Gas flush level setting:

For a selected program set the gas flush level following the same procedure as for the vacuum level; the maximum gas flush level setting is 10% below the vacuum setting.

3.3.3.5 Sealing time setting:

For a selected program set the sealing time, starting with the seconds; the decimal point is automatically inserted following the first digit entry and the validation is automatically performed following the third digit entry (the new sealing time is blinking). The sealing time is truncated to the nearest half hundredth. In a middle of an acquisition, use key "ENTER" to validate the sealing time and key "ESC" to come backward and start over with a new acquisition (the old sealing time is blinking).

Examples: 4.50s → keys 4, 5, 0 or 4, 5, ENTER or
keys 4, 5, 1 or 4, 5, 2 or 4, 5, 3 or 4, 5, 4
2.35s → keys 2, 3, 5 or
keys 2, 3, 6 or 2, 3, 7 or 2, 3, 8 or 2, 3, 9
0.00s → keys 0, 0, 0 or 0, ENTER

3.3.4 Vacuum cycle execution:

For the manual units and the automatic units set on manual, close the cover to initiate a vacuum cycle. For the automatic units set on semi-automatic or on automatic, use push button "STOP / START" to initiate or interrupt a vacuum cycle. A selected program can be initiated only in the programs menu, when no modifications are in progress, and the access to the other programs and functions is denied. During cycle execution the operation status is sequentially displayed on LCD screen, except for the parameters established to zero, which are not displayed:

- chamber vacuum level during vacuum sequence,
- vacuum plus time status during vacuum plus sequence,
- chamber vacuum level during gas flush sequence,
- sealing time status during sealing sequence,
- chamber vacuum level during atmosphere sequence.

During cycle execution, use key "1" to abort the vacuum sequence and execute the following sequence, which is gas flush or sealing, and key "ENTER" to accede and modify the program; the parameters become valid only for the following vacuum cycles.

3.3.5 System monitor:


To accede the diagnostics menu, power up the vacuum packaging machine while keeping pushed in the "ESC"key. Use key "SELECT" to select the system monitor function and key "ENTER" to accede and visualize the monitored parameters. Use key "SELECT" to change over from the software revision, the amount of working hours done and the amount of complete cycles performed since first initialization.

-MENUS STRUCTURE-

- **Functions menu:**
 - "F1 CREATE A PRGM"
 - "F2 DELETE A PRGM"
 - "F3 SELECT OPMODE" (automatic units only)
- **Programs menu:**
 - "Pxx NAME"
 - Program submenu:
 - "VACUUM: xx.x%" (10.0% - 99.5%)
 - "VACUUM PLUS: xxs"(0s - 99s)
 - "GAS FLUSH: xx.x%" (0.0% - 10% below the vacuum level) (units with gas option)
 - "SEAL TIME: x.xxs" (0.00s - maximum unit allocated setting)
 - "Pxx NAME" (12 characters)
- **Diagnostics menu** (keys "ESC" & "POWER" for access):
 - "DIAGNOSTICS MENU" (access code required)
 - "D1 INPUTS TEST"
 - "D2 OUTPUTS TEST"
 - "D3 MODEL SELECT"
 - "D4 GAS OPTION"
 - "D5 SEALING TIME"
 - "D6 COOLING TIME"
 - "D7 OFFSET CALIB."
 - "D8 VACUUM SENSOR"
 - "D9 SIPROMAC PUB"
 - "D10 LOADING TIME" (automatic units only)
 - "D11 UNLOADNG TIME" (automatic units only)
 - "SYSTEM MONITOR" (no access code required)
 - "SOFTWARE: R x.xx"
 - "WORK HRS: xxxxx"
 - "CYCLES: xxxxxxx"

-KEYBOARD DETAILS-

MC-40 CONTROLS





WARNING: All electrical work described in this brochure should be done by a QUALIFIED and AUTHORIZED technician.

3.4 Daily cleaning:

For hygienic cleanliness, it is imperative to clean chamber and spacers daily. Also clean the lid rubber to assure tight seat of the lid.

Cleaning instructions for gas injection nozzles: Periodically on a regular basis the gas injection nozzles must be removed with the connection tube and soaked in a food grade soap and water solution, then dried and re-installed.

4. TROUBLE SHOOTING:

4.1 Failure during packaging cycle:

4.1.1 "VACUUM ERROR" message is displayed on LCD:

No pressure variation is picked up by the PCB transducer during the vacuum sequence within a preset period of time.

- Check vacuum lines for potential leaks or kinks.

4.1.2 "GAS FLUSH ERROR" message is displayed on LCD:

No pressure variation is picked up by the PCB transducer during the gas flush sequence within a preset period of time.

- Check gas flush and vacuum lines for potential leaks or kinks.

4.1.3 "ATMOSPHERE ERROR" message is displayed on LCD:

No pressure variation is picked up by the PCB transducer during the atmosphere sequence within a preset period of time.

- Check vacuum lines for potential leaks or kinks.

4.1.4 "COVER DOWN ERROR" message is displayed on LCD(manual units):

The input signal of the down position switch has been lost during cycle execution.

- Check limit switch adjustment.

4.2 Insufficient vacuum:

4.2.1 Leakage in the bag:

Most frequently, insufficient vacuum in bags is due to leakage in bag and not due to any fault of the machine.

Pin-hole leak for which there is no obvious explanation is due to faulty bag material.

Pin-hole leak caused by sharp edge of the product (bone, etc.). Use bone-guard or thicker film.

Tear in bag by careless handling (sharp edge on filling table, damage made by retailer or customer).

Leakage in lateral or bottom seal, complain to supplier of bags or film.

4.2.2 No leakage in the bag:

Bag is too large, therefore the surplus of air remains visible (there is surplus of air in 0.4% of the bag volume in each bag). Use bags of suitable size.

Vacuum level is too low:

Pressure bar is jammed and closes opening of bag during evacuation.

4.2.3 Insufficient vacuum in chamber:

If troubles described under 4.2.1 and 4.2.2 do not apply, there is something wrong with the evacuation. To find the leakage quickly, check for leaks with a precision vacuumeter, going back step by step from the chamber to the pump.

At the chamber (measuring point at base of valve) at maximum time of evacuation. If more than 6 torr, proceed directly to the pump, if more than 3 torr: have pump service by pump supplier. If pressure at pump is good, reconnect hoses to pump and measure again.

Verify at vacuum hose connections and valve connections.

When proceeding this way, starting from pump, loss of pressure per step must not exceed 0.5 to 1 torr.

Caution: Verify connections of measuring equipment before verifying machine.

Most frequent points of leakage: lid gasket, damaged vacuum hose or loose hose clamps.

4.3 Faulty seal:

4.3.1 Insufficient seal:

Damaged teflon or silicone rubber.

Sealing pressure too low, bellows leaking or pressure bar jammed.

Leakers in seal: heating wire mechanically damaged (knicked) or silicone rubber uneven.

4.3.2 No seal:

Sealing wire burnt.

Faulty contact in sealing circuit.

Sealing transformer burnt through.

Contactors does not work.

4.3.3 Permanent sealing current:

Contactors is jammed check sealing transformer for damage through overload.

4.3.4 Seal does not stick:

Insufficient layer of polyethylene (inferior quality of bags).

Seal area extremely contaminated by fat or meat juice. Use filling aid.

Sealing temperature is too low (when using very thick films).

Caution: Do not increase sealing time more than really necessary; higher temperature will reduce working life of teflon and silicone rubber.

4.4 Fault in the valve:

Vacuum or air valve does not open.

Check whether there is voltage on the magnetic valves during their period of operation. If there is no voltage a wire is broken or the PC board is damaged.

Lid does not open at the end of the cycle; air enters, but there is still 20 - 40% vacuum in chamber. Vacuum valve does not close.

4.5 MC40 Control board failure

NOTE: Refer to menu structure on page 13.

This board software is allowing access to a "Diagnostics Menu". Only qualified service technicians are authorized to access this menu by entering a security password.

By acceding either the "D1 input test" feature or the "D2 output test" feature, a trained technician will be able to quickly know the origin of the problem: pump, sealing system, pneumatic problem, security switches problem, etc...

Keep in mind that in most cases trouble is due to a leakage, loose electrical connection or evident damage to the main components: vacuum pump, valves, electrical contactors, thermal overload, fuses holder or transformer.

For assistance do not hesitate to contact your local service technicians.

5. Regular maintenance:

Routine controls to be made at regular intervals:

Check teflon for wear.

Check silicone rubber for burnt spots and smooth even position.

Check pressure bar for jamming.

Check lid sealing for damage and hardened spots.

Check switch-point of micro switch, adjust if necessary.

Check evacuation hose for damage (contraction of diameter, or abrasions).

Check vacuum connections for tightness.

Check oil in pump (oil level in view glass; add if necessary. Regular change of oil - necessity indicated by change of color).

Check vacuum in chamber with precision vacuumeter.

Check function of cycle with various settings of timers.


MODEL 620A

COVER ADJUSTMENT PROCEDURE


Reference Drawing:# 005-0416
004-0223

PROBLEM: MACHINE TABLE AND COVER SEEMS TO BE STRAIGHT, LID GASKET IS GOOD BUT COVER DOES NOT SIT PROPERLY ON BOTH SIDES OF TABLE.

1. Floor should be flat (within 1/8" approx.).
 - 2.1 Mark position of original adjustment of guide arm length and its lower shaft position (See drawing # 005-0416; items: #37 & #14).
 - 2.2 Loosen the two bolts on the guide arm (See drawing # 005-0416; items #37).
 - 2.3 Now move the cover each side and check how cover sits on the table. Distance between table and lid gasket should be under 1/16" approx. If so, go to step 3.0 for guide arm adjustment. Otherwise go to step 2.4 for central arm adjustment.
 - 2.4 Put chamber in upright position and check with a square angle to see if arms are parallel. If not, loosen bolt at the end of one arm and adjust until square (See drawing # 005-0416; items #33, #12 & #42).
 - 2.5 When closing cover (guide arm still loose), if cover is not sitting properly on either the front or rear of the table, you have to change the height of a central pillow block (See drawing # 004-0223; item #3) until cover is sealing properly each side (less than 1/16").
3. Adjustment of guide arm: two things have to be adjusted, the length and the lower axis position. Each of these should be adjusted separately. Fix the lower axis in a central position, then adjust guide arm length by marking its position. When chamber is at the left and at the right, tighten at the center of your marks. Adjustment can be done a couple of times until everything is ok.




MECHANICAL DRAWING



ITEM	PART #	DESCRIPTION	QT.
1	005B0457	STRUCTURE ASSEMBLY	1
2	005-0414	TABLE ASSEMBLY	1
3	005-0463	8" COVER ASSEMBLY	1
4	005-0464	12" COVER ASSEMBLY (OPTION)	1
5	005A0812	REAR GAS 3 INJECTION BAR ASSY (OPT.)	2
6	005A0813	REAR GAS 4 INJECTION BAR ASSY (OPT.)	2
7	005A0423	FRONT GAS 3 INJECTION BAR ASSY (OPT.)	2
8	005A0424	FRONT GAS 4 INJECTION BAR ASSY (OPT.)	2
9	008-0464	GAS INJECTION CONN. TUBE (OPTION)	4
10	005A0560	SEAL BAR ASSY W/ SUPPORT	4
11	005A0561	SEAL BAR ASSY W/ SUPPORT (BAG CUT OPTION)	4
12	005A0562	SEAL BAR ASSY W/ SUPPORT (TBS OPTION)	4
13	005-0320	BELLOWS ASSEMBLY	4
14	051-0780	FLAT WASHER 3/8" S/S	4
15	051-0620	HEX. NUT 3/8"-16 NC.	4
16	002-0327	RIGHT SEAL BAR GUIDE BLOCK	4
17	002-0326	LEFT SEAL BAR GUIDE BLOCK	4
18	051-0740	FLAT WASHER 1/4" S/S	32
19	051-0250	HEX. BOLT 1/4"-20 NC. X 1 1/2" S/S	16
20	051-0581	NUT 1/4"-20 NC. NYLON LOCK S/S	16
21	051-0740	FLAT WASHER 1/4" S/S	4
22	051-0591	ACORN NUT 1/4"-20 NC. S/S	4
23	005A0583	P.C. BOARD SUPPORT ASSEMBLY	1
24	005-0422	FILLER PLATE ASSEMBLY	2
25	005-0427	HALF FILLER PLATE ASSEMBLY	4
26	057-0089	1/4" x 5/8" O.D. EPDM RUB. SEAL WASHER	4

NOTE:
FOR GAS INJECTION
KIT INSTALLATION
SEE DRAWING NO. 010A0018



MACHINE: 620A

PART: MACHINE ASSEMBLY FRONT VIEW

ITEM: _____

DATE: 05-09-07

DRAWN: M.A. LESLANGE

DATE: 10-08-09

SCALE: 1:1

MATERIAL: M-1

QUANTITY: 1

SIPROMAC
ST-GERMAIN DE GRANTHAM
QUEBEC CANADA


K	005B0457 WAS	005A0457	J.G.	10-08-09
J	REDRAWN		M.A.L.	05-08-07
LET.	MODIFICATION		DATE	INT.

005B0415

1005-0416


ITEM	#PART	DESCRIPTION	QT.
1	005B0415	MACHINE ASSEMBLY FRONT VIEW	1
2	005-0317	GUIDE ARM SHAFT ASSEMBLY	1
3	051-0783	FLAT WASHER (THICK) 3/8" S/S	20
4	051-0360	HEX. BOLT 3/8"-16 NC. X 1" S/S	8
5	051-0620	HEX. NUT 3/8"-16 NC. S/S	8
6	004-0280	COVER ARM ASS'Y	2
7	056-0167	KEY 1/4" SQ x 1" W/ ROUNDED END	2
8	001-1876	LOWER WIRE SUPPORT (TOP & BOT OPT.)	1
9	051-0422	HEX. BOLT 3/8"-16NC. X 3 1/4" S/S	2
10	051-0622	HEX. NUT 3/8"-16 NC. X 3/4" S/S	2
11	057-0013	CENTRAL SHAFT END CAP	2
12	002-0390	SET SCREW COLLAR	2
13	051-0178	SET SCREW 1/4"-20 X 5/16" S/S	4
14	004A1394	GUIDE ARM PRE-ASSEMBLY	1
15	058-0050	SPACERS	2
16	058-0060	SPACERS	2
17	056-0331	EXT. RETAINING RING 1/2" S/S	2
18	130-4PHB	4" PL. CASTER SWIVEL W/ BRAKE	2
19	130-4PHD	4" PL. CASTER SWIVEL W/ O BRAKE	2
20	052-0520	BOLT 5/16"-18 NC. X 3/4" ZINC	16
21	051-0760	FLAT WASHER 5/16" S/S	32
22	052-3110	NUT 5/16"-18 NC. ZINC	16
23	004-0726	REAR PANEL	1
24	052-0420	SCREW 1/4"-20 x 3/4" RND SLOT BRASS	4
25	004A1468	"BUSCH" 100M3 & PLUMBING	1
26	004A1469	"BUSCH" 165M3 & PLUMBING	1
27	004A1471	"BUSCH" 255M3 & PLUMBING	1
28	004A2828	VALVE SUPPORT ASSEMBLY	1
29	051-0740	FLAT WASHER 1/4"-20 S/S	2
30	051-0180	BOLT HEX. 1/4"-20 NC. x 1/2" S/S	2
31	004A0629	REAR PANEL 165 & 255M3 PRE-ASSY	1

-REAR PANEL #23 USE WITH #25 100m3 PUMP ASS'Y ONLY.
 -REAR PANEL #31 USE WITH #26 & #27 165m3 OR 255m3 PUMP ASS'Y ONLY.




-DETAIL "A"-
 GUIDE ARM ASS'Y &
 COVER ARM ASS'Y.

-DETAIL "C"-
 TABLE & STRUCTURE
 ASS'Y & GUIDE ARM
 SHAFT ASS'Y



-DETAIL "B"-
 INSTALL ITEM #18
 WHEEL WITH
 BRAKE TO
 FRONT OF MACHINE



NOTE:


-WHEELS ARE GENERALLY NOT INSTALLED AND SHIPPED IN SEPARATE BOX (ITEM #18 THRU #22).

MACHINE	620A		SYMBOLS	INCH	± 0.01	± 0.000"	SIPROMAC
PART	MACHINE ASSEMBLY REAR VIEW		USANCE	METRIC	± 0.1	± 0.002"	ST-GERMAIN DE GRANTHAM
ITEM	CNC:	DATE	TOLERANCE	± 0.5	± 0.020"	QUEBEC CANADA	
MAT:	DWG APP.	J.G.	± 0.3	± 0.020"	N.T.S.		
		DATE	10-08-09				M-(M)-1
		NO.					005-0416



R	REPRESSURE MODIF. A-454 E-BOX NOW IN STRUCTURE ASSY	10-09-09	J.G.
LET.	MODIFICATION	DATE	INT.

SPRING ADJUSTMENT PROCEDURE


- A- PLACE COVER UP (ARM VERTICAL) TO FREE TENSION OF SPRINGS.
- B- LOOSEN BOLTS (ITEMS #10) ON THE LEFT & RIGHT SPRING SUPPORT PLATE ASSY (ITEM #8).
- C- TURN SPRING/BLOCK ASSEMBLY TO OBTAIN 0mm (0°) AS SHOWN BELOW.




E- RETIGHTEN BOLTS ON SPRING SUPPORT PLATE ASSY. (ITEMS #10).



FOR SPRING BLOCK ASSY SEE DETAIL



SPRING BLOCK ASSY
SECTION




ITEM	PART #	DESCRIPTION	QTY.
1	005-0414	TABLE ASSEMBLY	1
2	002A0399	CENTRAL SHAFT	1
3	075-1650	FLANGED GEARING W/ GREASE FITTING 90°	2
4	051-0441	HEX.BOLT 1/2"-13 x 1 1/2" S.S.	4
5	051-0630	HEX.NUT 1/2"-13 S.S.	4
6	051-0790	FLAT WASHER 1/2" S.S.	4
7	008-0315	CENTRAL SHAFT SPRING	2
8	004A0117	SUPPORT PLATE ASSEMBLY	2
9	002A0319	SPRING BLOCK	2
10	052-0775	HEX.BOLT 3/8"-24 x 2 1/2" ZINC	4
11	052-0777	HEX.BOLT 3/8"-24 x 3" ZINC	4
12	052-2060	FLAT WASHER 3/8" ZINC	12
13	052-3128	HEX.NUT 3/8"-24 NC ZINC	8
14	005-0154	MICRO-SWITCH COLLAR	1
15	051-0334	SET SCREW 3/8"-16 x 3/8" S.S.	2
16	026-0610	MICRO-SWITCH	2
17	001-1294	MICRO-SWITCH FIXATION PLATE	2
18	051-0180	HEX.BOLT 1/4"-20 x 1 1/2" S.S.	2
19	051-0740	FLAT WASHER 1/4" S.S.	4
20	051-0580	HEX.NUT 1/4"-20 S.S.	2
21	056-0168	KEY 1/4" SQ x 1 1/2" W/ ROUNDED END	2
22	052-2071	CONTACT WASHER 3/8" STEEL	4
23	051-0783	WASHER 3/8" FLAT THICK SS	4

MACHINE	620A	SYMBOL	DATE	99-11-17	NO.	004A0223
PART	CENTRAL SHAFT ASSEMBLY			DATE	04-12-16	
ITEM	CENTRAL SHAFT ASSEMBLY			DATE	04-12-16	
MAT.	M-1			QTY.	1	
TOLERANCE		MAXI	ST-GERMAIN DE GRANTHAM			
TOLERANCE		MINI	QUEBEC CANADA			
TOLERANCE		ANGLE	N.T.S.			


REV.	DESCRIPTION	DATE	BY	INT.
D	MODIFIED VIEW ITEM #1	04-12-15	M.A.L.	
C	051-0783 ETAIT 052-2060	03-11-20	L.T.	
B	REDRAWN / NEW SPRING BLOC	99-11-17	S.L.	
LET.	MODIFICATION			

005A0583

ITEM	PART #	DESCRIPTION	QT.
1	004A0425	FRONT MC-40 SUPPORT PRE-ASSY	1
2	051-0092	SCREW #4-40 x 1 1/4" FLAT SLT S/S	4
3	051-0713	WASHER #4 FLAT S/S	4
4	058-0120	CPVC SPACER 0.120" x 1/4" x 5/8"	4
5	051-0540	NUT #4-40 HEX S/S	8
6	051-0715	WASHER #4 LOCK SS	4



033-0015 OR
 033-0017 OR
 033-0018 OR
 KEY BOARD REF.
 (NOT INCLUDED)





MACHINE	420A, 450A, 450T, 500A, 500D, 550A, 580A, 600A, 620A & 650A	DEPT. TOL. METRIC	FINISH	SIPROMAC
PART	FRONT MC-40 SUPPORT ASSY	USURAGE	± 0.004"	ST-GERMAIN DE GRANTHAM QUEBEC CANADA
ITEM	CNC	TOLERANCE	± 0.020"	
DATE	05-09-01	SOUDAGE	± 0.020"	
APP. BY	MAL			
DATE	22-04-23			
NO.				
DEPT.				
QTY.	1			
				005A0583

H	AJOUTER 500D	08-04-17	J.G.
G	REDRAWN	05-09-01	M.A.
LET.	MODIFICATION	DATE	INT.

005A0779

ITEM	PART #	DESCRIPTION	QT.
1	004A3166	FRONT MC-40 SUPPORT PRE-ASSY(OPT. HEATER)	1
2	051-0092	SCREW #4-40 x 1 1/4" FLAT SLT S/S	4
3	051-0713	WASHER #4 FLAT S/S	4
4	058-0120	CPVC SPACER 0.120" x 1/4" x 5/8"	4
5	051-0540	NUT #4-40 HEX S/S	8
6	051-0715	WASHER #4 LOCK SS	4
7	057-0089	1/4" x 5/8" O.D. EPDM RUB. SEAL. WASHER	4
8	051-0740	WASHER 1/4" FLAT S/S	4
9	051-0591	NUT 1/4"-20 ACORN S/S	4



USE JIG TO INSTALL, IN REGARDS TO OPENINGS IN ITEM #1

033-0015 OR
033-0017 OR
033-0018 OR
KEY BOARD REF.
(NOT INCLUDED)


033-0038 P.C. BOARD REF. (NOT INCLUDED)

MACHINE	420A, 450A, 550A, 580A, 600A, 620A & 650A	DEPT. TOL. METRIC INCH	± 0.1	± 0.004"
PART	FRONT MC-40 SUPPORT ASSY(OPT. HEATER)	USINAGE	± 0.1	± 0.002"
ITEM		TOLERIE	± 0.5	± 0.020"
MAT.		SOUDAGE	± 0.3	± 0.020"
				N.T.S.
		DWG BY	M.D.	DATE 10-02-03
		APP. BY		DATE 10-02-05
				DEPT. M
				NO. 005A0779
				QTY. 1

LET.	MODIFICATION	DATE	INT.
------	--------------	------	------

005-0422



ITEM	PART #	DESCRIPTION	QT.
1	008-0404	FILLER PLATE	2
2	003-0080	FILLER PLATE FOOT	8
3	054-0004	METAL SCREW #10 X 1" FLAT SLOT S/S	8




MACHINE	620A	INCH TOLERANCE	.0 ± .015"	SIPROMAC	SCALE	2
PART	FILLER PLATE ASSEMBLY	METRIC TOLERANCE	.0 ± .05 .00 ± .005 .000 ± .0005	ST-GERMAIN DE GRANTHAM QUEBEC CANADA	NO.	005-0422
ITEM:	CNC: ---	ANGLE ± 1°	N.T.S.		DATE	
MAT:	DWG BY: A. PROVENCHER	DATE	97-09-19	APP.		
A	REDRAWN/ MODIF. NO. A-0215	DATE	97-09-19	A.P.		
LET.	MODIFICATION	DATE		INT.		

1005-0427

ITEM	PART #	DESCRIPTION	QT.
1	008-0410	HALF FILLER PLATE	4
2	003-0080	FILLER PLATE FOOT	16
3	054-0004	METAL SCREW #10 X 1" FLAT SLOT S/S	16



-SECTION "A-A"-




-INSTALLATION DETAIL-

MACHINE	620A	INCH TOLERANCE	.0 ± .015"	SIPROMAC	SCALE	4
PART	HALF FILLER PLATE ASSEMBLY	METRIC TOLERANCE	.0 ± .05 .00 ± .005 .00 ± .005 .000 ± .0005 ANGLE ± 1°	ST-GERMAIN DE GRANTHAM, QUEBEC CANADA	DATE	97-09-19
ITEM:	CNC:	N.T.S.		DATE	DATE	NO.
MAT:	DWG. A. PROVENCHER	DATE	97-09-19	APP.	DATE	005-0427
A	REDRAWN / MODIF. NO. A-0215	DATE	97-09-19	A.P.	INT.	
LET.	MODIFICATION	DATE			INT.	

1004A1394

ITEM	PART #	DESCRIPTION	QT.
1	002-0679	RIGHT GUIDED ARM END	1
2	002-0681	GUIDE ARM ROD	1
3	002-0731	LEFT GUIDED ARM END	1
4	051-0623	HALF NUT 3/8"-24 UNF	1
5	051-0619	HALF NUT 3/8"-24nf. LEFT S/S	1



NOTE:


-PASSER AU JET DE SABLE APRÈS AVOIR ASSEMBLÉ LES 5 ITEMS.

MACHINE	600 & 620	DEPT. (IN) METRIC (INCH)	SIPROMAC
PART	GUIDE ARM PRE-ASS'Y	USINAGE ± 0.1 ± 0.0027	ST-GERMAIN DE GRANTHAM
ITEM		TOLERIE ± 0.5 ± 0.020"	QUEBEC CANADA
MAT.		SOUDAGE ± 0.5	
		⊕ N.T.S.	
		DEPT.	U-M-(J) QTY. 1
		DATE 03-12-09	NO. 004A1394
		APP. BY J.C.	DATE 28-05-20

A	AJOUTER JET DE SABLE	08-02-15	J.G.
LET.	MODIFICATION	DATE	INT.

004A1468

ITEM	PART #	DESCRIPTION	QTY.
1	007A0115	"BUSCH" 100M3 & PLUMBING	1
2	005-0104	PUMP SUPPORT ASSEMBLY	2
3	001-0199	PUMP FIXATION	4
4	051-0780	WASHER 3/8" FLAT S/S	8
5	052-4220	BOLT M8 x 30 ZINC	4
6	005-0088	PUMP SUPP. FIX. PLATE ASSY	4
7	051-0350	BOLT 3/8"-16nc. X 3/4" S/S	4




MACHINE	600A & 620A	DEPT. TO METRIC INCH	USINAGE ± 0.1 ± 0.004	SIPROMAC
PART	PUMP "BUSCH" 100 M ³ ASSEMBLY	TOLERANCE ± 0.5 ± 0.020	SOUDAGE ± 0.5 ± 0.020	ST GERMAIN DE GRANTHAM
ITEM		FINISH	Ø N.T.S.	QUEBEC CANADA
MAT.		CNC	DEPT.	M-J
		OWBY B.C.	DATE	QTY. 1
		APP. BY LT	DATE 04-02-24	NO 004A1468

LET. _____ DATE INT. _____ MODIFICATION _____

007A0115

ITEM	PART #	DESCRIPTION	QT.
1	125-XXXX	PUMP 100M ³	1
2	004A1404	VACUUM / ATMOSPHERE VALVE ASSY.	1

VOIR NOTE



NOTE:


- 125-0060 PUMP BUSCH 100M/230-460V/3PH/60Hz / 400V/3PH/50Hz
- 125-0062 PUMP BUSCH 100M/575V/3PH/60Hz
- 125-0064 PUMP BUSCH 100M/220V/1PH/60Hz

MACHINE		DEPT. TOC METRIC INCH		SIPROMAC	
600A & 620A		USINAGE ± 0.1	± 0.004	ST-GERMAIN DE GRANTHAM	
"BUSCH" 100M3 & PLUMBING		TOLERIE ± 0.5	± 0.020	QUEBEC CANADA	
ITEM		N.T.S.		M ^m I ⁿ QTY. 1	
DATE 04-01-23		DATE 04-01-23		NO 007A0115	
DWG BY J.G.		DWG BY J.G.		APP. BY L.F.	

LET. _____ DATE INT. _____

MODIFICATION _____

ITEM	PART #	DESCRIPTION	QT.
1	003-0074	BELLOWS ELBOW CONNECTOR	1
2	101-0190	STRAIGHT 1/8MNPT x 1/4" HOSE BARB	1
3	103-0247	CLOSE NIPPLE 1 1/4" NPT ZINC	2
4	106-0050	VALVE 2WAY 24V 1-1/4"NPT(B60)60Hz	1
5	103-0577	RED. BUSH. 1 1/2"npt. X 1 1/4"npt. ZINC	1
6	103-0482	T 1-1/2"NPT ZINC	1
7	103-0740	STR. 1-1/2"MNPTx1-1/2"HOSE ZC	1
8	103-0567	REDUC. 1-1/4"NPT x 3/4"NPT ZINC	1
9	103-0237	CLOSE NIPPLE 3/4" NPT	1
10	106-0030	VALVE 2WAY 24V 3/4"NPT(G95) 60Hz	1




-63 m³ & 100 m³ OPTION -

MACHINE	600A & 620A	DEPT. TO INVENTORY	SIPROMAC
PART	VACUUM / ATMOSPHERE VALVE ASSY.	USINAGE: ± 0.1	ST-GERMAIN DE GRANTHAM
ITEM		TOLERANCE: ± 0.020"	QUIBEC CANADA
		SOLDAGE: ± 0.5	
			N.T.S.
DATE	04-01-22	DEPT.	M-I
APP. BY	J.G.	NO.	004A1404
DATE	ET		

004A1469

ITEM	PART #	DESCRIPTION	QT.
1	007A0112	"BUSCH" 165M3 & PLUMBING	1
2	001A2952	WASHER 0.469"Ø ID x 2.010OD x 3.5	2
3	004A1454	PUMP SUPPORT ASS'Y	1
4	005-0104	PUMP SUPPORT ASSEMBLY	2
5	001-0199	PUMP FIXATION	4
6	051-0785	WASHER 7/16" FLAT S/S	4
7	052-4240	BOLT M10 x 30 HEX. ZINC	4
8	005-0088	PUMP SUPP. FIX. PLATE ASS'Y	5
9	051-0350	BOLT 3/8"-16nc. X 3/4" S/S	5
10	051-0780	WASHER 3/8" FLAT S/S	7
11	051-0310	BOLT 5/16"-18nc. X 1 1/2" S/S	1
12	051-0600	NUT 5/16" -18 S/S	1
13	004-0863	VACUUM / ATMOSPHERE VALVE ASS'Y	1



600A & 620A

PUMP "BUSCH" 165 M³ ASSEMBLY

DEPT. TOL. METRIC INCH
 USINAGE ± 0.1 ± 0.0004
 ALUMINUM ± 0.5 ± 0.0004
 SOUDAGE ± 0.5 ± 0.0004

N.T.S.

DATE 04-02-24

DWG BY B.C.

APP BY LT

ST-GERMAIN DE GRANTIAHA
 QUEBEC CANADA

SIPROMAC

DEPT. M-4

NO. 004A1469


QTY. 1

LET. MODIFICATION DATE INT.

007A0112

ITEM	PART #	DESCRIPTION	QT.
1	125-XXXX	PUMP BUSCH 165M3	1
2	003-0073	BELLOWS ELBOW CONNECTOR	1
3	101-0190	STRAIGHT 1/8MNPT x1/4" HOSE BARB	1
4	103-0760	STRAIGHT 2"mmpt. X 2" HOSE ZINC	1

VOIR NOTE



NOTE:


- 125-0070 PUMP BUSCH 165M/230-460V/3PH/60Hz / 400V/3PH/50Hz.
- 125-0075 PUMP BUSCH 165M/575V/3PH/60Hz

MACHINE		DEPT. TOC. FAC. TRACT. INCH	
600A, 620A, 650A, 680A & 700A	USINAGE	3 0.1	4 0.004
PART	TOLERANCE	± 0.5	± 0.002
	SOUDEUSE	± 0.5	± 0.002
"BUSCH" 165M3 & PLUMBING		N.T.S.	
ITEM	CNC	DEPT.	NO
		M-H	1
DWG BY	DATE	04-01-22	
APP. BY	DATE	LT	
MODIF. #A-0392		04-01-22 J.G.	
MODIFICATION		DATE INT.	
		007A0112	

A
LET.

004-0863

ITEM	#PART	DESCRIPTION	QT.
1	106-0050	VALVE 2WAY /24V /60Hz / 1-1/4" NPT	1
2	103-0247	CLOSE NIPPLE 1-1/4" NPT ZINC	1
3	103-0587	RED.BUSHING 2" NPT x 1-1/4" NPT ZINC	1
4	004A1621	VAC./ATM. VALVE SUPP. PRE-ASSY	1
5	103-0592	RED.BUSHING 2"NPT x 1-1/2" NPT ZINC	1
6	103-0740	STRIGHT 1-1/2"NPT x 1-1/2"HOSE ZINC	1
7	103-0260	CLOSE NIPPLE 2"NPT ZINC	1
8	106-0060	VALVE 2WAY /24V /60Hz / 2" NPT	1
9	103-0095	ELBOW STREET 2"NPT ZINC	1
10	103-0760	STRIGHT 2"NPT x 2"HOSE ZINC	1



PUMP 165M3 & 255M3

MACHINE 600A & 620A

PART VACUUM/ATMOSPHERE VALVE ASSY.

METRIC TOLERANCE
 0 ± .5
 .0 ± .05
 .000 ± .0005
 ANGLE ± 1°

INCH TOLERANCE
 .0 ± .015"
 .00 ± .005"
 .000 ± .0005"
 N.T.S.

SIPROMAC
 ST-GERMAIN DE GRANTHAM
 QUEBEC CANADA

ITEM: _____
 MAT: _____
 DWG BY: DAVE A
 APP: _____
 DATE: 01-01-29
 DATE: 05-08-23


CNC: _____
 M _____
 qt. 1

A 004A1621 WAS 004-0183, 165M3 WAS160M3, 255M3 x 250M3 05-08-11 M.A.L.
 MODIFICATION: _____ DATE: _____ INT. _____

004-0863

1004A1471

ITEM	PART #	DESCRIPTION	QT.
1	007A0113	"BUSCH" 255M3 & PLUMBING	1
2	001A2952	WASHER 0.469"Ø ID x 2.010OD x 3.5	2
3	004A1454	PUMP SUPPORT ASSY	1
4	005-0104	PUMP SUPPORT ASSEMBLY	2
5	001-0199	PUMP FIXATION	4
6	051-0785	WASHER 7/16" FLAT S/S	4
7	052-4240	BOLT M10 x 30 HEX. ZINC	4
8	005-0088	PUMP SUPP. FIX. PLATE ASSY	5
9	051-0360	BOLT 3/8"-16nc. X 3/4" S/S	5
10	051-0780	WASHER 3/8" FLAT S/S	7
11	051-0600	NUT 5/16" - 18 S/S	1
12	051-0310	BOLT 5/16"-18nc. X 1 1/2" S/S	1
13	004-0863	VACUUM / ATMOSPHERE VALVE ASSY	1



MACHINE	600A & 620A	DEPT. FOR METRIC TINGH	SIPROMAC
PART	PUMP "BUSCH" 255 M ³	NO. 1	ST-GERMAIN DE GRANTHAM
ITEM		DATE 04-02-23	QUEBEC CANADA
MAT.		DATE	
		APP. BY LT	
		DEPT. M-I	NO. 004A1471
		QTY. 1	


LET. _____ DATE INT. _____

MODIFICATION

1007A0113

ITEM	PART #	DESCRIPTION	QT.
1	125-XXXX	PUMP BUSCH 255M3	1
2	003-0073	BELLOWS ELBOW CONNECTOR	1
3	101-0190	STRAIGHT 1/8MNPT x1/4" HOSE BARB	1
4	103-0760	STRAIGHT 2" mnpt. X 2" HOSE ZINC	1

VOIR NOTE



NOTE:

- 125-0080 PUMP BUSCH 255M/230-460V/3PH/60Hz / 380-415V/3PH/50Hz
- 125-0085 PUMP BUSCH 255M/575V/3PH/60Hz

MACHINE		DEPT. TO METRIC INCH	
USINAGE	± 0.1	± 0.004	
TOLERIE	± 0.5	± 0.020	
SOUDAGE	± 0.5	± 0.020	
PART		N.T.S.	
"BUSCH" 255M3 & PLUMBING		DEPT.	
ITEM	CNC	DATE	QTY.
		04-01-22	1
DWG BY J.G.		NO. 007A0113	
APP BY LT		M-H	

SIPROMAC
ST-GERMAIN DE GRANTHAM
QUEBEC CANADA


A
LET.

MODIF. #A-0392
MODIFICATION

04-01-22 J.G.
DATE INT.

004-0726

ITEM	PART #	DESCRIPTION	QT.
1	001-2030	REAR GUARD	1
2	179-0004	NEOPRENE SPONGE 1/8" x 1/2" ADHESIVE (3.6')	1




-REAR GUARD OPTION-

MACHINE	600A & 620A	DEPT. TOL. METRIC INCH	SIPROMAC
PART	REAR PANEL PRE-ASSEMBLY	USINAGE ± 0.1 ± 0.05	ST-GERMAIN DE GRANTHAM
ITEM		TOLERIE ± 0.5 ± 0.025	QUEBEC CANADA
MAT.		SOUDEGE ± 0.5 ± 0.025	
		① N.T.S.	
		②	
		DATE 06-03-07	DEPT. M
		DWG BY J.G.	QTY. 1
		APP. BY	NO. 004-0726

A	REDESSINE	05-08-07	J.G.
LET.	MODIFICATION	DATE	INT.

004A0629

ITEM	PART #	DESCRIPTION	QT.
1	004A2162	REAR PANEL 165 & 255M ³ PRE-ASS'Y	1
2	179-0004	NEOPRENE SPONGE 1/8" x 1/2" ADHESIVE (4.1')	1




-REAR GUARD 165M³ & 255M³ OPTION-

MACHINE	600A & 620A	DEPT. TOL. METRIC	INCH	SIPROMAC
PART	REAR PANEL 165 & 255M ³ PRE-ASS'Y	USINAGE ± 0.1	± 0.004	ST-GERMAIN DE GRANTHAM
ITEM		TOLERIE ± 0.5	± 0.020	QUEBEC CANADA
MAT.		SOLDAGE ± 0.3	± 0.020	
			N.T.S.	
				DEPT. M
				QTY. 1
				NO. 004A0629
				DATE 06-02-22
				DR. J.G.
				APP. BY
				DN. 67-68-02



A	004A2162 E.TAIT 001A2768	07-08-02	E.D.
LET.	MODIFICATION	DATE	INT.

005B0457

ITEM	PART #	DESCRIPTION	QT.	ITEM	PART #	DESCRIPTION	QT.
12	001-2062	DRYER SUPPORT	2	1	004C0114	STRUCTURE PRE-ASSEMBLY	1
13	051-0741	WASHER 1/4" FLAT LARGE SS	2	2	005A0584	REAR MC-40 SUPPORT ASSY	1
14	051-0189	BOLT 1/4-20 x 5/8" HEX S/S	2	3	051-0757	WASHER 1/4" FLAT THICK S/S	4
15	051-0740	WASHER 1/4" FLAT S/S	2	4	051-0287	BOLT 1/4-20 x 3-1/4" S/S	4
16	101-0210	STRAIGHT 1/4" FNP 1/4" HOSE BARB	1	5	058-0139	NYLON SPACER 1/4" ID X 1/2" OD X 2-1/8"	4
17	114-2020	FILTER / DRYER 1/2" INPT. X 3/8" OP. COMP.	1	6	058-0016	NYLON SPACER .252" ID X 1/2" OD X 1/8" THK	4
18	101-0200	STRAIGHT 1/4" MNPT x 1/4" HOSE BARB	1	7	051-0750	WASHER 1/4" LOCK S/S	4
19	005A1162	E-BOX ASSEMBLY	1	8	051-0580	NUT 1/4"-20 S/S	6
				9	057-5010	NYLON SCREW #10 RECEPTACLE INSERT	8
				10	001A3230	STRUCTURE COVER	1
				11	054-0180	METAL SCREW #6 x 3/8" PAN SLOT S/S	8



DETAIL A



DETAIL B

-UNE FOIS L'ITEM 2 EST INSTALLÉ, UTILISER DE L'ADHÉSIF MARIN 5200 #169-0210 POUR SCELLER LE HAUT, LES CÔTES ET LES COINS DU BAS (LE CÔTÉ DU DESSOUS N'EST PAS SCELLÉ)



-ONCE ITEM 2 IS INSTALLED, USE 169-0210 5200 MARINE ADHESIVE TO SEAL TOP, SIDES & BOTTOM CORNERS (UNDER SIDE NOT SEALED).

MACHINE	600A & 620A	DEPT.	TOL. METRIC	INCH
PART	STRUCTURE ASSY	STIPROMAC	USINAGE	±0.1 ±0.004"
ITEM		ST-GERMAIN DE GRANITHAM	TOLERIE	±0.5 ±0.020"
MAT.		QUEBEC CANADA	SOUDAGE	±0.5 ±0.020"
			N.T.S.	
			DEPT.	
			M-(M)-1	
			QTY. 1	
			NO. 005B0457	
			DATE 10-09-09	
			DATE 10-09-09	
			APP. BY J.G.	
			DATE 10-09-09	

D	REDESINE MODIF #A-0454 + AJOUTER DISSICANT	10-09-09	J.G.
TFT	MODIFICATION	DATE	INT.

1005A0584

ITEM	PART #	DESCRIPTION	QT.
1	004A0426	REAR MC-40 SUPPORT PRE-ASSY	1
2	179-0019	U-CHANNEL BLACK EPDM FOAM (3.9)	1
3	057-0002	CABLE CLAMPS 9mm (1,2 X 9,3)	1




SECTION A

F	REDRAWN	05-09-01	M.A.
LET.	MODIFICATION	DATE	INT.

MACHINE	420A, 450T, 450A, 550A, 570A, 580A, 600A, 620A & 650A	DEPT. FOR	METRIC	INCH	NO.	1
PART	REAR MC-40 SUPPORT ASSY	USINAGE	± 0.1	± 0.004	ST. GERMAIN DE GRANTHAM	QUEBEC CANADA
ITEM		TOLERIE	± 0.5	± 0.020"	SIPROMAC	
MAT.		SOUDAGE	± 0.5	± 0.025"	ST. GERMAIN DE GRANTHAM	
					QUEBEC CANADA	
					DEPT. M	
					DATE 05-09-01	
					DWG BY M.A.L.	
					APP. BY <i>[Signature]</i>	
					DWG NO. 05-024	
					N.T.S.	
					1005A0584	

1005A0780

ITEM	PART #	DESCRIPTION	QT.
1	004A3167	REAR MC-40 SUPPORT PRE-ASSY	1
2	057-0002	CABLE CLAMPS 9mm (11,2 X 9,3)	1
3	179-0019	U-CHANNEL BLACK EPDM FOAM (4.5265)	1
4	036-0409	PRESSE-ETOUPE CD13	3
5	051-0757	WASHER 1/4" FLAT THICK S/S	4
6	051-02885	BOLT 1/4-20 x 3-3/4" HEX SS	4
7	058-0139	NYLON SPACER 1/4" ID X 1/2" OD X 2-1/8"	4
8	058-0025	NYLON SPACER 0.257" ID x 0.500" OD x 1/4"	8
9	051-0750	WASHER 1/4" LOCK S/S	4
10	051-0580	NUT 1/4"-20 S/S	4
11	058-0016	NYLON SPACER .252" ID X 1/2" OD X 1/8" THK	4



COUPER AVEC DES PINCES
ICI DES 2 CÔTÉS.
CUT OFF W/PLIERS
HERE BOTH SIDES.

UTILISER LES TROUS EXISTANTS DE LA
STRUCTURE LORS DE L'INSTALLATION.
USE EXISTING HOLES IN STRUCTURE
DURING INSTALLATION.


PERCER DE NOUVEAUX TROUS DANS LA
STRUCTURE LORS DE L'INSTALLATION.
DRILL NEW HOLES IN STRUCTURE
DURING INSTALLATION.

MACHINE	420A, 450A, 550A, 580A, 600A, 620A & 650A	DEPT. TOL. METRIC INCH	± 0.1 ± 0.05 ± 0.025
PART	REAR MC-40 SUPPORT ASSY(OPT. HEATER)	USINAGE	± 0.1 ± 0.05 ± 0.025
ITEM		SOLDOUSE	± 0.3
MAT.			
SIPROMAC		ST-GERMAIN DE GRANTHAM QUEBEC CANADA	
DATE 10-02-03		DEPT. M-(M)-1	
APP. BY		NO. 005A0780	
DWTG BY		QTY. 1	

A AJOUTER ITEM 058-0016 ET 058-0139 ETAIT 058-0140 10-09-01 J.G.
LET. MODIFICATION DATE INT.

005A1162

ITEM	PART #	DESCRIPTION	QT.
1	005A0991	E-BOX PRE-ASS'Y	1
2	005-0323	INLET ASSEMBLY	1
3	051-0740	WASHER 1/4" FLAT S/S	17
4	051-0180	BOLT. HEX. 1/4"-20 NC. x 1/2" S/S	1
5	051-0189	BOLT 1/4"-20 x 5/8" HEX S/S	6
6	051-0581	NUT 1/4"-20 NYLON LOCK S/S	7
7	004A2827	E-BOX COVER PRE-ASS'Y	1
8	052-0402	BOLT. HEX. 1/4"-20 NC. x 1/2" BRASS	4




DETAIL A

MACHINE	600A, 620A & 650A	DEPT. TOL. METRIC INCH	SIPROMAC
PART	E-BOX ASSEMBLY	USINAGE ± 0.1 ± 0.004	ST-GERMAIN DE GRANTHAM
ITEM		TOLERIE ± 0.5 ± 0.020	QUEBEC CANADA
MAT.		SOUDAGE ± 0.5 ± 0.020	
		FINISH	N.T.S.
		DEPT.	M-(M)-1
		NO.	10-09-09
		DATE	10-09-09
		APP. BY	J.G.
		DATE	10-09-09
		NO.	005A1162

A	REDESSINE RETIRER DISSICANT VOIR 005B0465	10-09-09	J.G.
	AJOUTER 600A & 620A		
LET.	MODIFICATION	DATE	INT.

004A2827


ITEM	PART #	DESCRIPTION	QT.
1	001A4933	E-BOX COVER	1
2	179-0004	NEOPRENE 1/2" x 1/8" ADHESIVE (3350mm) (11)	1
3	127-0100	STICKER ELEC.HAZARD ISO 2-1/2" TRIANGLE	1



PASSER UNE LIME RONDE POUR DÉGAGER LES TROUS

JOINT

③ CENTRER



B	AJOUTER 600A, 620A (MODIF. A-454) ÉTAIT 004-0279	10-09-09	J.G.
A	MODIF. #A-0443 / ÉTAIT 004-0279	08-12-16	J.G.
LET.	MODIFICATION	DATE	INT.

MACHINE: **600A, 620A & 650A**

DEPT. TO: **SIPROMAC**

ST-GERMAIN DE GRANTHAM
QUEBEC CANADA

USINAGE	± 0.1	± 0.004	N.T.S.
TOLERIE	± 0.5	± 0.020	
SOLDAGE	± 0.5	± 0.020	

DATE: 08-12-16

DWG BY: J.G.

APP BY: [Signature]


DEPT. M-(M)

NO. **004A2827**

QTY. 1

005A0560

ITEM	PART #	DESCRIPTION	QT.
1	005A0418	SEAL BAR PRE-ASSY	1
2	051-0251	CAP. HEX. SKT BOLT 1/4"-20 NC. x 1 1/2"	4
3	038-0230	WIRING DUCT W/ ADHESIVE BACKING (0.35" x 0.5" x 412) (1.4)	1
4	051-0581	NUT 1/4"-20 NYLON LOCK S/S	9
5	051-0230	HEX BOLT 1/4-20 x 1 1/4" SS	5
6	051-0250	BOLT 1/4"-20nc. X 1 1/2" S/S	4
7	051-0740	WASHER 1/4" FLAT S/S	8
8	001-1591	EXTERIOR BELLOWS COVER	1
9	002-0510	SEAL BAR SUPPORT	1
10	001-1958	INTERIOR BELLOWS COVER	1
11	001-0269	SEAL BAR GUIDE	2




-TWIN SEAL OPTION-

MACHINE		DEPT. 101		METRIC INCH	
PART		USINAGE ±0.1		±0.004	
ITEM		DRILLING ±0.020		±0.020	
MAT.		SOLDAJE ±0.025		±0.025	
DATE		05-09-12		NO	
APP. BY		M.A.L.		10-21-12	
CNC		M-(M)-1		QTY. 4	
620A		SEAL BAR ASSY W/SUPPORT		SIPROMAC	
N.T.S.		ST-GERMAIN DE GRANTHAM		QUEBEC CANADA	
005A0560		005A0560		005A0560	


B	REDRAWN	05-09-12	M.A.
LET.	MODIFICATION	DATE	INT.

005A0418

ITEM	PART #	DESCRIPTION	QT.
1	002A0400	SEAL BAR	1
2	039-0268	DOUBLE SEAM BAND (8MM) (2.4)	1
3	176-0200	TEFLON TAPE 5MIL (0.81)	1
4	056-1401	3/8"SET SCREW BANDING BUCKLE S/S	2
5	052-0393	SCREW 1/4-28x3/16"SKT SET OVAL POINT ZINC	2
6	051-0100	SCREW 8-32 X 3/8" PAN PHIL S/S	2
7	051-0550	NUT #8-32 SS	4
8	027-0400	CONNECTOR ADAPTOR	2
9	001A2742	8mm ELEMENT BINDER	2
10	051-0146	SCREW 10-24 X 1" PAN PHIL S/S	2
11	051-0572	LOCK NUT #10-24 S/S	2
12	171-0180	TAPE CLEAR SUPER BOND 3/4" 641.5mm (0.019)	2
13	077-0095	SPRING C 0360-059-1250 S/S	2



-DÉTAIL A-



PERMETTRE DE BOUGER LIBREMENT (9) ALLOW TO MOVE FREELY

INSTALLER CONTRE L'ENCOCHE DE L'ITEM #9 (4) INSTALL AGAINST NOTCH OF ITEM #9


-TWIN SEAL OPTION-

MACHINE	620A	DEPT. TOL. METRIC INCH	SIPROMAC
START	SEAL BAR PRE-ASSY	USINAGE ± 0.1	ST-BERMAIN DE GRANTHAM
ITEM		TOLERIE ± 0.5	QUEBEC CANADA
MAT.		SOUDAGE ± 0.5	
		N.T.S.	
		DEPT.	M-(M)-1
		DATE	05-09-12
		APP. BY	
		NO.	005A0418
		DATE	10-02-16

G	MODIF. A-453 AJOUTER 077-0095	10-06-01	J.G.
F	ADDED 052-0393	06-04-19	M.A.
E	REDRAWN	05-09-12	M.A.
LET.	MODIFICATION	DATE	INT.

1005C0561

ITEM	PART #	DESCRIPTION	QT.
1	005C0419	SEAL BAR PRE-ASSY	1
2	051-0251	CAP. HEX. SKT BOLT 1/4"-20 NC. x 1 1/2"	4
3	038-0230	WIRING DUCT W/ ADHESIVE BACKING (0.35" x 0.5" x 412) (1.4)	1
4	051-0581	NUT 1/4"-20 NYLON LOCK S/S	9
5	051-0230	HEX BOLT 1/4-20 x 1 1/4" SS	5
6	051-0250	BOLT 1/4"-20nc. X 1 1/2" S/S	4
7	051-0740	WASHER 1/4" FLAT S/S	8
8	001-1591	EXTERIOR BELLOWS COVER	1
9	002-0510	SEAL BAR SUPPORT	1
10	001-1958	INTERIOR BELLOWS COVER	1
11	001-0269	SEAL BAR GUIDE	2




MACHINE	620A	DEPT. TOI	METRIC	INCH
PART	SEAL BAR ASSY W/SUPPORT	USINAGE	± 0.1	± 0.004"
ITEM		OLENE	± 0.5	± 0.020"
MAT.		SOUDAGE	± 0.3	
				N.T.S.
		INC		DEPT.
		DESIGNED BY	M.A.L.	DATE
		APP. BY		06-05-29
				NO
				005C0561
				QTY: 4
				M-(M)-J

C	REDRAWN	06-05-29	M.A.
1 FT	MODIFICATION	DATE	INT.

005C0419

ITEM	PART #	DESCRIPTION	Q.T.
1	002A0400	SEAL BAR	1
2	077-0095	SPRING C 0360-059-1250 S/S	2
3	001-2666	ELEMENT BINDER	2
4	051-0146	SCREW 10-24 X 1" PAN PHIL S/S	2
5	051-0572	LOCK NUT #10-24 S/S	2
6	051-0104	SCREW 8-32 x 3/8" RND PHIL S/S	2
7	051-0550	NUT #8-32 SS	4
8	027-0400	CONNECTOR ADAPTOR	2
9	179-0003	SILICONE 2mm x 15mm ADHESIVE 663.5mm (0.663)	1
10	176-0220	TEFLON TAPE, PRESS.SENSITIVE 2" 663.5mm (0.081)	1
11	039-0269	SEAL CUT ELEMENT (0.0702)	1
12	056-1400	1/4" SET SCREW BANDING BUCKLE S/S	2
13	176-0203	TEFLON TAPE, 5MIL UNCOATED ZONE 663.5mm (0.066)	1
14	171-0180	TAPE CLEAR SUPER BOND 3/4" (0.02)	2



INSTALLER CONTRE L'ENCOCHE DE L'ITEM #3 (12) INSTALL AGAINST NOTCH OF ITEM #3

-BAG CUT OPTION-


MACHINE	620A	DEPT. (MILITARY) INCH	SIPROMAC
PART	SEAL BAR PRE-ASSY	NO. 1 ± 0.001	ST-GERMAIN DE GRANBY/AM
ITEM		NO. 2 ± 0.001	QUEBEC CANADA
MAT.		NO. 3 ± 0.001	
		NO. 4 ± 0.001	
		NO. 5 ± 0.001	
		NO. 6 ± 0.001	
		NO. 7 ± 0.001	
		NO. 8 ± 0.001	
		NO. 9 ± 0.001	
		NO. 10 ± 0.001	
		NO. 11 ± 0.001	
		NO. 12 ± 0.001	
		NO. 13 ± 0.001	
		NO. 14 ± 0.001	
		NO. 15 ± 0.001	
		NO. 16 ± 0.001	
		NO. 17 ± 0.001	
		NO. 18 ± 0.001	
		NO. 19 ± 0.001	
		NO. 20 ± 0.001	
		NO. 21 ± 0.001	
		NO. 22 ± 0.001	
		NO. 23 ± 0.001	
		NO. 24 ± 0.001	
		NO. 25 ± 0.001	
		NO. 26 ± 0.001	
		NO. 27 ± 0.001	
		NO. 28 ± 0.001	
		NO. 29 ± 0.001	
		NO. 30 ± 0.001	
		NO. 31 ± 0.001	
		NO. 32 ± 0.001	
		NO. 33 ± 0.001	
		NO. 34 ± 0.001	
		NO. 35 ± 0.001	
		NO. 36 ± 0.001	
		NO. 37 ± 0.001	
		NO. 38 ± 0.001	
		NO. 39 ± 0.001	
		NO. 40 ± 0.001	
		NO. 41 ± 0.001	
		NO. 42 ± 0.001	
		NO. 43 ± 0.001	
		NO. 44 ± 0.001	
		NO. 45 ± 0.001	
		NO. 46 ± 0.001	
		NO. 47 ± 0.001	
		NO. 48 ± 0.001	
		NO. 49 ± 0.001	
		NO. 50 ± 0.001	
		NO. 51 ± 0.001	
		NO. 52 ± 0.001	
		NO. 53 ± 0.001	
		NO. 54 ± 0.001	
		NO. 55 ± 0.001	
		NO. 56 ± 0.001	
		NO. 57 ± 0.001	
		NO. 58 ± 0.001	
		NO. 59 ± 0.001	
		NO. 60 ± 0.001	
		NO. 61 ± 0.001	
		NO. 62 ± 0.001	
		NO. 63 ± 0.001	
		NO. 64 ± 0.001	
		NO. 65 ± 0.001	
		NO. 66 ± 0.001	
		NO. 67 ± 0.001	
		NO. 68 ± 0.001	
		NO. 69 ± 0.001	
		NO. 70 ± 0.001	
		NO. 71 ± 0.001	
		NO. 72 ± 0.001	
		NO. 73 ± 0.001	
		NO. 74 ± 0.001	
		NO. 75 ± 0.001	
		NO. 76 ± 0.001	
		NO. 77 ± 0.001	
		NO. 78 ± 0.001	
		NO. 79 ± 0.001	
		NO. 80 ± 0.001	
		NO. 81 ± 0.001	
		NO. 82 ± 0.001	
		NO. 83 ± 0.001	
		NO. 84 ± 0.001	
		NO. 85 ± 0.001	
		NO. 86 ± 0.001	
		NO. 87 ± 0.001	
		NO. 88 ± 0.001	
		NO. 89 ± 0.001	
		NO. 90 ± 0.001	
		NO. 91 ± 0.001	
		NO. 92 ± 0.001	
		NO. 93 ± 0.001	
		NO. 94 ± 0.001	
		NO. 95 ± 0.001	
		NO. 96 ± 0.001	
		NO. 97 ± 0.001	
		NO. 98 ± 0.001	
		NO. 99 ± 0.001	
		NO. 100 ± 0.001	

J	MODIF. A-453 002A0400 ETAIT 009A0192	10-06-01	J.G.
H	REDRAWN	06-06-29	M.A.
LET.	MODIFICATION	DATE	INT.

M-(M)-I QTY. 4
005C0419

005A0562

ITEM	PART #	DESCRIPTION	QTY.
1	005A0420	SEAL BAR PRE-ASSY	1
2	051-0256	BOLT 1/4"-20nc. X 1 3/4" CAP SKT S/S	4
3	038-0230	WIRING DUCT W/ ADHESIVE BACKING (0.35" x 0.5" x 412) (1.4)	1
4	051-0581	NUT 1/4"-20 NYLON LOCK S/S	9
5	051-0230	HEX BOLT 1/4-20 x 1 1/4" SS	5
6	051-0250	BOLT 1/4"-20nc. X 1 1/2" S/S	4
7	051-0740	WASHER 1/4" FLAT S/S	8
8	001-1591	EXTERIOR BELLOWS COVER	1
9	002-0510	SEAL BAR SUPPORT	1
10	001-1958	INTERIOR BELLOWS COVER	1
11	001-0269	SEAL BAR GUIDE	2



MACHINE: 620A
 PART: SEAL BAR ASSY W/SUPPORT
 ITEM: _____
 MAT: _____

DEPT: M-I
 DATE: 07-12-17
 APP. BY: M.A.L.


ST GERMAIN DE GRANTHAM
 QUEBEC CANADA

QTY: 4
 005A0562

A LET. REDRAWN 07-12-17 M.A. DATE INT. MODIFICATION DATE INT.

005A0420

ITEM	PART #	DESCRIPTION	QT.
1	002A0400	SEAL BAR	1
2	001-2666	ELEMENT BINDER	2
3	051-0146	SCREW 10-24 X 1" PAN PHIL S/S	2
4	051-0572	NUT #10-24 NYLON LOCK S/S	2
5	051-0100	SCREW 8-32 X 3/8" PAN PHIL S/S	2
6	051-0550	NUT #8-32 SS	4
7	027-0400	CONNECTOR ADAPTOR	2
8	179-0003	SILICONE 2mm x 15mm ADHESIVE 664mm (0.664)	1
9	176-0220	TEFLON TAPE, PRESS SENSITIVE 2" (0.081)	1
10	039-0220	BI-ACTIVE SEALING ELEMENT 700mm (0.07)	1
11	056-1400	1/4" SET SCREW BANDING BUCKLE S/S	2
12	176-0200	TEFLON TAPE 5MIL (0.81)	1
13	171-0180	TAPE CLEAR SUPER BOND 3/4" 664mm (0.02)	2
14	077-0095	SPRING C 0360-059-1250 S/S	2



PERMETTRE DE BOUGER LIBREMENT (2) ALLOW TO MOVE FREELY

VOIR DÉTAIL A

DETAIL B

-DÉTAIL A-


-TOP & BOTTOM
SEALING OPTION-

INSTALLER CONTRE L'ENCOCHE DE L'ITEM #2 (11) INSTALL AGAINST NOTCH OF ITEM #2


F	MODIF. A-453 AJOUTER 077-0095	10-06-01	J.G.
E	REDRAWN	07-12-17	M.A.
LET.	MODIFICATION	DATE	INT.

MACHINE	620A	DEPT. TO	INSY	SIPROMAC	QTY.	4
PART	SEAL BAR PRE-ASSY	USINAGE	± 0.1	ST-GERMAIN DE GRANTHAM		
ITEM		TOLERANCE	± 0.5	QUEBEC CANADA		
MAT.		SOUDAGE	± 0.3			
		N.T.S.				
		DATE	07-12-17			
		APP. BY	M.A.L.			
		NO.	005A0420			

ITEM	PART #	DESCRIPTION	QTY.
1	002A0536	UPPER SEAL BAR SUPPORT	1
2	002B0401	UPPER SEAL BAR	1
3	051-0232	SCREW 1/4-20x 1-1/4"SKT CAP SS	8
4	001-2666	ELEMENT BINDER	2
5	051-0146	SCREW 10-24 X 1" PAN PHIL S/S	2
6	051-0572	LOCK NUT #10-24 S/S	2
7	051-0104	SCREW 8-32 x 3/8" RND PHIL S/S	2
8	051-0550	NUT #8-32 SS	4
9	027-0400	CONNECTOR ADAPTOR	2
10	179-0003	SILICONE 2mm x 15mm ADHESIVE 733mm (0.73)	1
11	176-0220	TEFLON TAPE,PRESS.SENSITIVE 2" 733mm (0.089)	2
12	039-0220	BI-ACTIVE SEALING ELEMENT (6mm) 776mm (0.076)	1
13	056-1400	1/4"SET SCREW BANDING BUCKLE S/S	2
14	171-0180	TAPE CLEAR SUPER BOND 3/4" 700mm (0.021)	2
15	077-0095	SPRING C 0360-059-1250 S/S	2



CE COTÉ DE LA BARRE DOIT ÊTRE ÉGAL
AU SUPPORT
THIS SIDE OF SEAL BAR TO FIT FLUSH
WITH SUPPORT



INSTALLER CONTRE ENCOCHE DE L'ITEM #4 (13) INSTALL AGAINST NOTCH OF ITEM #4

PERMETTRE DE BOUGER LIBREMENT (4) ALLOW TO MOVE FREELY

-TOP & BOTTOM SEALING OPTION-

G	MODIF. A-453 AJOUTER 077-0095	10-06-01	J.G.
F	REDESSINE	07-12-17	J.G.
LET.	MODIFICATION	DATE	INT.

MACHINE: 620A
 PART: UPPER SEAL BAR ASSY W/SUPPORT
 ITEM: GINC
 DATE: 07-12-17
 DWG BY: J.G.
 APP. BY: J.G.
 UNIT: 16-02-16
 N.T.S.
 SIPROMAC
 ST GERMAIN DE GRANTHAM
 QUEBEC CANADA
 M-(M)-1 QTY. 2
 NO. 005B0421

J010A0066


ITEM	PART #	DESCRIPTION	QT.
1	051-0740	WASHER 1/4" FLAT S/S	6
2	051-0210	BOLT 1/4"-20nc. X 1" S/S	6

004A1125 FOR TWIN OR E.C.O. SEALING
 004A2559 FOR E.C.O. SHRINKABLE BAG SEALING
 005B0421 FOR TOP & BOTTOM SEALING

004A1125 POUR SCELLAGE "TWIN" OU "E.C.O."
 004A2559 POUR SCELLAGE "E.C.O. SHRINKABLE BAG"
 005B0421 POUR SCELLAGE "TOP & BOTTOM"

005A0463 FOR 8" COVER
 005A0464 FOR 12" COVER

005A0463 POUR CLOCHE DE 8"
 005A0464 POUR CLOCHE DE 12"




MACHINE	620A		DEPT.	QTY.	1
PART	UPPER SEAL BAR INSTALLATION		NO.	10-10-01	
ITEM	CNC		DATE	10-10-04	
MAT.	J.G.		DEPT.	M-(M)-1	
DWG BY			APP. BY		
N.T.S.			010A0066		
SIPROMAC			ST-GERMAIN DE GRANTHAM		
			QUEBEC CANADA		

A	MODIF. #A-0444	ETAIT 005-0463 & 005-0464	10-10-01	J.G.
LET.	MODIFICATION			DATE INT.

005A0463

ITEM	PART #	DESCRIPTION	QT.
1	004A0227	8" COVER PRE-ASSY	1
2	179-0020	NEOPRENE SPONGE 1/2" x 14.5'	1

USE PERMATAX RUBBER ADHESIVE 169-0010 TO GLUE ① UTILISER PERMATAX RUBBER ADHESIVE 169-0010 POUR COLLER




POSITION JOINT HERE
POSITIONNER LE JOINT ICI

MACHINE	620A	DEPT. VOL. METRIC INCH	
PART	8" COVER ASSEMBLY	USAGE	± 0.1 ± 0.004
ITEM	CNC	TOLERIE	± 0.5 ± 0.025
MAT.		SOUDAGE	± 0.5 ± 0.025
		N.T.S.	
DATE	10-10-01	NO.	005A0463
DATE	10-10-04	DEPT.	M-I
DWG BY	J.G.	QTY.	1
APP. BY			

B	RECESSIVE MODIF. #A-0444 / VOIR AUSSI 010A0066	10-10-01	J.G.
LET.	MODIFICATION	DATE	INT.

004A1125

ITEM	PART #	DESCRIPTION	QT.
1	002A2124	UPPER SEAL BAR SUPPORT	1
2	008-0402	UPPER SEAL BAR RUBBER	1




-BAG CUT OPTION & TWIN-

MACHINE	620A	DEPT. TOL. METRIC	INCH	SIPROMAC
		USINAGE	± 0.1	ST-GERMAN DE GRANTHAM
		TOLERIE	± 0.004"	QUEBEC CANADA
		SOUDAGE	± 0.5	
PART	UPPER SEAL BAR ASSEMBLY (E.C.O.) & (TWIN)		N.T.S.	
ITEM		DATE	08-04-30	NO.
		DATE	10-10-05	004A1125
		APP. BY	J.G.	DEPT.
		DWG BY	J.G.	M-1
		QTY.	2	

B	MODIF. #A-0444 / A/OUTER TWIN/ ETAIT 005A0572	10-10-01	J.G.
A	REDESSINE VOIR AUSST 004A2559 & 004A2560	08-04-30	J.G.
LET.	MODIFICATION	DATE	INT.

004A2559

ITEM	PART #	DESCRIPTION	QTY.
1	002A2124	UPPER SEAL BAR SUPPORT	1
2	004A2560	SHRINKABLE BAG TEFLON PRE-ASSY	1




-SHRINKABLE BAG CUT OPTION-

MACHINE	620A	DEPT.	M-I	QTY.	2
PART	UPPER SEAL BAR ASSY (SHRINKABLE)	DATE	08-04-30	NO.	004A2559
ITEM		DATE	07-02-23		
DWG BY J.G.		DATE 08-04-30			
APP. BY		DATE 07-02-23			
GNC		N.T.S.			
SIPROMAC		ST-GERMAIN DE GRANTHAM QUEBEC CANADA			

A	E-TAIT 004A1125	08-04-30	J.G.
LET.	MODIFICATION	DATE	INT.

004A2560

ITEM	PART #	DESCRIPTION	QT.
1	008-0402	UPPER SEAL BAR RUBBER	1
2	008A0843	TEFLON CUTTING STRIP	1



-SHRINKABLE BAG CUT OPTION-


MACHINE		DEPT. TOL. METRIC INCH		SIPROMAC	
PART		CUTTING		ST-GERMAIN DE GRANTHAM	
ITEM		YOUVE		QUEBEC CANADA	
MAT.		SOLDAGE		M	
GNC		N.T.S.		QTY. 2	
DATE 08-04-30		DATE 08-04-30		NO. 004A2560	
APP. BY J.G.		DATE 08-05-07			

LET.	ETAIT 004A1125	08-04-30	J.G.
	MODIFICATION	DATE	INT.

005A0464

ITEM	PART #	DESCRIPTION	QT.
1	004A0228	12" COVER PRE-ASSY	1
2	179-0020	NEOPRENE SPONGE 1/2" x 14.5'	1


USE PERMATAX RUBBER ADHESIVE 169-0010 TO GLUE ② UTILISER PERMATAX RUBBER ADHESIVE 169-0010 POUR COLLER





-12" COVER OPTION-


MACHINE	620A	DEPT. TOL. METRIC	INCH	SIPROMAC	ST-GERMAIN DE GRANTHAM	QUEBEC CANADA
PART	12" COVER ASSEMBLY	± 0.004	± 0.01			
ITEM	CNC	TOLERANCE	± 0.020	N.T.S.		
DATE	10-10-01	DATE	10-10-01	DEPT.	M-I	QTY. 1
DESIGNED BY	J.G.	DRAWN BY	J.D.	NO.	005A0464	

B	REDESSINE MODIF. #A-0444 / VOIR AUSSI 010A0066	10-10-01	J.G.
LET.	MODIFICATION	DATE	INT.



ELECTRICAL DRAWING






(T / B OPTION)

Category	VACUUM PACK	model	620A	volL	1Ph 60Hz
system				circuit	block
usual					year
fonctions					month
options					day
					05 01 18
					app
					DL
					PP
					PP
					draw
					concept
					DL
					006-1420
					PAGE
					1 de
					1


SIPROMAC
 St-Germain de Grantham
 QUEBEC, CANADA




(T / B OPTION)

FRONT PC BOARD
HEATING OPTION

category		VACUUM PACK		model	vol
system		circuit			
usual functions	year	month	day	block	
options	10	07	15		
	concept	draw	app		
	XX	XX	XX		
SIPROMAC					006A0481
SK-Germain de Grantham					PAGE 1 de 5
QUEBEC, CANADA					



category	VACUUM PACK	model	620A	volt.	3Ph 60Hz
system		circuit		year	10
usual		functions		month	08
options		options		day	18
				block	XX
				draw	XX
				app	XX
				concept	XX
				concept	XX
				draw	XX
				app	XX
				block	XX
SIPROMAC St-Germain de Grantham QUEBEC ,CANADA 006-1430 PAGE 1 de 1					




TRANSF.CONT.(yel 25)

category		VOL		ALL	
VACUUM PACK		620A		month	
system		circuit		day	
usual functions		10 08 18		block	
options		concept		draw	
		year		app	
		XX		XX	
		10 08 18		006-1437	
		concept		PAGE 1 de 3	

RC filters must be connected on each AC coil (not shown on diagram)



TRANSF.CONT.(yel 25)





category		VACUUM PACK		model	620A	vol.	ALL
system						circuit	
usual							
functions							
options							
year	10	month	08	day	18	block	
concept	XX	draw	XX	app	XX		
SIPROMAC							
St-Germain de Grantham							
QUEBEC, CANADA							
006-1437							PAGE 2 de 3

RC filters must be connected on each AC coil (not shown on diagram)



TRANSF.CONT.(yel 25)




RC filters must be connected on each AC coil (not shown on diagram)



category	VACUUM PACK	model	620A	voit.	ALL
system				year	month
usual fonctions				10	08
options				day	18
				block	
				concept	draw
				XX	XX
				app	XX
				draw	XX
				concept	XX
				year	10
				month	08
				day	18
				block	
				006-1437	PAGE 3 de 3
				SIPROMAC	St-Germain de Grantham QUEBEC, CANADA

# SIPRO	PART DESCRIPTION	PART APPLICATION	MACHINE VOLTAGE	MACHINE	REF.	OPT.	QTY
028-0022	TERMINAL BLOCK M10/10	SUPPLY	208V/3PH/60HZ	620A	L1-L2-L3		3
028-0025	GROUND TERMINAL BLOCK M16/12P	SUPPLY	208V/3PH/60HZ	620A	GND		1
028-0060	SEPARATOR M4/6	SUPPLY	208V/3PH/60HZ	620A	L1-L2-L3		3
028-0080	BAM END STOP (BUTEE D'ARRET)	SUPPLY	ALL	620A			1
028-0105	GROUND BARRIER (6 HOLES)	SUPPLY	ALL	620A	GND		1
034-0700	FUSE HOLDER 30A/600V GOULD	VACUUM	208V/3PH/60HZ	600A	F1	A1	3
034-0550	FUSE MIDGET 25A/250V TIME-DELAY	VACUUM RA-0100	208V/3PH/60HZ	600A	F1	A1	3
025-0030	MOTOR CONTACTOR 5HP IN 208V/3PH-CSA,UL	VACUUM RA-0100	208V/3PH/60HZ	600A	C1	A1	1
025-0190	THERMAL OVERLOAD 12 TO 18A-CSA,UL	VACUUM RA-0100	208V/3PH/60HZ	600A	O/L1	A1	1
030-0140	CAB TIRE	VACUUM RA-0100	208V/3PH/60HZ	600A	WM1	A1	2M.
125-0060	BUSCH RA-0100 230-460V/3PH/60HZ 5HP 13.6A	VACUUM RA-0100	208V/3PH/60HZ	600A	M1	A1	1
034-0710	FUSE HOLDER 60A/600V (HRCII)	VACUUM	208V/3PH/60HZ	620A	F1	A2	3
034-0110	FUSE MIDGET 60A/600V	VACUUM	208V/3PH/60HZ	620A	F1	A2	3
025-0040	MOTOR CONTACTOR 7.5HP IN 208V/3PH-CSA,UL	VACUUM RA-0165	208V/3PH/60HZ	620A	C1	A2	1
025-0200	THERMAL OVERLOAD 17 TO 25A-CSA,UL	VACUUM RA-0165	208V/3PH/60HZ	620A	O/L1	A2	1
030-0050	CAB TIRE	VACUUM	208V/3PH/60HZ	620A	WM1	A2	2M.
125-0070	BUSCH RA-0165 230-460V/3PH/60HZ 7.5HP 21A	VACUUM RA-0165	208V/3PH/60HZ	620A	M1	A2	1
034-0710	FUSE HOLDER 60A/600V (HRCII)	VACUUM	208V/3PH/60HZ	620A	F1	A3	3
034-0110	FUSE MIDGET 60A/600V	VACUUM	208V/3PH/60HZ	620A	F1	A3	3
025-0050	MOTOR CONTACTOR 10HP IN 208V/3PH-CSA,UL	VACUUM RA-0255	208V/3PH/60HZ	620A	C1	A3	1
025-0210	THERMAL OVERLOAD 23 TO 32A-CSA,UL	VACUUM RA-0255	208V/3PH/60HZ	620A	O/L1	A3	1
030-0050	CAB TIRE	VACUUM	208V/3PH/60HZ	620A	WM1	A3	2M.
125-0080	BUSCH RA-0255 230-460V/3PH/60HZ 10HP 27A	VACUUM RA-0255	208V/3PH/60HZ	620A	M1	A3	1
034-0700	FUSE HOLDER 30A/600V GOULD	SEALING	208V/3PH/60HZ	620A	F2		2
034-0450	FUSE MIDGET 7A/250V TIME-DELAY	SEALING TWIN SEAL	208V/3PH/60HZ	620A	F2	B1	2
029-0040	TRANSFO 500VA/208-240/24V 60HZ	SEALING TWIN SEAL	208V/3PH/60HZ	620A	TR1	B1	1
027-0220	TERMINAL ROUND STUD #10 600v 75°C	SEALING	ALL	620A			4
025-0020	CONTACTOR ITH=25A-CSA,UL	SEALING	ALL	620A	C2+C3		2
030-0410	TEW #10/104 BLACK	SEALING	ALL	620A	WEL		12M.
027-0210	TERMINAL FEMALE .250" INSULATED 600v 75°C	SEALING	ALL	620A	WEL		8
005A0560	SEAL BAR ASSY W/SUPPORT	SEALING TWIN SEAL	ALL	620A		B1	4
034-0470	FUSE MIDGET 10A/250V TIME-DELAY	SEALING BAG CUT	208V/3PH/60HZ	620A	F1	B2	2
029-0062	TRANSFO 750VA 208-240V/30V/60HZ	SEALING BAG CUT	208V/3PH/60HZ	620A	TR1	B2	1
005C0561	SEAL BAR ASSY W/SUPPORT	SEALING BAG CUT	ALL	620A		B2	4
034-0500	FUSE MIDGET 15A/250V TIME-DELAY	SEALING TOP & BOTTOM	208V/3PH/60HZ	620A	F1	B3	2
029-0079	TRANSFO 1000VA 208-240/24V 60H	SEALING TOP & BOTTOM	208V/3PH/60HZ	620A	TR1	B3	1
027-0220	TERMINAL ROUND STUD #10 600v 75°C	SEALING TOP & BOTTOM	ALL	620A		B3	2
025-0020	CONTACTOR ITH=25A-CSA,UL	SEALING TOP & BOTTOM	ALL	620A	C4	B3	1
030-0120	CAB TIRE	SEALING TOP & BOTTOM	ALL	620A	WTB	B3	3M.
027-0065	TERMINAL FLAG FEMALE YELLOW .250"	SEALING TOP & BOTTOM	ALL	620A	WTB	B3	4
005A0562	SEAL BAR ASSY W/SUPPORT	SEALING TOP & BOTTOM	ALL	620A		B3	4

#	PART DESCRIPTION	PART APPLICATION	MACHINE VOLTAGE	MACHINE	REF.	OPT.	QTY
005B0421	UPPER SEAL BAR ASSY W/SUPPORT	SEALING TOP & BOTTOM	ALL	620A		B3	2
034-0740	FUSE HOLDER M4/8SF	CONTROL TRANSFO	208V/3PH/60HZ	620A	F5		2
034-0200	FUSE 5X20MM 3/4A 250V T-DELAY	CONTROL TRANSFO	208V/3PH/60HZ	620A	F5		2
029-0009	TRANSFO 65VA/208-230V/24-9V	CONTROL TRANSFO	208V/3PH/60HZ	620A	TR2		1
034-0740	FUSE HOLDER M4/8SF	CONTROL 9VAC+24VAC	ALL	620A	F3+F4		2
034-0210	FUSE 5X20MM 2A/250V TIME DELAY	CONTROL 9VAC	ALL	620A	F3		1
034-0240	FUSE 5X20MM 4A/250V TIME DELAY	CONTROL 24VAC	ALL	620A	F4		1
030-0590	20AWG/12COND.PVC,UNSHIELD.300V	OUTPUT CONTROL	ALL	620A	W001		2.5M.
036-0740	12 CONTACTS CONNECTOR	OUTPUT CONTROL	ALL	620A	JP3/1-2		1
030-0631	22AWG/4COND.PVC,SHIELDED.300V.	INPUT CONTROL	ALL	620A	WCV1+WCV3		2.5M.
030-0610	PVC #22-2COND.300V CSA RED/BLK	INPUT CONTROL	ALL	620A	WCV2		0.5M.
036-0820	0.156" CENTERLINE CRIMP HOUSING	INPUT CONTROL	ALL	620A	JP4		1
036-0850	0.156" CENTERLINE CRIMP TERMINAL	INPUT CONTROL	ALL	620A	JP4		2
033-0038	MICROPROCESSOR MC-40 SENSOR VACUUM	CONTROL WITH SENSOR	ALL	620A	MC-40	C1	1
033-00385	MICROPROCESSOR MC-40 NO SENSOR VAC.	CONTROL W/O SENSOR	ALL	620A	MC-40	C2	1
033-0015	MEMBRANE MC-40 SIPROMAC	CONTROL SIPROMAC	ALL	620A		D1	1
033-0018	MEMBRANE MC-40 BERKEL	CONTROL BERKEL	ALL	620A		D2	1
106-0050	VALVE 2WAY 24V 1-1/4" NPT(B60) 60HZ	VACUUM	ALL	600A	E	A1	1
106-0060	VALVE 2WAY 24V 2" NPT(B80) 60HZ	VACUUM	ALL	620A	E	A2	1
106-0060	VALVE 2WAY 24V 2" NPT(B80) 60HZ	VACUUM	ALL	620A	E	A3	1
106-0010	VALVE 2WAY 24V 1/4 NPT(G22) 60HZ	OPTION GAS	ALL	620A	H + I	E	2
106-0070	VALVE 3WAY 24V 1/4 NPT(G176)60HZ	BELLOWS	ALL	620A	G		1
106-0070	VALVE 3WAY 24V 1/4 NPT(G176)60HZ	OPTION AIR REGULATOR	ALL	620A	J	F	1
106-0030	VALVE 2WAY 24V 3/4 NPT(G95) 60HZ	ATMOSPHERE	ALL	600A	F	A1	1
106-0050	VALVE 2WAY 24V 1-1/4" NPT(B60) 60HZ	ATMOSPHERE	ALL	620A	F	A2	1
106-0050	VALVE 2WAY 24V 1-1/4" NPT(B60) 60HZ	ATMOSPHERE	ALL	620A	F	A3	1
026-0610	LIMIT SWITCH LONG ROLLER 15A 250V	COVER POSITION	ALL	620A	CV1+CV2+CV3		3
025-0600	4PDT RELAY 24VAC (55.34-24VAC)	COVER POSITION	ALL	620A	R1		1
025-0610	4PDT RELAY SOCKET 24VAC	COVER POSITION	ALL	620A	R1		1
025-0611	RELAY SOCKET RETAINING CLIP	COVER POSITION	ALL	620A	R1		1




PNEUMATIC DRAWING




007-0019

ITEM	PART #	DESCRIPTION	QT.
1	106-0010	GAS VALVE	2*
2	114-0260	VACUUM GAUGE	1
3A	106-0070	BELLOWS VALVE	1
3B	106-0070	BELLOWS VALVE	1*
4	114-0147	PRESSURE REGULATOR	1*
5	114-0245	PRESSURE GAUGE	1*
6	114-0170	PRESSURE REGULATOR SUPPORT	1*
7	106-0030	ATMOSPHERE VALVE FOR 420A	1
	106-0030	ATMOSPHERE VALVE FOR 600A, 063M ³ AND 100 M ³	
	106-0050	ATMOSPHERE VALVE FOR 800A & 620A; 160 M ³ AND 250 M ³	
8	106-0050	ATMOSPHERE VALVE FOR 850A & 700A	1
	106-0030	VACUUM VALVE FOR 420A	
	106-0050	VACUUM VALVE FOR 600A & 620A	
*: OPTION			




NOTE:
 -FOR GAS INJECTION
 KIT INSTALLATION
 SEE DRAWINGS #:
 420A: #010-0016
 600A: #010-0017
 620A: #010-0018
 650A: #010-0020



NOTE: SET TO A
 MAXIMUM OF 45 PSI

NOTE:
 -FOR AIR REGULATOR
 OPTION KIT INSTALLATION
 SEE DRAWINGS # 010-0019
 & 650A: #010-0027
 (FOR EXISTING MACHINES)



WITH OPTIONS

WITHOUT OPTION

MACHINE		420A, 600A, 620A & 650A	
PART		PNEUMATIC	
ITEM:	CNC	SCALE	QT.
MAT:	DWG M.LAVIGNE	DATE 97-03-11	NO.
APP.		DATE	007-0019
ST-GERMAIN DE GRANTHAM, QUEBEC CANADA		N.T.S.	
A RE-DRAWN		MODIFICATION	
LET.			

MANUEL D'UTILISATEUR

MICROPROCESSEUR MC-40 AVEC OU SANS DÉTECTEUR DE VIDE

EMBALLEUSE SOUS VIDE

TABLE DES MATIÈRES

I INSTRUCTIONS POUR LES OPÉRATIONS

II MÉCANIQUE

- A- Vue de face
- B- Vue de l'arrière
- C- Procédure d'ajustement du couvercle
- D- Schéma de l'assemblage de l'axe central
- E- Barres de scellage
(Double scellage)
- F- Dessin des barres de scellage
(Option du coupe sac électrique)
- G- Dessins des barres d'assemblage
(Scellage du haut et du bas en option)
- H- Gas injection kit installation drawing
(gaz injection option)

III ELECTRIQUE

- A- Schéma électrique (Bas voltage)
- B- Schéma électrique (Haut voltage à une phase)
- C- Schéma électrique (Haut voltage à 3 phases)
- D- Schéma électrique (Haut voltage 1 phase 50 Hz)
- E- Schéma électrique (Haut voltage 3 phase 50 Hz)

IV PNEUMATIQUE

- A- Schéma Pneumatique

EMBALLÉUSES SOUS VIDE INSTRUCTIONS D'OPÉRATIONS

TABLE DES MATIÈRES

1. Mise en marche de la machine
2. Connexion Électrique
3. Opération
 - 3.1 Principes de travail
 - 3.2 Emballage Spécial
 - 3.2.1 Injection de Gaz
 - 3.2.2 Scellage haut et bas
(bi-active sealing)
 - 3.2.3 Coupe sac électrique
 - 3.3 Ajustement des contrôles digital
 - 3.4 Nettoyage Quotidien
4. Trouble de lancement
 - 4.1 Échec durant le cycle d'emballage
 - 4.2 Vide insuffisant
 - 4.2.1 Fuites dans le sac
 - 4.2.2 Pas de fuite dans le sac
 - 4.2.3 Vide insuffisant dans la chambre
 - 4.3 Scellage Inadéquat
 - 4.3.1 Scellage insuffisant
 - 4.3.2 Pas de scellage
 - 4.3.3 Courant ininterrompu sur les barres de scellage
 - 4.3.4 Le scellage ne tient pas
 - 4.4 Problème avec les valves
 - 4.5 Problème du panneau de contrôle
5. Maintenance Régulière

SIPROMAC INC.

EMBALLEUSES SOUS VIDE

1. MISE EN PLACE DE LA MACHINE:

Avant de choisir le site d'installation de votre machine, veuillez considérer que vous aurez besoin d'espace pour les produits emballés et non-emballés à part de l'espace occupé par la machine elle-même.

Bien vouloir vous rappelez que vous aurez besoin d'un sol bien au niveau pour votre installation. Spécialement avec les modèles mobiles, le poids de la pompe peut gauchir la machine et le couvercle ne fermera plus correctement.

Avant de commencer à travailler, vérifier l'huile de la pompe pour voir si elle est en quantité suffisante. Bien vouloir ne jamais utiliser une huile autre que celle recommandée par le fabricant. Ne pas excéder la quantité indiquée quand vous ajoutez ou faites le changement d'huile et faites votre vérification hebdomadairement.

En raison de la viscosité de l'huile, la machine sera plus difficile à démarrer à basses températures. Ainsi donc la pompe doit être placée dans un endroit où la température est d'au moins 50°F (+10°C). D'autre part, l'air doit circuler librement aux alentours de la pompe pour permettre le refroidissement dans les cas où la température des opérations atteindrait 160°F (70°C) ou la température maximale permise.

2. CONNEXION ÉLECTRIQUE:

Les connexions électriques doivent se faire par du personnel qualifié. La personne désignée doit s'assurer que les entrées électriques correspondent au voltage et à l'ampérage approprié de la machine.

Un schéma électrique accompagne chacune de nos machines.

Une étape importante dans le branchement de la machine est de s'assurer que le moteur de la pompe tourne dans une rotation appropriée.

Attention: Le moteur de la pompe ne devrait pas tourner plus de 3 ou 4 secondes dans une mauvaise rotation car il en résultera des dommages sérieux. La rotation est indiquée par une flèche sur le moteur de la pompe.


3. OPÉRATION:

3.1 Principes de travail:

Un emballage sous vide est un cycle composé de 3 étapes. Premièrement le vide est fait et l'air est complètement enlevé de la chambre et du sac contenant le produit. (Voir figure 1). Ensuite c'est possible d'injecter du gaz neutre par les conduits si le produit est très délicat. Finalement, un mécanisme pousse la barre de scellage sur le support de caoutchouc pour sceller le sac

Pour obtenir de beaux emballages, les produits et les sacs doivent être de taille proportionnelles. L'ouverture du sac ne devrait jamais excéder 2" (50cm) au delà des barres de scellage. Le produit doit être centré en hauteur par rapport aux barres de scellage en ajustant les écarteurs qui vous sont fournis.

Pour obtenir un bon scellage, assurez-vous qu'il n'y a pas de résidu de graisse qui reste entre les côtés intérieurs des sacs où le scellage doit être fait.



3.2 Emballage Spécial:

3.2.1 Injection de Gaz (option):

Il y a une pression atmosphérique de 14 lbs / pouce carré (= 1 kg / cm carré) sur les produits quand le vide demandé est atteint. Les produits qui peuvent être endommagés par une haute pression doivent être emballés avec un vide partiel et la pression doit être contrebalancée en injectant du gaz dans le sac (azote ou dioxyde de carbone) avant le scellement et après avoir atteint le vide.

Pour l'injection de gaz, les sacs sont placés sur les barres de scellage, l'ouverture placée au-dessus des conduits de gaz qui sont montés le long des barres de scellage. Après que le vide soit atteint, la valve du vide se ferme et la valve du gaz s'ouvre. Le pourcentage de gaz peut être ajusté par le menu du programme.

Le réservoir de gaz et la valve de pression qui est rattachée au réservoir ne sont pas fournis par Sipomac. La pression pour le régulateur de gaz devrait être ajustée approximativement à 5 lbs/pouce carré (1/3 Kg/cm carré). Chaque machine a un adaptateur pour la connexion de gaz quand l'option de l'injection de gaz est commandée.

3.2.2 Scellage Haut et Bas (optionnel):

Pour le scellage des sacs en aluminium comme pour le café il est impératif d'avoir une barre de scellage en haut et en bas.

3.2.3 Coupe sac électrique: (optionnel):

Cette option est utilisée pour obtenir un paquet dont l'excédent de film au niveau du scellage doit être coupée très près de la ligne de scellage. (cette option ne peut pas être utilisée avec le scellage Haut et Bas)

3.3 Les opérations de l'emballage sous vide:

Note: Reportez-vous aux menus structure de la page 8 et aux détails du panneau de contrôle sur la page 9

3.3.1 Bases:

Utilisez la touche "POWER" pour initier le bouton ON/OFF sur votre machine sous vide. Quand votre unité sera en fonction le dernier programme exécuté apparaîtra sur l'écran à cristaux liquides.

Utilisez la touche "ESC" pour passer du menu programme au menu fonctions et du menu des fonctions au menu des programmes.

Dans le menu des fonctions, utilisez la touche "SELECT" pour sélectionner une fonction et la touche "ENTER" pour exécuter la sélection.

Dans le menu des programmes, utilisez la touche "SELECT" pour sélectionner un programme et la touche "Enter" pour accéder ou modifier la sélection.

Dans les programmes du sous menu, utilisez la touche "ENTER" pour voir défiler les paramètres et lorsque ces derniers clignotent pour indiquer ils sont dans le mode d'acquisition. Quand la séquence de tous les paramètres se sont affichés, on revient automatiquement au début de la liste.

Dans les programmes du sous menu, utilisez la touche "ESC" pour revenir au menu des programmes. Pressez n'importe quelle touche pour effacer les messages d'erreur qui peuvent s'afficher sur l'écran à cristaux liquide.

3.3.2 Menu des fonctions:

3.3.2.1 Créer un programme:

Quand vous exécutez la fonction "create a program", le programme sous menu est atteint en commençant par l'identification. L'identification initiale "PxxNO NAME" est donné au programme et tous les paramètres sont établis à zéro; le numéro du programme est alloué automatiquement.

3.3.2.2 Supprimer un programme:

En exécutant la fonction de "delete a program", vous avez accès au menu des programmes et le numéro du premier programme en mémoire clignote pour indiquer le mode de suppression. Utilisez la touche "SELECT" pour sélectionner un programme et la touche "ENTER" pour avoir accès et confirmer la suppression de la sélection. Utilisez la touche "ESC" pour annuler une suppression et quitter la fonction. Quand vous quittez la fonction, le nombre des programmes actuels sur l'écran à cristaux liquides cesse de clignoter.

3.3.2.3 Choisir le mode d'opération:

Quand vous exécutez la fonction "Select Operating Mode", laquelle est disponible seulement pour les unités automatiques, la sélection en cours clignote pour vous indiquez le mode. Utilisez la touche "SELECT" pour parcourir les modes d'opération, lesquels sont automatiques, semi-automatiques et manuels.

Le mode d'opération sera validé et exécuté automatiquement. Utilisez la touche "ESC" ou "ENTER" pour quitter la fonction et retourner au menu des programmes.

3.3.3 Menu des Programmes:

3.3.3.1 Identification des Programmes:

Pour un programme sélectionné, choisissez l'identification en utilisant le panneau de contrôle numérique avec la chartre des caractères et pressez sur la touche numérique jusqu'à ce que le caractère soit sélectionné (4 x pour la valeur numérique). Utilisez la touche "ENTER" pour valider le caractère ainsi que la chaîne de caractères jusqu'à la fin (la nouvelle chaîne de caractères clignote). Vous pouvez utiliser la touche "ESC" pour revenir en arrière dans le cas où vous vous êtes trompé et que vous voulez effacer le caractère.

Example: EXAMPLE 1 → (9 caractères)

Touche 2, 2, ENTER	→ E
Touche 8, 8, 8, ENTER	→ X
Touche 1, ENTER	→ A
Touche 5, ENTER	→ M
Touche 6, ENTER	→ P
Touche 4, 4, 4, ENTER	→ L
Touche 2, 2, ENTER	→ E
Touche 9, 9, 9, ENTER	→ espace
Touche 1, 1, 1, 1, ENTER	→ 1

Touche ENTER pour valider la chaîne de caractères

3.3.3.2 L'ajustement du niveau de Vide (capteur de vide désactivé):

Pour un programme sélectionné, ajustez le niveau de vide, en secondes; la validation est automatiquement exécutée après la deuxième entrée digitale (Le nouveau temps de vide clignote). En cours de traitement, utilisez la touche "ENTER" pour valider la valeur du niveau de vide et la touche "ESC" pour revenir en arrière et changer la valeur du niveau de vide (La valeur du niveau de vide la plus ancienne clignotera à ce moment).

Exemples: 1 sec. → Touches 0, 1 ou 1, ENTER
15 sec. → Touches 1, 5

3.3.3.3 L'ajustement du niveau de Vide (capteur de vide en activé):

Pour un programme sélectionné, ajustez le niveau de vide avec les valeurs; le point décimal est automatiquement inséré suivant la deuxième entrée digitale et la validation est automatiquement exécutée après la troisième entrée digitale (La nouvelle valeur du niveau du vide clignote). Le niveau de vide est arrondi à la demie la plus près de la valeur. En cours de traitement, utilisez la touche "ENTER" pour valider la valeur du niveau de vide et la touche "ESC" pour revenir en arrière et changer la valeur du niveau de vide (La valeur du niveau de vide la plus ancienne clignotera à ce moment). Ajustez le niveau du vide à zéro pour pouvoir contourner le capteur de vide et procédez en réglant seulement le " Temps de vide Plus" (Vacuum plus time).

Exemples: 90.0% → Touches 9, 0, 0 ou 9, 0, ENTER ou
Touches 9, 0, 1 ou 9, 0, 2 or 9, 0, 3 ou 9, 0, 4
97.5% → Touches 9, 7, 5 ou
Touches 9, 7, 6 ou 9, 0, 7 or 9, 0, 8 ou 9, 0, 9
0.0% → Touches 0, 0, 0 ou 0, ENTER

3.3.3.4 Ajustement du Temps de Vide "Plus" (capteur de vide activé):

Pour un programme sélectionné, réglez le "temps de vide plus" en secondes; la validation est automatiquement exécutée après la deuxième entrée digitale (La nouvelle valeur du "temps de vide plus" clignotera à ce moment). En cours de traitement, utilisez la touche "ENTER" pour valider la nouvelle valeur du "temps de vide plus" et la touche "ESC" pour revenir et recommencer avec de nouvelles valeurs (la valeur la plus ancienne du "temps de vacuum plus" clignotera).

Exemples: 1s → Touche 0, 1 or 1, ENTER
15s → Touche 1, 5

3.3.3.5 Ajustement de l'injection de gaz (capteur de vide désactivé):

Pour sélectionner un programme placer le niveau d'injection de gaz en suivant la même procédure que pour le niveau de vide. Gardez en mémoire que plus le temps d'injection de gaz est haut, moins la pression du sellage sera forte. Un certain niveau de vide doit être maintenu pour un bon fonctionnement.

3.3.3.6 Ajustement de l'injection de gaz (capteur de vide activé):

Pour sélectionner un programme placer le niveau d'injection de gaz en suivant la même procédure que pour le niveau de vide; L'ajustement pour le gaz le plus haut devrait être de 10% au-dessous du niveau de l'ajustement de vide.

3.3.3.7 Ajustement du cachetage:

Pour sélectionner un programme le temps de cachetage, en commençant par les secondes; le point décimale est automatiquement insérée après la première entrée de chiffre et la validation est automatiquement effectuée après la troisième entrée de chiffre (le nouveau temps de cachetage clignote). Le temps de cachetage est arrondi à la moitié la plus proche du cent. À un milieu l'entrée des données, utiliser la clé "ENTER" pour valider l'heure du cachetage et la clé " ESC " pour revenir en arrière et reprogrammer le temps cachetage avec de nouvelles données (le vieux temps de cachetage clignote).

Exemples: 4.50s → clés 4, 5, 0 or 4, 5, ENTER or
clés 4, 5, 1 or 4, 5, 2 or 4, 5, 3 or 4, 5, 4
2.35s → clés 2, 3, 5 or
clés 2, 3, 6 or 2, 3, 7 or 2, 3, 8 or 2, 3, 9
0.00s → clés 0, 0, 0 or 0, ENTER

3.3.4 Exécution de cycle de vide :


Pour les unités manuels ainsi que les unités automatiques faire la mise en marche manuelle, fermer le couvercle afin de lancer un cycle de vide. Pour l'unité automatique faire mise en marche semi-automatique ou automatique, utilisez le bouton "ARRÊT / DÉBUT" pour lancer ou interrompre un cycle de vide. Le programme sélectionné peut être lancé seulement dans le programme du menu, au moment où aucune modification n'est nécessaire, et l'accès des autres programmes et des fonctions ne sont pas requis. Pendant l'exécution du cycle le statut d'opération est séquentiellement affiché sur l'écran à cristaux liquides, excepté pour les paramètres établis à zéro, qui ne sont pas montrés:

- niveau de vide de la chambre pendant la séquence,
- vide additionné du temps pendant le vide plus la séquence,
- niveau de vide de la chambre pendant la séquence d'injection de gaz,
- statut de temps de cachetage pendant la séquence de cachetage,
- niveau de vide de la chambre pendant La séquence d'atmosphère .7


Pendant l'exécution du cycle, utilisé la clef "1" pour interrompre la séquence de vide et pour exécuter la séquence suivante, soit l'injection du gaz ou le cachetage, suivi de la clé "ENTER" afin d'accéder et modifier le programme; les paramètres deviennent valides seulement pour les cycles suivants de vide.

3.3.5 System monitor:


Pour accéder le menu des diagnostics, monter la puissance de la machine d'emballage sous vide tout en maintenant le bouton "ESC" enfoncé. Utilisez la clé "SELECT" pour choisir la fonction du système du moniteur et "ENTER" pour accéder et visualiser les paramètres surveillés. Employez la clé "SELECT" pour changer la révision de logiciel, la quantité d'heures de travail faites et de la quantité de cycles complets exécutés depuis la première initialisation.




250




300




350/350D




380A




450T




400A




450A




550A



580A




420A




600A


VACUUM PACKAGING MACHINES




620A




650A



680A



700A



750A