



**MODEL
650A**



OWNERS MANUAL
(MANUEL D'UTILISATION)
(MANUAL DE UTILIZACIÓN)

Safe Operation Practices



This symbol points out important safety instructions which, if not followed, could endanger the personal safety and/or property of yourself and others. Read and follow all instructions in this manual before attempting to operate your vacuum machine. Failure to comply with these instructions may result in personal injury.

General Operation

- Read, understand, and follow all instructions in the manual and on the machine before starting. Keep this manual in a safe place for further and regular reference and for ordering replacement parts.
- Only allow responsible individuals familiar with the instructions to operate the machine. Be sure to know controls and how to stop the machine quickly.
- Never put your hands near moving parts.
- Only allow qualified individuals for the maintenance of your machine.
- Remove all obstacles, which may interfere with the machine functions.
- Clear the work area such as electrical wires, buckets, knives etc.
- Be sure that everyone else is clear of your work area before operating the machine.
- Do not sit nor stand on the machine.
- Always turn off the machine after your work is done. Never leave a running machine unattended.
- Always disconnect and wait till the machine has cooled before attempting any maintenance.
- Do not wear loose fitting clothes or jewelry as they may get caught in moving parts of the machine.
- Always wear security shoes, to prevent injury caused by moving the machine or objects falling from the machine.
- Never exceed the time limit to seal, which is recommended by the manufacturer. This is to avoid any damage that may be caused to the sealing bars and to eliminate the risk of fire in the machine. Thus avoiding corporal burns.
- Never touch the sealing bars after they have been used, this will avoid corporal burns. Wait a few minutes to let the machine cool down before touching.
- Always make sure that the sealing bars are well installed in their "Guide Blocks" before starting a cycle.
- Never incline the machine more than 30 degrees, it may tip over and hurt someone seriously.
- Work only in daylight or good artificial light.

Do not operate the machine while under the influence of alcohol or drugs!

Service

- Use proper containers when draining the oil. Do not use food or beverage containers that may mislead someone into drinking from them. Properly dispose of the containers, or store in a safe place immediately following the draining of the oil.
- Prior to disposal, determine the proper method to dispose of waste from your local office of Environmental Protection Agency. Recycling centers are established to properly dispose of materials in an environmentally safe fashion.

Do not pour oil or other fluids into the ground, down a drain or into a body of water.

Warning-Your responsibility:

This machine should only be operated by personal who can read, understand and respect warnings and instruction regarding this machine in the owners manual.

VACUUM PACKAGING MACHINE

MODEL 650A

GENERAL TABLE OF CONTENTS

I OPERATION INSTRUCTIONS

II MECHANICAL

- A- Front view general assembly drawing
- B- Rear view general assembly drawing
- C- Cover adjustment procedure
- D- Central shaft assembly drawing
- E- Seal bar assembly drawings
(twin seal)
- F- Seal bar assembly drawings
(electrical bag cut option)
- G- Seal bar assembly drawings
(top and bottom sealing option)
- H- Gas injection kit installation drawing
(gas injection option)

III ELECTRICAL

- A- Electrical drawing low voltage
- B- Electrical drawing high voltage 1 phase
- C- Electrical drawing high voltage 3 phase
- D- Electrical drawing high voltage 1 phase 50 Hz
- E- Electrical drawing high voltage 3 phase 50 Hz

IV PNEUMATIC

- A- Pneumatic drawing
- B- Air regulator option kit installation drawings

VACUUM PACKAGING MACHINES

OPERATION INSTRUCTIONS

TABLE OF CONTENTS

1. Setting up the machine
2. Electrical connection
3. Operation
 - 3.1 Working principles
 - 3.2 Special packaging
 - 3.2.1 Gas flushing
 - 3.2.2 Top and bottom sealing (bi-active sealing)
 - 3.2.3 Electrical bag cut
 - 3.3 Setting of digital controls
 - 3.4 Daily cleaning
4. Trouble shooting
 - 4.1 Failure during a packaging cycle
 - 4.2 Insufficient vacuum
 - 4.2.1 Leakage in the bag
 - 4.2.2 No leakage in the bag
 - 4.2.3 Insufficient vacuum in the chamber
 - 4.3 Faulty seal
 - 4.3.1 Insufficient seal
 - 4.3.2 No seal
 - 4.3.3 Permanent sealing current
 - 4.3.4 Seal does not stick
 - 4.4 Fault in the valves
 - 4.5 Control board failure
5. Regular maintenance

SIPROMAC INC.

VACUUM PACKAGING MACHINES

1. SETTING UP THE MACHINE:

Before choosing the site for the machine, please consider that you will also need room for packaged and non-packaged products apart from the space needed for the machine itself.

Keep in mind that the machine must not be set up upon uneven ground. Especially with mobile models, the weight of the pump might then cause warping of the machine. Then the lid will not fit correctly.

Before starting to work, check the oil view glass on the pump, if there is a sufficient quantity of oil in the pump. Never use oil other than recommended by the producer. Never exceed maximum quantity of oil indicated, when adding or changing oil. Verify weekly.

Due to the oil viscosity, the machine is hard to start when temperatures are very low. Therefore the pump should be put in a room with an air temperature of at least 50°F (+10°C). On the other hand, there must be free access of air to the pump to allow for cooling so that operation temperature of 160°F (70°C) is not exceeded.

2. ELECTRICAL CONNECTION:

Electrical connections must be made by qualified personnel. This person must make sure that the electrical entries corresponds to the proper voltage and amperage of the machine.

All vacuum machines are supplied with an electrical schematic drawing.

An important step in connecting the machine is to make sure that the pump turns in its correct rotation.

Warning: The pump should not rotate more than 3 to 4 seconds in the wrong rotation or it may cause serious damage. The proper rotation is indicated by an arrow on the pump motor.


3. OPERATION:

3.1 Working principles:

A vacuum packaging cycle is made of 3 stages. First the vacuum is made, the air is completely taken out of the chamber and from bag containing the product. (See figure 1). Then it is possible to inject neutral gas from the nozzles, if the product is delicate. Finally, a mechanism pushes the sealing bar to the rubber support to seal the bag.

To obtain nice packages, the products and the bags have to be of proportional sizes. The bag's opening should never exceed 50 cm(2") past the seal bars. The product should be centered in height in relation to the seal bar by adjusting the spacers provided.

To obtain a good seal, make sure that no residue of fat is left between the bag's inner sides where sealing is done.



3.2 Special packaging:

3.2.1 Gas flushing (option):

There is an atmospheric pressure of 1 kg/ sq. cm(14 lbs/sq. inch) upon products when fully evacuated. Products which can be damaged by high pressure must be packaged with a partial vacuum, or the pressure must be counterbalanced by inflating the bag with gas (nitrogen or carbon dioxide) before sealing after evacuation.

For gas flushing, the bags are placed on the sealing bars, the open end placed over the gas nozzles mounted alongside the sealing bar. After evacuation, the vacuum valve closes and the gas valve opens. Gas level (%) can be set in the program menu.

The necessary gas tank and pressure valve mounted on tank is not supplied by Sipromac. The pressure of the gas regulator should be set at approximately 1/3 kg/sq. cm (5 lbs/sq.inch.). Each machine has an adaptor for gas connection when gas flush option is ordered.

3.2.2 Top and bottom sealing (optional):

When sealing aluminium laminate bags (especially bags for e.g. coffee) it is imperative to have an upper and a lower sealing bar.

3.2.3 Electrical bag cut (optional):

This option is used to obtain a package that the excess bagtail is cut off close to the seal (cannot be used with top and bottom sealing).

3.3 Vacuum packaging operation:

Note: Refer to the menus structure on page 8 and the keyboard detail on page 9.

3.3.1 Basics:

Use key "POWER" to power ON / OFF the vacuum packaging machine. When the unit is energized, the identification of the last executed program is displayed on LCD screen.

Use the "ESC" key to change over from the programs menu to the functions menu and from the functions menu to the programs menu.

In functions menu, use key "SELECT" to select a function and key "ENTER" to accede and executed the selection.

In programs menu, use key "SELECT" to select a program and key "ENTER" to accede and modify the selection.

In programs submenu, use key "ENTER" to pass over the parameters and point to the following one; the parameters are blinking to point out the acquisition mode. A return to programs menu is performed automatically following the last parameter acquisition.

In program submenu, use key "ESC" to get back to the programs menu. Strike any key to clear the error messages which may be displayed on LCD screen.

3.3.2 Functions menu:

3.3.2.1 Create a program:

When executing the "create a program" function, the program submenu is acceded, starting with the identification. The initial identification "Pxx NO NAME" is given to the program and all parameters are established to zero; the program number is allocated automatically.

3.3.2.2 Delete a program:

When executing the "delete a program" function, the programs menu is acceded and the number of the first program in memory is blinking to point out the deletion mode. Use key "SELECT" to select a program and key "ENTER" to accede and confirm deletion of the selection. Use key "ESC" to unconfirm a deletion and to leave the function. When leaving the function, the number of the actual program on LCD screen cease to blink.

3.3.2.3 Select operating mode:

When executing the "select operating mode" function, which is available only for the automatic units, the actual selection is blinking to point out the acquisition mode. Use key "SELECT" to get through the operating modes, which are automatic, semi-automatic and manual; the validation of the selected operating mode is performed automatically. Use key "ESC" or "ENTER" to leave the function and get back to the program menu.

3.3.3 Programs menu:

3.3.3.1 Program identification:

For a selected program, set the identification, using the numeric keyboard characters chart; press numeric key until the desired character is selected (4 times for the numeric value). Use key "ENTER" to validate the character and to validate the characters string at the end (the new characters string is blinking). In a middle of an acquisition, use key "ESC" to come backward and erase one or several characters.

Example: EXAMPLE 1 → keys 2, 2, ENTER → E
(9 characters) → keys 8, 8, 8, ENTER → X
→ keys 1, ENTER → A
→ keys 5, ENTER → M
→ keys 6, ENTER → P
→ keys 4, 4, 4, ENTER → L
→ keys 2, 2, ENTER → E
→ keys 9, 9, 9, ENTER → space
→ keys 1, 1, 1, 1, ENTER → 1
key ENTER to validate the characters string

3.3.3.2 Vacuum level setting:

For a selected program set the vacuum level, starting with the values; the decimal point is automatically inserted following the second digit entry and the validation is automatically performed following the third digit entry (the new vacuum level is blinking). The vacuum level is rounded off to the nearest half value. In the middle of an acquisition, use key "ENTER" to validate the vacuum level and key "ESC" to come backward and start over with a new acquisition (the old vacuum level is blinking). Set vacuum level to zero to bypass the pressure transducer and proceed only using the vacuum plus time.

Examples: 90.0% → keys 9, 0, 0 or 9, 0, ENTER or
keys 9, 0, 1 or 9, 0, 2 or 9, 0, 3 or 9, 0, 4
97.5% → keys 9, 7, 5 or
keys 9, 7, 6 or 9, 0, 7 or 9, 0, 8 or 9, 0, 9
0.0% → keys 0, 0, 0 or 0, ENTER

3.3.3.3 Vacuum plus time setting:

For a selected program set the vacuum plus time, in seconds; the validation is automatically performed following the second digit entry (the new vacuum plus time is blinking). In a middle of an acquisition, use key "ENTER" to validate the vacuum plus time and key "ESC" to come backward and start over with a new acquisition (the old vacuum plus time is blinking).

Examples: 1s → keys 0, 1 or 1, ENTER
15s → keys 1, 5

3.3.3.4 Gas flush level setting:

For a selected program set the gas flush level following the same procedure as for the vacuum level; the maximum gas flush level setting is 10% below the vacuum setting.

3.3.3.5 Sealing time setting:

For a selected program set the sealing time, starting with the seconds; the decimal point is automatically inserted following the first digit entry and the validation is automatically performed following the third digit entry (the new sealing time is blinking). The sealing time is truncated to the nearest half hundredth. In a middle of an acquisition, use key "ENTER" to validate the sealing time and key "ESC" to come backward and start over with a new acquisition (the old sealing time is blinking).

Examples:

- 4.50s → keys 4, 5, 0 or 4, 5, ENTER or
keys 4, 5, 1 or 4, 5, 2 or 4, 5, 3 or 4, 5, 4
- 2.35s → keys 2, 3, 5 or
keys 2, 3, 6 or 2, 3, 7 or 2, 3, 8 or 2, 3, 9
- 0.00s → keys 0, 0, 0 or 0, ENTER

3.3.4 Vacuum cycle execution:

For the manual units and the automatic units set on manual, close the cover to initiate a vacuum cycle. For the automatic units set on semi-automatic or on automatic, use push button "STOP / START" to initiate or interrupt a vacuum cycle. A selected program can be initiated only in the programs menu, when no modifications are in progress, and the access to the other programs and functions is denied. During cycle execution the operation status is sequentially displayed on LCD screen, except for the parameters established to zero, which are not displayed:

- chamber vacuum level during vacuum sequence,
- vacuum plus time status during vacuum plus sequence,
- chamber vacuum level during gas flush sequence,
- sealing time status during sealing sequence,
- chamber vacuum level during atmosphere sequence.

During cycle execution, use key "1" to abort the vacuum sequence and execute the following sequence, which is gas flush or sealing, and key "ENTER" to accede and modify the program; the parameters become valid only for the following vacuum cycles.

3.3.5 System monitor:

To accede the diagnostics menu, power up the vacuum packaging machine while keeping pushed in the "ESC"key. Use key "SELECT" to select the system monitor function and key "ENTER" to accede and visualize the monitored parameters. Use key "SELECT" to change over from the software revision, the amount of working hours done and the amount of complete cycles performed since first initialization.

-MENUS STRUCTURE-

- Functions menu:

"F1 CREATE A PRGM"
"F2 DELETE A PRGM"
"F3 SELECT OPMODE" (automatic units only)

- Programs menu:

"Pxx NAME"

Program submenu:

"VACUUM: xx.x%"	(10.0% - 99.5%)
"VACUUM PLUS: xxs"	(0s - 99s)
(units with gas option) "GAS FLUSH: xx.x%"	(0.0% - 10% below the vacuum level)
"SEAL TIME: x.xxs"	(0.00s - maximum unit allocated setting)
"Pxx NAME"	(12 characters)

- Diagnostics menu (keys "ESC" & "POWER" for access):

"DIAGNOSTICS MENU" (access code required)

"D1 INPUTS TEST"

"D2 OUTPUTS TEST"

"D3 MODEL SELECT"

"D4 GAS OPTION"

"D5 SEALING TIME"

"D6 COOLING TIME"

"D7 LOADING TIME" (automatic units only)

"D8 UNLOADNG TIME" (automatic units only)


"SYSTEM MONITOR" (no access code required)

"SOFTWARE: R x.xx"

"WORK HRS: xxxxx"

"CYCLES: xxxxxxxx"

-KEYBOARD DETAILS-



WARNING: ALL ELECTRICAL WORK DESCRIBED IN THIS BROCHURE SHOULD BE DONE BY A QUALIFIED AND AUTHORIZED TECHNICIAN.

3.4 Daily cleaning:

For hygienic cleanliness, it is imperative to clean chamber and spacers daily. Also clean the lid rubber to assure tight seat of the lid.

4. TROUBLE SHOOTING:

4.1 Failure during packaging cycle:

4.1.1 "VACUUM ERROR" message is displayed on LCD:

No pressure variation is picked up by the PCB transducer during the vacuum sequence within a preset period of time.

- Check vacuum lines for potential leaks or kinks.

4.1.2 "GAS FLUSH ERROR" message is displayed on LCD:

No pressure variation is picked up by the PCB transducer during the gas flush sequence within a preset period of time.

- Check gas flush and vacuum lines for potential leaks or kinks.

4.1.3 "ATMOSPHERE ERROR" message is displayed on LCD:

No pressure variation is picked up by the PCB transducer during the atmosphere sequence within a preset period of time.

- Check vacuum lines for potential leaks or kinks.

4.1.4 "COVER DOWN ERROR" message is displayed on LCD(manual units):

The input signal of the down position switch has been lost during cycle execution.

- Check limit switch adjustment.

4.2 Insufficient vacuum:

4.2.1 Leakage in the bag:

Most frequently, insufficient vacuum in bags is due to leakage in bag and not due to any fault of the machine.

Pin-hole leak for which there is no obvious explanation is due to faulty bag material.

Pin-hole leak caused by sharp edge of the product (bone, etc.). Use bone-guard or thicker film.

Tear in bag by careless handling (sharp edge on filling table, damage made by retailer or customer).

Leakage in lateral or bottom seal, complain to supplier of bags or film.

4.2.2 No leakage in the bag:

Bag is too large, therefore the surplus of air remains visible (there is surplus of air in... 0.4% of the bag volume in each bag). Use bags of suitable size.

Evacuation time is too short:

Pressure bar is jammed and closes opening of bag during evacuation.

4.2.3 Insufficient vacuum in chamber:

If troubles described under 4.2.1 and 4.2.2 do not apply, there is something wrong with the evacuation. To find the leakage quickly, check for leaks with a precision vacuumeter, going back step by step from the chamber to the pump.

At the chamber (measuring point at base of valve) at maximum time of evacuation. If more than 6 torr, proceed directly to the pump, if more than 3 torr: have pump service by pump supplier. If pressure at pump is good, reconnect hoses to pump and measure again.

Verify at vacuum hose connections and valve connections.

When proceeding this way, starting from pump, loss of pressure per step must not exceed 0.5 to 1 torr.

Warning: Verify connections of measuring equipment before verifying machine.

Most frequent points of leakage: lid gasket, damaged vacuum hose or loose hose clamps.

4.3 Faulty seal:

4.3.1 Insufficient seal:

Damaged teflon or silicone rubber.

Sealing pressure too low, bellows leaking or pressure bar jammed.

Leakers in seal: heating wire mechanically damaged (knicked) or silicone rubber uneven.

4.3.2 No seal:

Sealing wire burnt.

Faulty contact in sealing circuit.

Sealing transformer burnt through.

Contactors does not work.

4.3.3 Permanent sealing current:

Contactors is jammed check sealing transformer for damage through overload.

4.3.4 Seal does not stick:

Insufficient layer of polyethylene (inferior quality of bags).

Seal area extremely contaminated by fat or meat juice. Use filling aid.

Sealing temperature is too low (when using very thick films).

* Warning: Do not increase sealing time more than really necessary; higher temperature will reduce working life of teflon and silicone rubber.

4.4 Fault in the valve:

Vacuum or air valve does not open.

Check whether there is voltage on the magnetic valves during their period of operation. If there is no voltage a wire is broken or the PC board is damaged.

Lid does not open at the end of the cycle; air enters, but there is still 20 - 40% vacuum in chamber. Vacuum valve does not close.

4.5 MC40 Control board failure

NOTE: Refer to menu structure on page 8.

This board software is allowing access to a "Diagnostics Menu". Only qualified service technicians are authorized to access this menu by entering a security password.

By acceding either the "D1 input test" feature or the "D2 output test" feature, a trained technician will be able to quickly know the origin of the problem: pump, sealing system, pneumatic problem, security switches problem, etc...

Keep in mind that in most cases trouble is due to a leakage, loose electrical connection or evident damage to the main component: vacuum pump, valves..., electrical contactors, thermal overload, fuses holder or transformer.

For assistance do not hesitate to contact your local service technicians.

5. Regular maintenance:

Routine controls to be made at regular intervals:

Check teflon for wear.

Check silicone rubber for burnt spots and smooth even position.

Check pressure bar for jamming.

Check lid sealing for damage and hardened spots.

Check switch-point of micro switch, adjust if necessary.

Check evacuation hose for damage (contraction of diameter, or abrasions).

Check vacuum connections for tightness.

Check oil in pump (oil level in view glass; add if necessary. Regular change of oil - necessity indicated by change of color).

Check vacuum in chamber with precision vacuumeter.


Check function of cycle with various settings of timers.

INSTALLATION NOTICE FOR MODELS: 420A, 450T, 450A, 550A, 600A, 620A, 650A AND 700A


IN ORDER TO RESPECT NSF REGULATIONS:

NOTE: A PLASTIC CAP IS INSTALLED ON THE TABLE TOP VACUUM INLET USED FOR LEANING PURPOSES ONLY AND IS TO BE REMOVED PRIOR TO OPERATING THE MACHINE.











MECHANICAL DRAWING



ITEM	PART #	DESCRIPTION	QT.
1	005A0352	MACHINE ASSEMBLY FRONT VIEW	1
2	051-0783	FLAT WASHER 3/8" (THICK) S/S	12
3	051-0360	HEX. BOLT 3/8"-16 NC. X 1" S/S	6
4	051-0620	HEX. NUT 3/8"-16 NC.	6
5	005-0374	ELECTRICAL BOX PRE-ASSEMBLY	1
6	001-1364	LEFT/ ELECTRICAL BOX UPPER SUPPORT	1
7	051-0180	HEX. BOLT 1/4"-20 NC. X 1/2" S/S	4
8	051-0740	FLAT WASHER 1/4" S/S	12
9	051-0581	HEX. NUT 1/4"-20 NC. NYLON LOCK S/S	3
10	052-0402	HEX. BOLT 1/4"-20 X 1/2" BRASS	4
11	051-0190	HEX. BOLT 1/4"-20 NC. X 3/4" S/S	2
12	004-0279	E-BOX COVER ASSY	1
13	114-2020	DRYER FILTER	1
14	101-0210	STRAIGHT 1/4" FNPT X 1/4" HOSE	1
15	101-0200	STRAIGHT 1/4" MNPT X 1/4" HOSE	1
16	001-2062	DRYER SUPPORT	2
17	005-0323	GAS INLET ASSEMBLY (OPTION)	1
18	051-0180	HEX. BOLT 1/4"-20 NC. X 1/2" S/S (OPTION)	1
19	051-0740	FLAT WASHER 1/4" S/S (OPTION)	1
20	051-0581	HEX. NUT 1/4"-20 NC. NYLON LOCK S/S (OPTION)	1
21	005-0361	FRONT LEGS ASSEMBLY	2
22	005-0362	REAR LEGS ASSEMBLY	2
23	051-0300	HEX. BOLT 5/16"-18 NC. X 3/4" S/S	16
24	051-0760	FLAT WASHER 5/16" S/S	32
25	051-0860	HEX. NUT 5/16"-18 NC. S/S	16
26	130-5HPB	WHEEL W/ BRAKES (OPT.)	2
27	130-5PHO	WHEEL W/ O BRAKES (OPT.)	2
28	052-0520	HEX. BOLT 5/16"-18 NC. X 3/4" ZINC (OPT.)	16
29	052-2150	FLAT WASHER 5/16" ZINC (OPT.)	32
30	052-3110	HEX. NUT 5/16"-18 NC. ZINC (OPT.)	16
31	004A1472	PUMP "BUSCH" 165M3 ASSY	1
32	004A1473	PUMP "BUSCH" 255M3 ASSY	1
33	101-0200	STRAIGHT 1/4" MNPTX1/4" HOSE BARB	1
34	104-00633	SILICONE TUBING 1/2" OD X 1/4" ID 70 DURO (5 FT)	1
35	105-0450	METAL CABLE CLAMPS #6 SS	3
36	058-0025	NYLON SPACER .257ID x.500OD x"	3
37	051-0233	SCREW 1/4"-20x 1 1/4" PAN PHIL SS	2
38	051-0212	SCREW 1/4"-20x 1" PAN PHIL SS	1
39	051-0581	HEX. NUT 1/4"-20 NC. NYLON LOCK S/S	1
40	105-0220	1 EAR CLAMPS 1/2" SS	1
41	001-1876	LOWER WIRE SUPPORT	1



650A		SIPROMAC	
MACHINE		ST-GERMAIN DE GRANTHAM	
PART		QUEBEC CANADA	
ITEM #		SCALE	
MFR.		QT.	
DATE 04-12-16		NO. 005A0353	

METRIC TOLERANCE	INCH TOLERANCE
0.001 ± 0.005	0.005 ± 0.015
0.002 ± 0.005	0.010 ± 0.020
0.003 ± 0.005	0.015 ± 0.030
0.004 ± 0.005	0.020 ± 0.040
ANGLE ± 1°	N.T.S.


NOTE:
FOR GAS INJECTION
INSTALLATION SEE #010-0020

REV	MODIFIED VIEW ITEM #1	M.A.L.	DATE	INT.
R	MODIFIED PARTS #33 TO #41	M.A.L.	04-12-16	
Q	ADDED PARTS #33 TO #41	M.A.L.	04-11-09	
P	MODIF # A-0382	B.C.	04-02-27	
N	005-0374 ETAIT 005-0623	J.G.	04-01-06	
M	MODIF. #A-0337	Y.C.	02-11-12	
L	REDRAWN	S.L.	00-03-22	


1004B0137

SPRING ADJUSTMENT PROCEDURE

- A - PLACE COVER UP (ARMS VERTICAL) TO FREE TENSION OF SPRINGS.
- B - LOOSEN BOLTS ITEM #14 ON THE LEFT & RIGHT SPRING SUPPORT PLATE ASSY ITEM #9 & #10
- C - TURN SPRING/BLOCK ASSEMBLY TO OBTAIN 0mm AS SHOWN BELOW.



D - RETIGHTEN BOLTS ITEM #10 ON LEFT & RIGHT SPRING SUPPORT PLATE ASSY




ITEM	PART #	DESCRIPTION	QT.
1	005A0355	TABLE ASSEMBLY	1
2	009A0056	CENTRAL SHAFT	2
3	075-1650	FLANGED BEARING W/ GREASE FITTING 90°	4
4	051-0790	WASHER 1/2" FLAT S/S	8
5	051-0630	NUT 1/2"-13 S/S	8
6	051-0441	BOLT 1/2"-13 x 1 1/2" SS	8
7	008-0589	RIGHT COVER SPRING	2
8	008-0590	LEFT COVER SPRING	2
9	004A0222	LEFT SPRING SUPPORT ASSY	2
10	004A0170	RIGHT SPRING SUPPORT ASSY	2
11	002A0319	SPRING BLOCK	4
12	051-0540	NUT #4-40 HEX S/S	4
13	052-2060	FLAT WASHER 3/8" ZINC	24
14	052-0775	BOLT 3/8"-24x2-1/2" ZINC	8
15	052-3128	NUT 3/8"-24 UNF ZINC	16
16	005-0154	MICRO-SWITCH COLLAR ASSY	1
17	051-0334	SCREW 3/8"-16 x 3/8" SET HEX SKT	2
18	001-1294	MICRO-SWITCH FIXATION PLATE	2
19	026-0610	LIMIT SWITCH LONG ROLLER	2
20	051-0080	SCREW 4-40 x 5/8" RND SLOT SS	4
21	052-0777	BOLT 3/8"-24 x 3" ZINC	8
22	056-0168	KEY 1/4" SQ. x 1-1/2"	4
23	051-0580	NUT 1/4"-20nc. S/S	2
24	052-2071	WASHER 3/8" CONTACT BELLVILLE STL.	8
25	051-0783	WASHER 3/8" FLAT THICK S/S	8
26	051-0740	WASHER 1/4" FLAT S/S	2
27	051-0180	BOLT. HEX. 1/4"-20 NC. x 1/2" S/S	2
28	051-0715	WASHER #4 LOCK SS	4

DETAIL B

DETAIL A

MACHINE		DEPT. TOL. METRIC INCH	
PART		SHAFT ± 0.001	
ITEM		TOLERANCE ± 0.01	
MAT.		SOLDERAGE ± 0.020	
GNC		N.T.S.	
CENTRAL SHAFT ASSEMBLY		ST-GERMAIN DE GRANTHAM	
650A		QUEBEC CANADA	
DRAWN BY M.A.L.		DATE 05-05-12	
APP. BY		DATE 05-07-28	
REDRAWN S.E.		DATE 05-05-12	
MODIFICATION		DATE INT.	
H. LET.		M. I.	
QTY. 1		NO. 004B0137	




MACHINE FRONT VIEW

650-680-700 A

CENTRAL SHAFT ASSEMBLY


005A0583

ITEM	PART #	DESCRIPTION	QT.
1	004A0425	FRONT MC-40 SUPPORT PRE-ASS'Y	1
2	051-0092	SCREW #4-40 x 1 1/4" FLAT SLT S/S	4
3	051-0713	WASHER #4 FLAT S/S	4
4	058-0120	CPVC SPACER 0.120" x 1/4" x 5/8"	4
5	051-0540	NUT #4-40 HEX S/S	8
6	051-0715	WASHER #4 LOCK SS	4



033-0015 OR
033-0017 OR
033-0018 OR
KEY BOARD REF.
(NOT INCLUDED)

USE JIG TO INSTALL, IN REGARDS TO OPENINGS IN ITEM #1




MACHINE	420A, 450A, 450T, 500A, 550A, 600A, 620A & 650A	UNIT	INCH
PART	FRONT MC-40 SUPPORT ASS'Y	USINCS	± 0.005
ITEM		TOLERIE	± 0.005
MAT.		SOLDAGE	± 0.003T
			± 0.003T
			N.T.S.
DATE	05-09-01	DEPT.	M
APP. BY	M.A.L.	QTY.	1

REDRAWN	050901	M.A.
MODIFICATION	DATE	INT.

005A0583

1005A0465

ITEM	PART #	DESCRIPTION	QT.
1	004A0138	STRUCTURE PRE-ASSY	1
2	005A0584	REAR MC-40 SUPPORT ASSY	1
3	051-0287	BOLT 1/4-20 x 3-1/4" S/S	4
4	051-0757	WASHER 1/4" FLAT THICK S/S	4
5	058-0140	PLASTIC SPACER 0.266" x 1/2" x 2 1/4"	4
6	051-0750	WASHER 1/4" LOCK S/S	4
7	051-0580	NUT 1/4"-20nc. S/S	4
8	057-5010	NYLON SCREW #10 RECEPTACLE INSERT	8
9	001A3230	STRUCTURE COVER	1
10	054-0180	METAL SCREW #6 x 3/8" PAN SLOT S/S	8




-UNE FOIS L'ITEM 2 INSTALLÉ, UTILISER DE L'ADHÉSIF MARIN 5200 #169-0210 POUR SCELLER LE HAUT, LES CÔTES ET LES COINS DU BAS (LE CÔTÉ DU DESSOUS N'EST PAS SCELLÉ)

-ONCE ITEM 2 IS INSTALLED, USE 169-0210 5200 MARINE ADHESIVE TO SEAL TOP, SIDES & BOTTOM CORNERS (UNDER SIDE NOT SEALED)


MACHINE		DEPT. TOL. METRIC INCH.		SIPROMAC	
PART		TOLERANCE		ST. GERMAIN DE GRANTHAN	
ITEM		SOUDAGE		QUEBEC CANADA	
MAT.		N.T.S.		DEPT. I.	
DWG BY		DATE		NO.	
APP. BY		DATE		NO.	
M.A.L.		05-09-07		M	
MODIFICATION		25-1-23		005A0465	
REDRAWN		05-09-07		M.A.	
MODIFICATION		DATE		INT.	

004A0254

ITEM	PART #	DESCRIPTION	QT.
1	002A0332	SEAL BAR	1
2	039-0268	DOUBLE SEAM BAND (8MM) (3.1)	1
3	176-0200	TEFLON TAPE 5MIL (0.104)	1
4	056-1401	3/8" SET SCREW BANDING BUCKLE S/S	2
5	052-0393	SCREW 1/4-28x3/16" SKT SET OVAL POINT ZINC	2
6	051-0100	SCREW 8-32 X 3/8" PAN PHIL S/S	2
7	051-0550	NUT #8-32 SS	4
8	027-0400	CONNECTOR ADAPTOR	2
9	001A2742	8mm ELEMENT BINDER	2
10	051-0146	SCREW 10-24 X 1" PAN PHIL S/S	2
11	051-0572	LOCK NUT #10-24 S/S	2
12	171-0180	TAPE CLEAR SUPER BOND 3/4" 854.5mm (0.026)	2



-DÉTAIL A-



-TWIN SEAL OPTION-

DEPT. / INCH	± 0.020"
TOLENCES	± 0.05
SOUDEAGE	± 0.5
N.T.S.	
DEPT.	M-1
DATE	06-01-16
DRAWN BY	M.A.L.
APP. BY	B
NO.	004A0254
LIST	004A0254

REVISION	580A, 650A, 680A & 700A
PART	SEAL BAR PRE-ASSY
ITEM	
MAT.	
DATE	06-04-19
DATE	06-01-16
DATE	
INT.	
INT.	

INSTALLER CONTRE L'ENCOCHE DE L'ITEM #8 (4) INSTALL AGAINST NOTCH OF ITEM #8

ADDED 052-0393
 REDRAWN
 MODIFICATION


06-04-19 M.A.
 06-01-16 M.A.
 DATE INT.
 DATE INT.

E
 D
 LET.

1005B0548

ITEM	PART #	DESCRIPTION	QT.
1	004A0255	SEAL BAR PRE-ASSY	1
2	051-0581	NUT 1/4"-20 NYLON LOCK S/S	10
3	051-0256	BOLT 1/4"-20nc. X 1 3/4" CAP SKT S/S	5
4	051-0230	HEX BOLT 1/4"-20 x 1 1/4" SS	10
5	051-0740	WASHER 1/4" FLAT S/S	8
6	002A0357	SEAL BAR SUPPORT	1
7	001A1901	EXTERIOR BELLOWS COVER	1
8	001A1900	INTERIOR BELLOWS COVER	1
9	001-0269	SEAL BAR GUIDE	2
10	038-0230	WIRING DUCT W/ ADHESIVE BACKING (0.35" x 0.5" x 600 (2.1)	1

CUTTING ELEMENT THIS SIDE



-BAG CUT OPTION-

700A	4
680A	4
650A	4
MACHINE	QTY


MACHINE	650A, 680A & 700A	DEPT.	M-1	DT	LIST
PART	SEAL BAR ASSY W/SUPPORT	DATE	06-01-16	NO	005B0548
ITEM		DATE	06-01-16	NO	005B0548
MAT.		DATE	06-01-16	NO	005B0548

UNIT	INCH	CONV.	25.4
TOLERANCE	± 0.1	± 0.004	
SOUDAGE	± 0.5	± 0.020	
	± 0.3	± 0.020	
		N.T.S.	

F	REDRAWN	06-01-16	M.A.
LET.	MODIFICATION	DATE	INT.

1004A0255

ITEM	PART #	DESCRIPTION	QT.
1	009A0193	ECO SEAL BAR	1
2	077-0095	SPRING C 0360-059-1250 S/S	2
3	001-2666	ELEMENT BINDER	2
4	051-0146	SCREW 10-24 X 1" PAN PHIL S/S	2
5	051-0572	LOCK NUT #10-24 S/S	2
6	051-0100	SCREW 8-32 X 3/8" PAN PHIL S/S	2
7	051-0550	NUT #8-32 SS	4
8	027-0400	CONNECTOR ADAPTOR	2
9	179-0003	SILICONE 2mm x 15mm ADHESIVE (0.89)	1
10	176-0220	TEFLON TAPE, PRESS SENSITIVE 2" 854.5mm (0.104)	1
11	039-0269	SEAL CUT ELEMENT (0.0892)	1
12	056-1400	1/4" SET SCREW BANDING BUCKLE S/S	2
13	176-0203	TEFLON TAPE, 5MIL UNCOATED ZONE 854.5mm (0.085)	1
14	171-0180	TAPE CLEAR SUPER BOND 3/4" 854.5mm (0.026)	2



-BAG CUT OPTION-


700A	4
680A	4
650A	4
580A	2
MACHINE	QTY

MACHINE	DEPT. TOL. METRIC	INCH
580A, 650A, 680A & 700A	USURAGE ±0.1	±0.004
PART	CHARGE ±0.5	±0.025
	SOUDAGE ±0.5	±0.025
	N.T.S.	
ITEM	DWG BY	DATE
	M.A.L.	06-01-16
	APP. BY	DATE
		06-05-16
		004A0255

D	REDESSINE	06-01-16	M.A.
LEL	MODIFICATION		INT.

SIPROMAC
ST-GERMAIN DE GRANTHAM
QUEBEC CANADA

ITEM	PART #	DESCRIPTION	QTY.
1	002B0364	UPPER SEAL BAR SUPPORT	2
2	008-0374	UPPER SEAL BAR RUBBER	2
3	176-0200	TEFLON TAPE (5S) ADHESIVE (2" x 936MM) 0.12	




NOTE:
-FOR ELECTRICAL BAG CUT OPTION ONLY

MACHINE		580A, 650A, 680A & 700A		SIPROMAC	
PART		UPPER SEAL BAR ASSEMBLY		GERMAIN DE GRANTHAM QUEBEC CANADA	
ITEM		N.T.S.		SCALE	
DATE		99-08-20		QTY. 2	
BY: S. LAROUICHE		DATE		NO. 004B0207	

ADDED	DATE	M.A.L.	INT.
ADDED 580A	04-11-08		
ADDED 650A WAS 004B0139	00-02-01	S.L.	
REDRAWN WAS 004A0207	99-08-20	S.L.	
MODIFICATION	DATE		

005B0549

ITEM	PART #	DESCRIPTION	QT.
1	004A0256	SEAL BAR PRE-ASSY	1
2	051-0581	NUT 1/4"-20 NYLON LOCK S/S	10
3	051-0256	BOLT 1/4"-20nc. X 1 3/4" CAP SKT S/S	5
4	051-0230	HEX BOLT 1/4-20 x 1 1/4" SS	10
5	051-0740	WASHER 1/4" FLAT S/S	8
6	002A0357	SEAL BAR SUPPORT	1
7	001A1901	EXTERIOR BELLOWS COVER	1
8	001A1900	INTERIOR BELLOWS COVER	1
9	001-0269	SEAL BAR GUIDE	2
10	038-0230	WIRING DUCT W/ ADHESIVE BACKING (0.35" x 0.5" x 600 (2.1)	1



-TOP & BOTTOM SEALING OPTION-

700A	4
650A	4
650A	4
MACHINE	QTY



MACHINE	DEPT. FOR METRIC INCH	1.0000
PART	USMAGE	1.03
	TOLERANCE	± 0.020
	SOUDAGE	± 0.020
	N.T.S.	

650A, 680A & 700A	DATE	07-12-17
SEAL BAR ASS'Y W/SUPPORT	APP. BY	[Signature]
	DEPT.	M-1
	NO.	005B0549
	LIST	

F	REDRAWN	07-12-17	M.A.
LET	MODIFICATION	DATE	INT.

004A0256

ITEM	PART #	DESCRIPTION	QT.
1	002A0332	SEAL BAR	1
2	001-2666	ELEMENT BINDER	2
3	051-0146	SCREW 10-24 X 1" PAN PHIL S/S	2
4	051-0572	LOCK NUT #10-24 S/S	2
5	051-0100	SCREW 8-32 X 3/8" PAN PHIL S/S	2
6	051-0550	NUT #8-32 SS	4
7	027-0400	CONNECTOR ADAPTOR	2
8	179-0003	SILICONE 2mm x 15mm (0.9)	1
9	176-0220	TEFLON TAPE, PRESS SENSITIVE 2" (0.104)	1
10	039-0220	BI-ACTIVE SEALING ELEMENT (0.09)	1
11	056-1400	1/4" SET SCREW BANDING BUCKLE S/S	2
12	176-0200	TEFLON TAPE 5MIL (0.104)	1
13	171-0180	TAPE CLEAR SUPER BOND 3/4" 854.5mm (0.026)	2



-DÉTAIL A-

-TOP & BOTTOM
SEALING OPTION-

580A, 650A, 680A & 700A
SEAL BAR PRE-ASSY

700A	4
680A	4
650A	4
580A	2
MACHINE	QTY
SIPROMAC	
ST-GERMAIN DE GRANITIAM QUEBEC CANADA	

DESIGNATION	REVISE	DATE
TOUVERIE	1.0.1	07-12-17
SOUDEAGE	1.0.5	07-12-17
N.T.S.		




MACHIN: _____ DEPT: _____
 DWG BY: M.A.L. DATE: 07-12-17 NO: 004A0256
 APP. BY: _____
 LIST

E: _____ REDRAWN: _____ DATE: 07-12-17 M.A.
 LET: _____ MODIFICATION: _____ DATE: INT.

INSTALL AGAINST NOTCH OF ITEM #2
INSTALLER CONTRE L'ENCOCHE DE L'ITEM #2

1005B0437

ITEM	PART #	DESCRIPTION	QT.
1	002B0378	UPPER SEAL BAR SUPPORT	1
2	002B0396	UPPER SEAL BAR	1
3	051-0220	SCREW 1/4"-20nc x 1" SKT. CAP S/S	8
4	001-2666	ELEMENT BINDER	2
5	051-0146	SCREW 10-24 X 1" PAN PHIL S/S	2
6	051-0572	LOCK NUT #10-24 S/S	2
7	051-0104	SCREW 8-32 x 3/8" RND PHIL S/S	2
8	051-0550	NUT #8-32 SS	4
9	027-0400	CONNECTOR ADAPTOR	2
10	179-0003	SILICONE 2mm x 15mm ADHESIVE 828mm (0.83)	1
11	176-0220	TEFLON TAPE, PRESS SENSITIVE 2" 828mm (0.10)	2
12	039-0220	BI-ACTIVE SEALING ELEMENT (6mm) 871mm (0.087)	1
13	056-1400	1/4"SET SCREW BANDING BUCKLE S/S	2
14	171-0180	TAPE CLEAR SUPER BOND 3/4" 795mm (0.024)	2




DETAIL A

-TOP & BOTTOM SEALING OPTION-

MATRICE 580A, 650A, 680A & 700A		DEPT. COL. METRIC INCH USAGE 4.01 4.0000 Soudage 4.05 4.0200	SIPROMAC ST-GERMAIN DE GRANTHAM QUEBEC, CANADA
PART UPPER SEAL BAR ASSY W/SUPPORT		N.T.S.	DATE 07-12-17 DWG BY J.G. APP. BY [Signature]
ITEM	QTY	DEPT.	QTY
		M-I	2
REVISIONS 07-12-17 J.G. DATE INT.		005B0437	

REVISIONS
 07-12-17 J.G.
 DATE INT.

ITEM	PART #	DESCRIPTION	QTY.
1	004-0329	SEAL BAR PRE-ASSEMBLY	1
2	002-0398	SEAL BAR SUPPORT	1
3	051-0251	CAP HEX. SKT BOLT 1/4"-20 NC. X 1 1/2" S/S	5
4	001-1903	EXTERIOR BELLOWS COVER	1
5	001-1904	INTERIOR BELLOWS COVER	1
6	001-1631	SEAL BAR GUIDE	2
7	001-1578	SEAL BAR GUIDE SPACER	4
8	038-0230	W/ING. DUCT W/ ADHESIVE BACKING (0.35" X 0.5" X 600 MM) PVC	2.1
9	051-0255	HEX. BOLT 1/4"-20 NC. X 1 3/4" S/S	6
10	051-0260	HEX. BOLT 1/4"-20 NC. X 2" S/S	4
11	051-0581	HEX. NUT 1/4"-20 NC. NYLON LOCK S/S	10
12	051-0740	FLAT WASHER 1/4" S/S	8



--- MECHANICAL BAG CUT OPTION (MBC) ---

MACHINE	650A & 700A
PART	SEAL BAR ASSEMBLY
ITEM:	
MAT:	
ENG:	
BY:	P. PRINCEVEICHER
AP.P.	
DATE	98-06-12
SCALE	1/1" = 1"
QTY.	4


SIPROMAC
 ST-GERMANN DE GRANTHAM
 QUEBEC CANADA

D	ADDED 650A WAS 005-0356	S.L.	00-02-07
C	REDRAWN/ MODIF. NO. A-0245	A.P.	98-06-12
LET.	MODIFICATION	DATE	

NOTE:
 BEVELED EDGE
 THIS SIDE TYP. (ITEM 6)

005-0550

ITEM	PART #	DESCRIPTION	QT.
1	002-0332	SEAL BAR (TABLE)	1
2	002-0031	CONNECTOR	2
3	179-0003	SILICONE 2mm x 15mm ADHESIVE (852mm EA.) 0.890	
4	176-0220	TEFLON TAPE (10S) ADHESIVE .862mm 0.109	
5	039-0230	REFLEX BAND 2.5mm (992mm EA.) 0.104	
6	052-0395	SET SCREW 1/4" - 20 x 5/16" (OVAL POINT)	4
7	052-0250	SCREW #8-32 x 1 1/2" RND SLOT BRASS	2
8	051-0550	NUT #8-32 S/S	4
9	027-0400	CONNECTOR ADAPTOR	2
10	176-0200	TEFLON TAPE (5S) ADHESIVE (862mm EA.) 0.109	
11	002-0339	BAG HOLD BAR	1
12	001-0266	TEFLON SUPPORT (TABLE)	1
13	051-0158	SCREW #10-24 x 1 3/4" FLAT PHILL	S/S 6
14	051-0571	NUT #10-24 S/S	6



NOTE: ITEM #2(CONNECTOR) SHOULD NOT STICK OUT FROM ITEM #1 (SEAL BAR) ON THE SIDE THAT HAS ITEM #12 (TEFLON SUPPORT)

NOTE: INSTALL ITEM #9 AT ±45° TYP.


NOTE: CUT OFF HEAD OF SCREW AFTER ASSEMBLING

-MECHANICAL BAG CUT OPTION (MBC)-

MACHINE	650A & 700A	INCH TOLERANCE 0.005 0.010 0.015 0.020 0.030 0.040 0.050 0.060 0.070 0.080 0.090 0.100	DATE	96-06-25	IND	004-0329
PART	SEAL BAR PRE-ASSY (TABLE)	METRIC TOLERANCE 0.05 0.10 0.15 0.20 0.30 0.40 0.50 0.60 0.70 0.80 0.90 1.00	DATE		IND	
ITEM:		ANGLE ± 1°	DATE		IND	
MAT:		N.T.S.	DATE		IND	
APP:	BWS M. LAVIGNE		DATE		IND	
QTY:	4		DATE		IND	

LET.	A	ITEM NO. 5 WAS 039-0200/ MODIF. A-020297-05-08	DATE	A.P.
		MODIFICATION		INT.

ITEM	PART #	DESCRIPTION	QTY.
1	004-0449	UPPER SEAL BAR PRE-ASSEMBLY	1
2	002B0337	BAG HOLD BAR SUPPORT	1
3	077-0030	INTERIOR COMPRESSION SPRING	10
4	077-0100	EXTERIOR COMPRESSION SPRING	10
5	002A0395	BAG HOLD BAR	1
6	179-0002	SILICONE 1/4" X 3/8" X 845 MM GRAY 60	2.8
7	003-0066	COUNTER BAR & BAG HOLDER BAR SCREW	5
8	009-0058	CUTTING BLADE	1
9	001A1573	COUNTER BAR SPACER SUPPORT	1
10	051-0260	HEX. BOLT 1/4"-20 NC. X 2" S/S	5
11	004B0149	PERFORATOR SUBSTITUTE ASSEMBLY	1
12	051-0375	SCREW 3/8"-16 NC. X 1 1/2" FLAT HEX. SKT S/S	4
13	051-0621	HALF HEX. NUT 3/8"-16 NC. S/S	4



END VIEW "A-A"
(END VIEW ASSEMBLY)

MECHANICAL BAG CUT OPTION (MBC)

MACHINE
650A

PART
UPPER SEAL BAR ASSEMBLY

INCH TOLERANCE
0 ± .015
.00 ± .005
(.00 ± .0005)

METRIC TOLERANCE
0 ± .015
0.00 ± .005
(.00 ± .0005)

N.T.S.
ANGLE #1

SIPROMAC
ST-GERMAIN DE GRANTHAM
QUEBEC CANADA

DATE 00-02-03
DATE 11-1-03
APP. [Signature]
CHK. [Signature]
REV. SYLVAIN L.
SCALE M-1
DT. 2


NOTE:
INSTALL BAG HOLD BAR ASSEMBLY IN COVER USING SCREWS (2) & NUTS (13) BEFORE INSTALLING CUTTING BLADE (8) & COUNTER BAR SUPPORT SPACER (9) WITH COUNTER BAR ASSEMBLY TO BAG HOLD BAR ASSEMBLY WITH BOLT (10) & NUTS (1)

USE "BLACK MAX" #169-0020 TO INSTALL


LET.	REDRAWN	MODIFICATION	DATE	S.L.	INT.
			00-02-03		

005B0442

ITEM	PART #	DESCRIPTION	QT.
1	002A0394	COUNTER BAR SUPPORT	1
2	077-0030	INTERIOR COMPRESSION SPRING	10
3	077-0100	EXTERIOR COMPRESSION SPRING	10
4	002-0543	UPPER SEAL BAR	1
5	003-0066	COUNTER BAR & BAG HOLDER BAR SCREW	5
6	001-2087	UPPER TEFLON HOLDER	2
7	179-0003	SILICONE 15MM X 2MM X 861 MM	0.9
8	176-0200	TEFLON TAPE (5S) ADHESIVE	0.1
9	051-0121	SCREW #8-32 NC. X 1" FLAT PHIL. S/S	8
10	051-0550	HEX. NUT #8-32 NC. S/S	8



PART ON THIS SIDE HAS COUNTERSUNK HOLES FOR ITEM (9)



- MECHANICAL BAG CUT OPTION (MBC) -


MACHINE	650A & 700A	INCH TOLERANCE	0.005	METRIC TOLERANCE	0.15	DATE	98-06-16	NO.	98-06-16
PART	UPPER SEAL BAR PRE-ASSEMBLY	0.0005	0.005	0.0005	0.005	DATE		NO.	
ITEM		0.0005	0.0005	0.0005	0.0005	DATE		NO.	
MAT.		0.0005	0.0005	0.0005	0.0005	DATE		NO.	
		N.T.S.		N.T.S.		DATE		DATE	
		SCALE		SCALE		DATE		DATE	
		M-1		M-1		DATE		DATE	
		QTY		QTY		DATE		DATE	
		2		2		DATE		DATE	

B	ADDED 650A WAS 004-0457	00-02-07	S.L.
A	WAS 005-0440	98-06-16	A.P.
ET.	MODIFICATION	DATE	INT.


004-0449

SIPROMAC
ST-GERMAIN DE GRANTHAM
QUEBEC CANADA

ITEM	PART #	DESCRIPTION	QTY
1	004-0330	SEAL BAR PRE-ASSEMBLY (TBS)	1
2	002-0398	SEAL BAR SUPPORT	1
3	051-0251	CAP HEX. SKI BOLT 1/4"-20 NC. X 1 1/2" S/S	5
4	001-1903	EXTERIOR BELLOWS COVER	1
5	001-1904	INTERIOR BELLOWS COVER	1
6	001-1631	SEAL BAR GUIDE	2
7	001-1578	SEAL BAR GUIDE SPACER (3 MM THK. ONLY)	4
8	038-0230	WRING DUCT W/ ADHESIVE BONDING (0.35" X 0.5" X 600 MM) PVC 2.1	2.1
9	051-0255	HEX. BOLT 1/4"-20 NC. X 1 3/4" S/S	6
10	051-0260	HEX. BOLT 1/4"-20 NC. X 2" S/S	4
11	051-0581	HEX. NUT 1/4"-20 NC. NYLON LOCK S/S	10
12	051-0740	FLAT WASHER 1/4" S/S	8



ITEM 12 FLUSH WITH ITEM (4) & (5)




NOTE:
BEVELED EDGE
THIS SIDE (Y.P. (ITEM 6))

MECHANICAL BAG CUT TOP & BOTTOM SEALING OPTION (MBC/TBS)

MACHINE: **650A & 700A** SIPROMAC
 PART: **SEAL BAR ASSEMBLY** ST-GERMAIN DE GRANTHAM QUEBEC CANADA
 INCH TOLERANCE: .005 ± .010 ± .015 ± .020 ± .030 ± .040 ± .050 ± .060 ± .080 ± .100 ± .125 ± .150 ± .200 ± .250 ± .300 ± .375 ± .500 ± .625 ± .750 ± .875 ± 1.000 ± 1.250 ± 1.500 ± 1.750 ± 2.000 ± 2.500 ± 3.000 ± 3.750 ± 4.500 ± 5.000 ± 6.000 ± 7.500 ± 9.000 ± 10.000 ± 12.500 ± 15.000 ± 17.500 ± 20.000 ± 25.000 ± 30.000 ± 37.500 ± 45.000 ± 50.000 ± 60.000 ± 75.000 ± 90.000 ± 100.000 ± 125.000 ± 150.000 ± 175.000 ± 200.000 ± 250.000 ± 300.000 ± 375.000 ± 450.000 ± 500.000 ± 600.000 ± 750.000 ± 900.000 ± 1000.000 ± 1250.000 ± 1500.000 ± 1750.000 ± 2000.000 ± 2500.000 ± 3000.000 ± 3750.000 ± 4500.000 ± 5000.000 ± 6000.000 ± 7500.000 ± 9000.000 ± 10000.000 ± 12500.000 ± 15000.000 ± 17500.000 ± 20000.000 ± 25000.000 ± 30000.000 ± 37500.000 ± 45000.000 ± 50000.000 ± 60000.000 ± 75000.000 ± 90000.000 ± 100000.000 ± 125000.000 ± 150000.000 ± 175000.000 ± 200000.000 ± 250000.000 ± 300000.000 ± 375000.000 ± 450000.000 ± 500000.000 ± 600000.000 ± 750000.000 ± 900000.000 ± 1000000.000 ± 1250000.000 ± 1500000.000 ± 1750000.000 ± 2000000.000 ± 2500000.000 ± 3000000.000 ± 3750000.000 ± 4500000.000 ± 5000000.000 ± 6000000.000 ± 7500000.000 ± 9000000.000 ± 10000000.000 ± 12500000.000 ± 15000000.000 ± 17500000.000 ± 20000000.000 ± 25000000.000 ± 30000000.000 ± 37500000.000 ± 45000000.000 ± 50000000.000 ± 60000000.000 ± 75000000.000 ± 90000000.000 ± 100000000.000 ± 125000000.000 ± 150000000.000 ± 175000000.000 ± 200000000.000 ± 250000000.000 ± 300000000.000 ± 375000000.000 ± 450000000.000 ± 500000000.000 ± 600000000.000 ± 750000000.000 ± 900000000.000 ± 1000000000.000 ± 1250000000.000 ± 1500000000.000 ± 1750000000.000 ± 2000000000.000 ± 2500000000.000 ± 3000000000.000 ± 3750000000.000 ± 4500000000.000 ± 5000000000.000 ± 6000000000.000 ± 7500000000.000 ± 9000000000.000 ± 10000000000.000 ± 12500000000.000 ± 15000000000.000 ± 17500000000.000 ± 20000000000.000 ± 25000000000.000 ± 30000000000.000 ± 37500000000.000 ± 45000000000.000 ± 50000000000.000 ± 60000000000.000 ± 75000000000.000 ± 90000000000.000 ± 100000000000.000 ± 125000000000.000 ± 150000000000.000 ± 175000000000.000 ± 200000000000.000 ± 250000000000.000 ± 300000000000.000 ± 375000000000.000 ± 450000000000.000 ± 500000000000.000 ± 600000000000.000 ± 750000000000.000 ± 900000000000.000 ± 1000000000000.000 ± 1250000000000.000 ± 1500000000000.000 ± 1750000000000.000 ± 2000000000000.000 ± 2500000000000.000 ± 3000000000000.000 ± 3750000000000.000 ± 4500000000000.000 ± 5000000000000.000 ± 6000000000000.000 ± 7500000000000.000 ± 9000000000000.000 ± 10000000000000.000 ± 12500000000000.000 ± 15000000000000.000 ± 17500000000000.000 ± 20000000000000.000 ± 25000000000000.000 ± 30000000000000.000 ± 37500000000000.000 ± 45000000000000.000 ± 50000000000000.000 ± 60000000000000.000 ± 75000000000000.000 ± 90000000000000.000 ± 100000000000000.000 ± 125000000000000.000 ± 150000000000000.000 ± 175000000000000.000 ± 200000000000000.000 ± 250000000000000.000 ± 300000000000000.000 ± 375000000000000.000 ± 450000000000000.000 ± 500000000000000.000 ± 600000000000000.000 ± 750000000000000.000 ± 900000000000000.000 ± 1000000000000000.000 ± 1250000000000000.000 ± 1500000000000000.000 ± 1750000000000000.000 ± 2000000000000000.000 ± 2500000000000000.000 ± 3000000000000000.000 ± 3750000000000000.000 ± 4500000000000000.000 ± 5000000000000000.000 ± 6000000000000000.000 ± 7500000000000000.000 ± 9000000000000000.000 ± 10000000000000000.000 ± 12500000000000000.000 ± 15000000000000000.000 ± 17500000000000000.000 ± 20000000000000000.000 ± 25000000000000000.000 ± 30000000000000000.000 ± 37500000000000000.000 ± 45000000000000000.000 ± 50000000000000000.000 ± 60000000000000000.000 ± 75000000000000000.000 ± 90000000000000000.000 ± 100000000000000000.000 ± 125000000000000000.000 ± 150000000000000000.000 ± 175000000000000000.000 ± 200000000000000000.000 ± 250000000000000000.000 ± 300000000000000000.000 ± 375000000000000000.000 ± 450000000000000000.000 ± 500000000000000000.000 ± 600000000000000000.000 ± 750000000000000000.000 ± 900000000000000000.000 ± 1000000000000000000.000 ± 1250000000000000000.000 ± 1500000000000000000.000 ± 1750000000000000000.000 ± 2000000000000000000.000 ± 2500000000000000000.000 ± 3000000000000000000.000 ± 3750000000000000000.000 ± 4500000000000000000.000 ± 5000000000000000000.000 ± 6000000000000000000.000 ± 7500000000000000000.000 ± 9000000000000000000.000 ± 10000000000000000000.000 ± 12500000000000000000.000 ± 15000000000000000000.000 ± 17500000000000000000.000 ± 20000000000000000000.000 ± 25000000000000000000.000 ± 30000000000000000000.000 ± 37500000000000000000.000 ± 45000000000000000000.000 ± 50000000000000000000.000 ± 60000000000000000000.000 ± 75000000000000000000.000 ± 90000000000000000000.000 ± 100000000000000000000.000 ± 125000000000000000000.000 ± 150000000000000000000.000 ± 175000000000000000000.000 ± 200000000000000000000.000 ± 250000000000000000000.000 ± 300000000000000000000.000 ± 375000000000000000000.000 ± 450000000000000000000.000 ± 500000000000000000000.000 ± 600000000000000000000.000 ± 750000000000000000000.000 ± 900000000000000000000.000 ± 1000000000000000000000.000 ± 1250000000000000000000.000 ± 1500000000000000000000.000 ± 1750000000000000000000.000 ± 2000000000000000000000.000 ± 2500000000000000000000.000 ± 3000000000000000000000.000 ± 3750000000000000000000.000 ± 4500000000000000000000.000 ± 5000000000000000000000.000 ± 6000000000000000000000.000 ± 7500000000000000000000.000 ± 9000000000000000000000.000 ± 10000000000000000000000.000 ± 12500000000000000000000.000 ± 15000000000000000000000.000 ± 17500000000000000000000.000 ± 20000000000000000000000.000 ± 25000000000000000000000.000 ± 30000000000000000000000.000 ± 37500000000000000000000.000 ± 45000000000000000000000.000 ± 50000000000000000000000.000 ± 60000000000000000000000.000 ± 75000000000000000000000.000 ± 90000000000000000000000.000 ± 100000000000000000000000.000 ± 125000000000000000000000.000 ± 150000000000000000000000.000 ± 175000000000000000000000.000 ± 200000000000000000000000.000 ± 250000000000000000000000.000 ± 300000000000000000000000.000 ± 375000000000000000000000.000 ± 450000000000000000000000.000 ± 500000000000000000000000.000 ± 600000000000000000000000.000 ± 750000000000000000000000.000 ± 900000000000000000000000.000 ± 1000000000000000000000000.000 ± 1250000000000000000000000.000 ± 1500000000000000000000000.000 ± 1750000000000000000000000.000 ± 2000000000000000000000000.000 ± 2500000000000000000000000.000 ± 3000000000000000000000000.000 ± 3750000000000000000000000.000 ± 4500000000000000000000000.000 ± 5000000000000000000000000.000 ± 6000000000000000000000000.000 ± 7500000000000000000000000.000 ± 9000000000000000000000000.000 ± 10000000000000000000000000.000 ± 12500000000000000000000000.000 ± 15000000000000000000000000.000 ± 17500000000000000000000000.000 ± 20000000000000000000000000.000 ± 25000000000000000000000000.000 ± 30000000000000000000000000.000 ± 37500000000000000000000000.000 ± 45000000000000000000000000.000 ± 50000000000000000000000000.000 ± 60000000000000000000000000.000 ± 75000000000000000000000000.000 ± 90000000000000000000000000.000 ± 100000000000000000000000000.000 ± 125000000000000000000000000.000 ± 150000000000000000000000000.000 ± 175000000000000000000000000.000 ± 200000000000000000000000000.000 ± 250000000000000000000000000.000 ± 300000000000000000000000000.000 ± 375000000000000000000000000.000 ± 450000000000000000000000000.000 ± 500000000000000000000000000.000 ± 600000000000000000000000000.000 ± 750000000000000000000000000.000 ± 900000000000000000000000000.000 ± 1000000000000000000000000000.000 ± 1250000000000000000000000000.000 ± 1500000000000000000000000000.000 ± 1750000000000000000000000000.000 ± 2000000000000000000000000000.000 ± 2500000000000000000000000000.000 ± 3000000000000000000000000000.000 ± 3750000000000000000000000000.000 ± 4500000000000000000000000000.000 ± 5000000000000000000000000000.000 ± 6000000000000000000000000000.000 ± 7500000000000000000000000000.000 ± 9000000000000000000000000000.000 ± 10000000000000000000000000000.000 ± 12500000000000000000000000000.000 ± 15000000000000000000000000000.000 ± 17500000000000000000000000000.000 ± 20000000000000000000000000000.000 ± 25000000000000000000000000000.000 ± 30000000000000000000000000000.000 ± 37500000000000000000000000000.000 ± 45000000000000000000000000000.000 ± 50000000000000000000000000000.000 ± 60000000000000000000000000000.000 ± 75000000000000000000000000000.000 ± 90000000000000000000000000000.000 ± 100000000000000000000000000000.000 ± 125000000000000000000000000000.000 ± 150000000000000000000000000000.000 ± 175000000000000000000000000000.000 ± 200000000000000000000000000000.000 ± 250000000000000000000000000000.000 ± 300000000000000000000000000000.000 ± 375000000000000000000000000000.000 ± 450000000000000000000000000000.000 ± 500000000000000000000000000000.000 ± 600000000000000000000000000000.000 ± 750000000000000000000000000000.000 ± 900000000000000000000000000000.000 ± 1000000000000000000000000000000.000 ± 1250000000000000000000000000000.000 ± 1500000000000000000000000000000.000 ± 1750000000000000000000000000000.000 ± 2000000000000000000000000000000.000 ± 2500000000000000000000000000000.000 ± 3000000000000000000000000000000.000 ± 3750000000000000000000000000000.000 ± 4500000000000000000000000000000.000 ± 5000000000000000000000000000000.000 ± 6000000000000000000000000000000.000 ± 7500000000000000000000000000000.000 ± 9000000000000000000000000000000.000 ± 10000000000000000000000000000000.000 ± 12500000000000000000000000000000.000 ± 15000000000000000000000000000000.000 ± 17500000000000000000000000000000.000 ± 20000000000000000000000000000000.000 ± 25000000000000000000000000000000.000 ± 30000000000000000000000000000000.000 ± 37500000000000000000000000000000.000 ± 45000000000000000000000000000000.000 ± 50000000000000000000000000000000.000 ± 60000000000000000000000000000000.000 ± 75000000000000000000000000000000.000 ± 90000000000000000000000000000000.000 ± 100000000000000000000000000000000.000 ± 125000000000000000000000000000000.000 ± 150000000000000000000000000000000.000 ± 175000000000000000000000000000000.000 ± 200000000000000000000000000000000.000 ± 250000000000000000000000000000000.000 ± 300000000000000000000000000000000.000 ± 375000000000000000000000000000000.000 ± 450000000000000000000000000000000.000 ± 500000000000000000000000000000000.000 ± 600000000000000000000000000000000.000 ± 750000000000000000000000000000000.000 ± 900000000000000000000000000000000.000 ± 1000000000000000000000000000000000.000 ± 1250000000000000000000000000000000.000 ± 1500000000000000000000000000000000.000 ± 1750000000000000000000000000000000.000 ± 2000000000000000000000000000000000.000 ± 2500000000000000000000000000000000.000 ± 3000000000000000000000000000000000.000 ± 3750000000000000000000000000000000.000 ± 4500000000000000000000000000000000.000 ± 5000000000000000000000000000000000.000 ± 6000000000000000000000000000000000.000 ± 7500000000000000000000000000000000.000 ± 9000000000000000000000000000000000.000 ± 10000000000000000000000000000000000.000 ± 12500000000000000000000000000000000.000 ± 15000000000000000000000000000000000.000 ± 17500000000000000000000000000000000.000 ± 20000000000000000000000000000000000.000 ± 25000000000000000000000000000000000.000 ± 30000000000000000000000000000000000.000 ± 37500000000000000000000000000000000.000 ± 45000000000000000000000000000000000.000 ± 50000000000000000000000000000000000.000 ± 60000000000000000000000000000000000.000 ± 75000000000000000000000000000000000.000 ± 90000000000000000000000000000000000.000 ± 100000000000000000000000000000000000.000 ± 125000000000000000000000000000000000.000 ± 150000000000000000000000000000000000.000 ± 175000000000000000000000000000000000.000 ± 200

ITEM	PART #	DESCRIPTION	QT.
1	002-0332	SEAL BAR (TABLE)	1
2	009-0029	CONNECTOR	2
3	179-0003	SILICONE 2mm x 15mm ADHESIVE (852mm EA.)	0.890
4	176-0220	TEFLON TAPE (10S) ADHESIVE (862mm EA.)	0.109
5	176-0200	TEFLON TAPE (5S) ADHESIVE (2x862mm)	0.218
6	039-0220	BI-ACTIVE SEALING ELEM. (992mm EA.)	0.104
7	052-0395	SET SCREW 1/4" - 20 x 5/16" (OVAL POINT)	2
8	052-0250	SCREW #8-32 x 1 1/2" RND SLOT BRASS	2
9	051-0550	NUT #8-32 S/S	4
10	027-0400	CONNECTOR ADAPTOR	2
11	176-0200	STRIP TEFLON TAPE (5S) ADHESIVE (2x862mm)	0.218
12	176-0220	STRIP TEFLON TAPE (10S) ADHESIVE (862mm EA.)	0.109
13	002-0339	BAG HOLD BAR	1
14	001-0266	TEFLON SUPPORT (TABLE)	1
15	051-0158	SCREW #10-24 x 1 3/4" FLAT PHILL S/S	6
16	051-0571	NUT #10-24 S/S	6




MECHANICAL BAG CUT
 TOP & BOTTOM SEALING OPTION
 (MBC/TBS)

MACHINE	650A & 700A	SIPROMAC
PART	SEAL BAR PRE-ASSY (TABLE)	ST-GERMAIN DE GRANTHAM, QUEBEC CANADA
ITEM:		
MAT:		
DATE	97-02-06	NO.
DATE		DT.
DATE		NO.
DATE		DT.
DATE		NO.
DATE		DT.

A	REDRAWN / ITEM NO.11 & 12 ADDED / ITEM NO. 14 QTY WAS 8	197-02-06	A.P.
LET.	MODIFICATION	DATE	INT.

004-0330

ITEM	PART #	DESCRIPTION	QT.
1	004A0332	UPPER SEAL BAR PRE-ASSEMBLY	1
2	002B0337	BAG HOLD BAR SUPPORT	1
3	077-0030	INTERIOR COMPRESSION SPRING	10
4	077-0100	EXTERIOR COMPRESSION SPRING	10
5	002A0395	BAG HOLD BAR	1
6	179-0002	SILICONE 1/4" X 3/8" X 845 MM GRAY 60	2.9
7	003-0066	COUNTER BAR & BAG HOLDER BAR SCREW	5
8	009-0058	CUTTING BLADE	1
9	001A1573	COUNTER BAR SPACER SUPPORT	1
10	051-0260	HEX. BOLT 1/4"-20 NC. X 2" S/S	5
11	004B0149	PERFORATOR SUBSTITUTE ASSEMBLY	1
12	051-0375	SCREW 3/8"-16 NC. X 1 1/2" FLAT HEX. SKT S/S	4
13	051-0621	HALF HEX. NUT 3/8"-16 NC. S/S	4



-- END VIEW "A-A" --
(END VIEW ASSEMBLY)

MECHANICAL BAG CUT TOP & BOTTOM SEALING OPTION (MBC/TBS) -

650A

SIPROMAC

UPPER SEAL BAR ASSEMBLY

DATE: 00-02-07
SCALE: 1:1

NO. 005B0443

DATE: 00-02-07

SCALE: 1:1

NO. 005B0443

NOTE:

INSTALL BAG HOLD BAR ASSEMBLY IN COVER USING SCREWS (12) & NUTS (13) BEFORE INSTALLING CUTTING BLADE (8) & COUNTER BAR SUPPORT SPACER (9) WITH COUNTER BAR ASSEMBLY TO BAG HOLD BAR ASSEMBLY WITH BOLT (10) & NUTS (11)

USE "BLACK MAX" #169-0020 TO INSTALL


TEETH BEVEL REAR SIDE

TO CHAMBER

LET. C REDRAWN
MODIFICATION
DATE 00-02-07
S.L. INT.

004-0505

ITEM	PART #	DESCRIPTION	QT.
1	106-0050	VALVE 2WAY 24V 1-1/4"NPT(B60)60Hz	2
2	103-0247	CLOSE NIPPLE 1 1/4" NPT ZINC	2
3	103-0587	RED. BUSH. 2"npt. X 1 1/4"npt ZINC	2
4	004A1621	VAC./ATM. VALVE SUPP. PRE-ASSY	2
5	103-0260	CLOSE NIPPLE 2"NPT ZINC	4
6	106-0060	VALVE 2WAY / 24V / 60Hz / 2" NPT	2
7	103-0487	T 2" NPT GALV.	1
8	103-0760	STRAIGHT 2"mmpt. X 2" HOSE ZINC	3






NOTE:



-UTILISER RUBAN DE TEFLON #154-0060 & TEFLON LIQUIDE #154-0030 POUR L'ASSEMBLAGE.




MACHINE 650A, 680A & 700A		DEPT. TOL. METRIC INCH USINAGE ±0.1 ±0.004 TOILERIE ±0.5 ±0.027 SOUDAGE ±0.5 ±0.027	SIPROMAC ST-GERMAIN DE GRANTHAM QUEBEC CANADA
PART VACUUM / ATMOSPHERE VALVE ASSY		CHC	N.T.S.
ITEM	QTY	DATE	DEPT.
MAT.		04-03-03	M-I
DRAWN BY B.C.		DATE 25-7-04	NO. 004-0505
APP. BY			

LET.	MODIFICATION	DATE	INT.
H	REMOVED SORT AIR OPTION NOTE	05-10-31	M.A.
G	004A1621 WAS 004-0183	05-09-27	M.A.
F	REMOVED 2 ITEMS 103-0092	05-09-21	M.A.
E	REDESSINE ET AJOUT OPTION	04-03-03	B.C.



ELECTRICAL DRAWING





MC-40

MACHINE

VACUUM DOUBLE CHAMBER

SIPROMAC

ST-GERMAIN DE GRANTHAM,
QUEBEC CANADA

LOW VOLTAGE WITH MC-40

FOR PART NUMBERS FOR LETTERS (A) THRU (N) SEE FOLLOWING LIST

MAT: _____

DESS. D.L. _____ DATE 15 MAY 1988


APP. _____ NO. _____

016-0118

1006-0037

PUMP	MOTOR	VOLT-PL	FUSE F1
7.5	7.5	230-3	034-0110
7.5	7.5	380-3	034-0100
7.5	7.5	575-3	034-0540
10	10	230-3	034-0110
10	10	380-3	034-0100
10	10	575-3	034-0580

OPTION	VOLTAGE	FUSE F2	FUSE F5
TWIN SEAL	220	034-0530	034-0200
TWIN SEAL	380	034-0510	034-0410
TWIN SEAL	600	034-0465	034-0410
BAG CUT	220	034-0530	034-0200
BAG CUT	380	034-0510	034-0410
BAG CUT	600	034-0465	034-0410
TOP & BOTTOM SEAL	220	034-0530	034-0200
TOP & BOTTOM SEAL	380	034-0510	034-0410



COLOR CODE PRIMARY
 WHITE 0V
 BLACK 120V
 GREY 208V
 RED 230V
 BROWN 380V
 YELLOW 460-480V
 BLUE 575-600V
SECONDARY (VAC)
 RED 24V
 PURPLE 9V

WIRE LOCATION	W1	W2	W1	W2
VOLTAGE	220	575	220	575
PUMP	7.5			
SEAL OPTION	STAND.	TOP	STAND.	TOP
WIRE DIA.	10/4SJ	6/4SO	12/4SO	12/4SO
	6/4SO	6/4SO	6/4SO	10/4SO
	6/4SO	6/4SO	6/4SO	10/4SO

MACHINE
VACUUM 650A


PIECE
ELECT. WIRING HIGH VOLTAGE 3Ø

QT. _____ ECH. SCALE _____
 MAT: _____
 NE PAS MESURER / N.T.S.
 DATE 97-03-12
 APP. _____




SIPROMAC
 ST-GERMAIN DE GRANTHAM,
 QUEBEC CANADA

NO. 006-0037

SINGLE CHAMBER



DOUBLE CHAMBER



① WIRE TEW 12 AWG SIPROMAC # 030-0420


② WIRE CABTIRE 12/3 SJ SIPROMAC # 030-0120
CONNECTOR CD-13 SIPROMAC # 036-0409

MACHINE	ALL MODEL		SIPROMAC	
PIECE	WIRING FOR SEALING BAR		ST-GERMAIN DE GRANTHAM QUEBEC CANADA	
QT.	ECH. SCALE	NE PAS MESURER /N.T.S.		NO.
MAT.	DESS. APP.	ERIC J. I.P.	DATE	12 DEC. 2000



006-0131

ELECTRICAL DRAWINGS PARTS LIST

A : VOLT	PHASE	PUMP HP	CONTACTOR	OVERLOAD
220	1	4	025-0050	025-0200
220	3	4	025-0030	025-0190
460	3	4	025-0010	025-0170
575	3	4	025-0010	025-0160
220	1	7.5	025-0070	025-0222
220	3	7.5	025-0040	025-0210
575	3	7.5	025-0010	025-0180
220	3	10	025-0060	025-0220
460	3	10	025-0030	025-0190
575	3	10	025-0020	025-0190
B,C & O: SEALING CONTACTOR:			025-0020	
D: OPTIONAL GAZ SOLENOID VALVE:			106-0010	
E: VACUUM SOLENOID VALVE:			106-0060	
F: ATMOSPHERE SOLENOID VALVE:			106-0030 106-0050 WITH PUMP: 7.5 HP	
G: BELLOWS SOLENOID VALVE:			106-0070	
H, I, J: COVER SWITCH:			026-0590	
K: SEALING TRANSFO.:			029-0172,029-0174	
L: RELAY & BASE:				
RELAY:			025-0600	
BASE:			025-0610	
M: OPTIONAL TOP SEALING CONTACTOR:			025-0020	
N: CONTROL TRANSFO.:			029-0007, 029-0008, 029-0009, 029-0250	




PNEUMATIC DRAWING




007-0019

-NOTE:
-FOR GAS INJECTION
KIT INSTALLATION
SEE DRAWINGS #:
420A: #010-0016
600A: #010-0017
620A: #010-0018
650A: #010-0020



AIR REGULATOR OPTION


NOTE: SET TO A
MAXIMUM OF 45 PSI



-NOTE:
-FOR AIR REGULATOR
OPTION KIT INSTALLATION
SEE DRAWINGS # 010-0019
& 650A: #010-0027
(FOR EXISTING MACHINES)

WITH OPTIONS

WITHOUT OPTION





ITEM	PART #	DESCRIPTION	QT.
1	106-0010	GAS VALVE	2*
2	114-0280	VACUUM GAUGE	1
3A	106-0070	BELLOWS VALVE	1
3B	106-0070	BELLOWS VALVE	1*
4	114-0147	PRESSURE REGULATOR	1*
5	114-0245	PRESSURE GAUGE	1*
6	114-0170	PRESSURE REGULATOR SUPPORT	1*
7	106-0030	ATMOSPHERE VALVE FOR 420A	1
	106-0030	ATMOSPHERE VALVE FOR 600A, 650A & 700A	
	106-0050	ATMOSPHERE VALVE FOR 600A & 620A: 160 M ³ AND 250 M ³	
8	106-0030	ATMOSPHERE VALVE FOR 650A & 700A	1
	106-0050	VACUUM VALVE FOR 600A & 620A	
	106-0060	VACUUM VALVE FOR 650A & 700A	
*: OPTION			

MACHINE 420A, 600A, 620A & 650A		SIPROMAC	
PART PNEUMATIC		ST-GERMAIN DE GRANTHAM QUEBEC CANADA	
ITEM	SCALE	DATE	QT.
97-03-11	M.L.	97-03-11	1
RE-DRAWN	MODIFICATION	DATE	INT.
LET.			
DRAWN BY M. LAVIGNE		DATE	
APP.		DATE	
N.T.S.		007-0019	

1010-0027

ITEM	PART #	DESCRIPTION	QT.
1	005-0353	MACHINE ASSEMBLY REAR VIEW	1
2	005-037A	ELECTRICAL BOX ASSEMBLY	1
3	051-0190	BOLT 1/4"-20 x 3/4" 9/5	2
4	051-0710	WASHER 1/4" FLAT 5/5	15
5	051-0580	NUT 1/4"-20 5/9	6
6	051-0180	BOLT 1/4"-20 x 1/2" 9/5	9
7	001-136A	LEFT/ELEC. BOX UPPER SUPPORT	1
8	004-0279	E-BOX COVER ASSEMBLY	1
9	009-004A	VALVE/REGULATOR SUPPORT	1



— AIR REGULATOR OPTION — (FOR EXISTING MACHINES)

MACHINE	650A	INCH TOLERANCE 0 ± .015 .00 ± .005 .000 ± .0005	METRIC TOLERANCE 0 ± .015 .00 ± .005 .000 ± .0005	STIPROMAC ST-GERMAIN DE GRANTHAM QUEBEC CANADA	SCALE	GT.
PART	AIR REGULATOR OPTION KIT INSTALLATION	N.T.S.				
ITEM:		CNR				
DATE	97-02-21	DATE	97-02-21	NO.	010-0027	
INT.		APP.	DANE A			
LET.	A. REDMAN	MODIFICATION				



United States
Department of
Agriculture

Food Safety
and Inspection
Service

Washington, D.C.
20250

May 14, 1992

Sipromac, Inc.

The following equipment is acceptable for use in federally inspected meat and poultry plants:

EQUIPMENT: Vacuum Packaging Machine, Models: Sipromac 650A,
Sipromac 600A, Sipromac 550A, and Sipromac 420A

This acceptance is with the understanding that all future equipment designated by a similar model number will be of the same design and material as those for which this letter is written. Once this equipment is published in our "Accepted Meat and Poultry Equipment" booklet, this letter becomes invalid and can no longer be used as an authorization for installation of equipment in plants.


This acceptance does not imply compliance with Department of Labor Occupational Safety and Health Standards, nor should it be considered as an approval of processing methods. Any departure from established procedures must be cleared with the Slaughter Inspection Standards and Procedures Division or the Processed Products Inspection Division.

Sincerely,


Robert E. Owens
Industrial Specialist
Equipment Branch
Facilities, Equipment and Sanitation Division
Science and Technology

REC'D


NOTES




250



300




350/350D




380A




450T




400A



450A




550A




580A




VACUUM PACKAGING MACHINES




420A




600A




620A




650A




680A



700A



750A



MANUEL D'UTILISATEUR

MICROPROCESSUR MC-40 AVEC DÉTECTEUR DE VIDE

EMBALLEUSE SOUS VIDE

TABLE DES MATIÈRES

I INSTRUCTIONS POUR LES OPÉRATIONS

II MÉCANIQUE

- A- Vue de face
- B- Vue de l'arrière
- C- Procédure d'ajustement du couverc
- D- Schéma de l'assemblage de l'axe central
- E- Barres de scellage
(Double scellage)
- F- Dessin des barres de scellage
(Option du coupe sac électrique)
- G- Dessins des barres d'assemblage
(Scellage du haut et du bas en option)
- H- Gas injection kit installation drawing
(gaz injection option)

III ELECTRIQUE

- A- Schéma électrique (Bas voltage)
- B- Schéma électrique (Haut voltage à une phase)
- C- Schéma électrique (Haut voltage à 3 phases)
- D- Schéma électrique (Haut voltage 1 phase 50 Hz)
- E- Schéma électrique (Haut voltage 3 phase 50 Hz)

IV PNEUMATQUE

- A- Schéma Pneumatique

EMBALLEUSES SOUS VIDE INSTRUCTIONS D'OPÉRATIONS

TABLE DES MATIÈRES

1. Mise en marche de la machine
2. Connexion Électrique
3. Opération
 - 3.1 Principes de travail
 - 3.2 Emballage Spécial
 - 3.2.1 Injection de Gaz
 - 3.2.2 Scellage haut et bas
(bi-active sealing)
 - 3.2.3 Coupe sac électrique
 - 3.3 Ajustement des contrôles digital
 - 3.4 Nettoyage Quotidien
4. Trouble de lancement
 - 4.1 Échec durant le cycle d'emballage
 - 4.2 Vide insuffisant
 - 4.2.1 Fuites dans le sac
 - 4.2.2 Pas de fuite dans le sac
 - 4.2.3 Vide insuffisant dans la chambre
 - 4.3 Scellage Inadéquat
 - 4.3.1 Scellage insuffisant
 - 4.3.2 Pas de scellage
 - 4.3.3 Courant ininterrompu sur les barres de scellage
 - 4.3.4 Le scellage ne tient pas
 - 4.4 Problème avec les valves
 - 4.5 Problème du panneau de contrôle
5. Maintenance Régulière

SIPROMAC INC.

EMBALLEUSES SOUS VIDE

1. MISE EN PLACE DE LA MACHINE:

Avant de choisir le site d'installation de votre machine, veuillez considérer que vous aurez besoin d'espace pour les produits emballés et non-emballés à part de l'espace occupé par la machine elle-même.

Bien vouloir vous rappelez que vous aurez besoin d'un sol bien au niveau pour votre installation. Spécialement avec les modèles mobiles, le poids de la pompe peut gauchir la machine et le couvercle ne fermera plus correctement.

Avant de commencer à travailler, vérifier l'huile de la pompe pour voir si elle est en quantité suffisante. Bien vouloir ne jamais utiliser une huile autre que celle recommandée par le fabricant. Ne pas excéder la quantité indiquée quand vous ajoutez ou faites le changement d'huile et faites votre vérification hebdomadairement.

En raison de la viscosité de l'huile, la machine sera plus difficile à démarrer à basses températures. Ainsi donc la pompe doit être placée dans un endroit où la température est d'au moins 50°F (+10°C). D'autre part, l'air doit circuler librement aux alentours de la pompe pour permettre le refroidissement dans les cas où la température des opérations atteindrait 160°F (70°C) ou la température maximale permise.

2. CONNEXION ÉLECTRIQUE:

Les connexions électriques doivent se faire par du personnel qualifié. La personne désignée doit s'assurer que les entrées électriques correspondent au voltage et à l'ampérage approprié de la machine.

Un schéma électrique accompagne chacune de nos machines.

Une étape importante dans le branchement de la machine est de s'assurer que le moteur de la pompe tourne dans une rotation appropriée.

Attention: Le moteur de la pompe ne devrait pas tourner plus de 3 ou 4 secondes dans une mauvaise rotation car il en résultera des dommages sérieux. La rotation est indiquée par une flèche sur le moteur de la pompe.


3. OPÉRATION:

3.1 Principes de travail:

Un emballage sous vide est un cycle composé de 3 étapes. Premièrement le vide est fait et l'air est complètement enlevé de la chambre et du sac contenant le produit. (Voir figure 1). Ensuite c'est possible d'injecter du gaz neutre par les conduits si le produit est très délicat. Finalement, un mécanisme pousse la barre de scellage sur le support de caoutchouc pour sceller le sac

Pour obtenir de beaux emballages, les produits et les sacs doivent être de taille proportionnelles. L'ouverture du sac ne devrait jamais excéder 2" (50cm) au delà des barres de scellage. Le produit doit être centré en hauteur par rapport aux barres de scellage en ajustant les écarteurs qui vous sont fournis.

Pour obtenir un bon scellage, assurez-vous qu'il n'y a pas de résidu de graisse qui reste entre les côtés intérieurs des sacs où le scellage doit être fait.



3.2 Emballage Spécial:

3.2.1 Injection de Gaz (option):

Il y a une pression atmosphérique de 14 lbs / pouce carré (= 1 kg / cm carré) sur les produits quand le vide demandé est atteint. Les produits qui peuvent être endommagés par une haute pression doivent être emballés avec un vide partiel et la pression doit être contrebalancée en injectant du gaz dans le sac (nitrogène ou dioxyde de carbone) avant le scellement et après avoir atteint le vide.

Pour l'injection de gaz, les sacs sont placés sur les barres de scellage, l'ouverture placée au dessus des conduits de gaz qui sont montés le long des barres de scellage. Après que le vide soit atteint, la valve du vide se ferme et la valve du gaz s'ouvre. Le pourcentage de gaz peut être ajusté par le menu du programme.

Le réservoir de gaz et la valve de pression qui est rattachée au réservoir ne sont pas fournis par Sipromac. La pression pour le régulateur de gaz devrait être ajustée approximativement à 5 lbs/pouce carré (1/3 Kg/cm carré). Chaque machine a un adapteur pour la connexion de gaz quand l'option de l'injection de gaz est commandée.

3.2.2 Scellage Haut et Bas (optionnel):

Pour le scellage des sacs en aluminium comme pour le café il est impératif d'avoir une barre de scellage en haut et en bas.

3.2.3 Coupe sac électrique: (optionnel):

Cette option est utilisée pour obtenir un paquet dont l'excédent de film au niveau du scellage doit être coupée très près de la ligne de scellage. (cette option ne peut pas être utilisée avec le scellage Haut et Bas)

3.3 Les opérations de l'empaquetage sous vide:

Note: Reportez-vous aux menus structure de la page 8 et aux détails du panneau de contrôle sur la page 9

3.3.1 Bases:

Utilisez la touche "POWER" pour initier le bouton ON/OFF sur votre machine sous vide. Quand votre unité sera en fonction le dernier programme exécuté apparaîtra sur l'écran à cristaux liquides.

Utilisez la touche "ESC" pour passer du menu programme au menu fonctions et du menu des fonctions au menu des programmes.

Dans le menu des fonctions, utilisez la touche "SELECT" pour sélectionner une fonction et la touche "ENTER" pour exécuter la sélection.

Dans le menu des programmes, utilisez la touche "SELECT" pour sélectionner un programme et la touche "Enter" pour accéder ou modifier la sélection.

Dans les programmes du sous menu, utilisez la touche "ENTER" pour voir défiler les paramètres et lorsque ces derniers clignotent pour indiquer ils sont dans le mode d'acquisition. Quand la séquence de tous les paramètres se sont affichés, on revient automatiquement au début de la liste.

Dans les programmes du sous menu, utilisez la touche "ESC" pour revenir au menu des programmes. Pressez n'importe quelle touche pour effacer les messages d'erreur qui peuvent s'afficher sur l'écran à cristaux liquide.

3.3.2 Menu des fonctions:

3.3.2.1 Créer un programme:

Quand vous exécutez la fonction "create a program", le programme sous menu est atteint en commençant par l'identification. L'identification initiale "PxxNO NAME" est donné au programme et tous les paramètres sont établis à zéro; le numéro du programme est alloué automatiquement.

3.3.2.2 Supprimer un programme:

En exécutant la fonction de "delete a program", vous avez accès au menu des programmes et le numéro du premier programme en mémoire clignote pour indiquer le mode de suppression. Utilisez la touche "SELECT" pour sélectionner un programme et la touche "ENTER" pour avoir accès et confirmer la suppression de la sélection. Utilisez la touche "ESC" pour annuler une suppression et quitter la fonction. Quand vous quittez la fonction, le nombre des programmes actuels sur l'écran à cristaux liquides cesse de clignoter.

3.3.2.3 Choisir le mode d'opération:

Quand vous exécutez la fonction "Select Operating Mode", laquelle est disponible seulement pour les unités automatiques, la sélection en cours clignote pour vous indiquez le mode. Utilisez la touche "SELECT" pour parcourir les modes d'opération, lesquels sont automatiques, semi-automatiques et manuels. Le mode

d'opération sera validé et exécuté automatiquement. Utilisez la touche "ESC" ou "ENTER" pour quitter la fonction et retourner au menu des programmes.

3.3.3 Menu des Programmes:

3.3.3.1 Identification des Programmes:

Pour un programme sélectionné, choisissez l'identification en utilisant le panneau de contrôle numérique avec la chartre des caractères et pressez sur la touche numérique jusqu'à ce que le caractère soit sélectionné (4 x pour la valeur numérique). Utilisez la touche "ENTER" pour valider le caractère ainsi que la chaîne de caractères jusqu'à la fin (la nouvelle chaîne de caractères clignote). Vous pouvez utiliser la touche "ESC" pour revenir en arrière dans le cas où vous êtes trompé et que vous voulez effacer le caractère.

Example: EXAMPLE 1 → (9 caractères)

Touche 2, 2, ENTER	→ E
Touche 8, 8, 8, ENTER	→ X
Touche 1, ENTER	→ A
Touche 5, ENTER	→ M
Touche 6, ENTER	→ P
Touche 4, 4, 4, ENTER	→ L
Touche 2, 2, ENTER	→ E
Touche 9, 9, 9, ENTER	→ espace
Touche 1, 1, 1, 1, ENTER	→ 1

Touche ENTER pour valider la chaîne de caractères

3.3.3.2 L'ajustement du niveau de Vide:

Pour un programme sélectionné, ajustez le niveau de vide avec les valeurs; le point décimal est automatiquement inséré suivant la deuxième entrée digitale et la validation est automatiquement exécutée après la troisième entrée digitale (La nouvelle valeur du niveau du vide clignote). Le niveau de vide est arrondi à la demie la plus près de la valeur. En cours de traitement, utilisez la touche "ENTER" pour valider la valeur du niveau de vide et la touche "ESC" pour revenir en arrière et changer la valeur du niveau de vide (La valeur du niveau de vide la plus ancienne clignotera à ce moment). Ajustez le niveau du vide à zéro pour pouvoir contourner le capteur de vide et procédez en réglant seulement le " Temps de vide Plus" (Vacuum plus time).

Exemples: 90.0% → Touches 9, 0, 0 ou 9, 0, ENTER ou
Touches 9, 0, 1 ou 9, 0, 2 or 9, 0, 3 ou 9, 0, 4
97.5% → Touches 9, 7, 5 ou
Touches 9, 7, 6 ou 9, 0, 7 or 9, 0, 8 ou 9, 0, 9
0.0% → Touches 0, 0, 0 ou 0, ENTER

3.3.3.3 Ajustement du Temps de Vide "Plus":

Pour un programme sélectionné, réglez le "temps de vide plus" en secondes; la validation est automatiquement exécutée après la deuxième entrée digitale (La nouvelle valeur du "temps de vide plus" clignotera à ce moment). En cours de traitement, utilisez la touche "ENTER" pour valider la nouvelle valeur du "temps de vide plus" et la touche "ESC" pour revenir et recommencer avec de nouvelles

"ENTER" afin d'accéder et modifier le programme; les paramètres deviennent valides seulement pour les cycles suivants de vide.

3.3.5 System monitor:

Pour accéder le menu des diagnostics, monter la puissance de la machine d'emballage sous vide tout en maintenant le bouton "ESC" enfoncé. Utilisez la clé "SELECT" pour choisir la fonction du système du moniteur et "ENTER" pour accéder et visualiser les paramètres surveillés. Employez la clé "SELECT" pour changer la révision de logiciel, la quantité d'heures de travail faites et de la quantité de cycles complets exécutés depuis la première initialisation.

-MENUS STRUCTURE-

- Functions menu:

"F1 CREATE A PRGM"
"F2 DELETE A PRGM"
"F3 SELECT OPMODE" (automatic units only)

- Programs menu:

"Pxx NAME"

Program submenu:

"VACUUM: xx.x%"	(10.0% - 99.5%)
"VACUUM PLUS: xxs"	(0s - 99s)
(units with gas option) "GAS FLUSH: xx.x%"	(0.0% - 10% below the vacuum level)
"SEAL TIME: x.xxs"	(0.00s - maximum unit allocated setting)
"Pxx NAME"	(12 characters)

- Diagnostics menu (keys "ESC" & "POWER" for access):

"DIAGNOSTICS MENU" (access code required)

"D1 INPUTS TEST"

"D2 OUTPUTS TEST"

"D3 MODEL SELECT"

"D4 GAS OPTION"

"D5 SEALING TIME"

"D6 COOLING TIME"

"D7 LOADING TIME" (automatic units only)

"D8 UNLOADNG TIME" (automatic units only)

"SYSTEM MONITOR" (no access code required)


"SOFTWARE: R x.xx"

"WORK HRS: xxxxx"


"CYCLES: xxxxxxx"

PROGRAMMATION MC-40


Pour modifier un programme déjà créé



Pour créer un programme




Pour sélectionner un programme créé




SYSTEM MONITOR


Pour accéder au menu "system monitor", mettre la machine à off, tenir la touche "esc", appuyer et relacher la touche "on/off" et finalement relacher la touche "esc". L'affichage indique DIAGNOSTIC MENU, appuyer sur select pour accéder au SYSTEM MONITOR.



DIAGNOSTIC MENU

Pour accéder au "DIAGNOSTIC MENU", mettre la machine à off, tenir la touche "esc", appuyer et relâcher la touche "on/off" et finalement relâcher la touche "esc". L'affichage indique DIAGNOSTIC MENU, appuyer sur enter pour accéder.





Drag the side handles to change the width of the text block.

Entrer le temps de scellage maximum