



Transformer Diagnosis For the JVR Vac410 v1.0

Vac410 Large Seal Transformer Part #410-62

DISCONNECTED TRANSFORMER



DURING SEAL

