


Transformer Diagnosis For the JVR Vac310 v1.0

Vac310 Large Seal Transformer Part #310-62


DISCONNECTED TRANSFORMER

0.8-1.0 Ω 0.2-0.6 Ω



GOOD ✓


OPEN OPEN



BAD ✗


DURING SEAL

100-120 VOLTS 17-21 VOLTS



GOOD ✓

100-120 VOLTS 0 VOLTS



BAD ✗