



Transformer Diagnosis For the JVR Vac100 v1.0

Vac100 Transformer Part #100-62

DISCONNECTED TRANSFORMER




GOOD ✓




BAD ✗

POWER ON




GOOD ✓




BAD ✗

DURING SEAL



GOOD ✓



BAD ✗